

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011651/AYA3Q2**Date:** 12/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900263208
Claimant Vehicle No :	SKT5885U	Insured Vehicle No :	SMR3204K
Date of Loss:	30/10/2022	Nature of Claim:	TP
		Claim No:	8679957487SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT5885U		
Make & Model:	LEXUS NX300, 2.0 (A)	Engine No:	8ARW776120
Reg. Date:	21/03/2018 (Man. Year: 2018)	Chassis No:	JTJBARBZ702171142
Colour:	Black	Odometer:	99332 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R19	Rear Tyre Size:	255/45 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,100.04	2,607.06	6,492.98	71.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	550.00	2,400.00	81.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,050.04	3,157.06	8,892.98	73.80
Approved Total (Overridden) (\$\$)		2,500.00		
Nett Amount (\$\$)	12,050.04	2,500.00	9,550.04	79.25
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	16/11/2022	
Date Inspected:	16/11/2022	Inspected At: SM Automotive (HQ) 756 JURONG WEST STREET 74, #12-60 Singapore 640756
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,586.20 FL	*985.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Dented	799.60 FL	*799.60 FL
3	1		*REAR BUMPER SPONGE	Not Necessary	230.40 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Necessary	163.80 FL	*163.80 FL
5	1		*REAR BUMPER LOWER DIFFUSER	Deformed	685.20 FL	*595.00 FL
6	2		*REAR BUMPER SIDE REFLECTOR	Not Necessary	371.20 FL	*- FL
7	1		*REAR TAILGATE	Not Necessary	2,215.60 FL	*- FL
8	1		*REAR TAILGATE LOCK WITH SENSOR & MOTOR	Not Necessary	899.60 FL	*- FL
9	1		*REAR TAILGATE EMBLEM LOGO	Not Necessary	76.50 FL	*- FL
10	1		*REAR TAILGATE EMBLEM LEXUS	Not Necessary	65.90 FL	*- FL
11	1		*REAR TAILGATE EMBLEM NX300	Not Necessary	69.60 FL	*- FL
12	1		*REAR END PANEL	Not Necessary	798.60 FL	*- FL
13	1		*REAR END PANEL TOP GARNISH	Not Necessary	425.50 FL	*- FL
14	1		*REAR WEATHER STRIPE	Not Necessary	389.70 FL	*- FL
15	2		*REAR EXHAUST CHROME MOULDING	Not Necessary	558.20 FL	*- FL
16	1		*REAR END PANEL GRILLE LH	Cracked	95.00 FL	*95.00 FL
17	1		*REAR BUMPER LOWER COVER	Deformed	225.00 FL	*225.00 FL
18	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
19	1		*REAR TAILGATE INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
20	1		*REAR END PANEL SEALANT	Not Necessary	120.00 FS	*- FS
21	2		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Not Necessary	150.00 FS	*- FS
					Sub Total (\$\$)	10,065.60 2,893.40
					- List Item Discount on L Items 10.00/10.00% (\$\$)	965.56 286.34
					Total Parts (\$\$)	9,100.04 2,607.06

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,200.00	300.00
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	200.00
3	WIRING CHECK	New	80.00	0.00
4	TO APPLY TUFF COATING / RUST PROOF ACCIDENT AREAS	New	300.00	0.00
5	LABOUR FOR REMOVE & RENEW REAR TAILGATE WINDSCREEN GLASS	New	150.00	0.00
6	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING	New	120.00	0.00
7	TO REMOVE REVERSE SENSOR	New	100.00	50.00
Gross Labour Cost (S\$)			2,950.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >