4/13/23, 2:10 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22011657/UYA3Q2

13/04/2023 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210015063 **Claimant Vehicle** SLK1908A Insured Vehicle No: SKC8175E No:

Date of Loss: 17/11/2022 Nature of Claim: TP Claim No: 9255191838SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK1908A**

MERCEDES-BENZ A200, 1.6 FL STYLE (R17 Make & Model: Engine No: 27091031023047 HLG) (A)

09/01/2017 (Man. Year: 2016) Chassis No: WDD1760432J492132 Reg. Date:

Colour: White Odometer: 71287 km

Engine Capacity: 1595 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): **Engine Modification:** Yes No

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17 Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,542.88	3,332.38	3,210.50	49.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,460.00	570.00	890.00	60.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,002.88	3,902.38	4,100.50	51.24
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	8,002.88	3,100.00	4,902.88	61.26
+ GST 7.00/7.00% (S\$)	560.20	217.00	343.20	61.26
Nett Amount (S\$)	8,563.08	3,317.00	5,246.08	61.26
+ Loss of Use (5.0 x S	\$60.00/day) (S\$)	300.00		
N	lett Liability (S\$)	3,617.00		

INSPECTION

Date of Assignment: 21/11/2022

Tan Lim Motor Pte Ltd (Defu) Date Inspected: 21/11/2022 Inspected At:

1 Defu Lane 6

Singapore 539365

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: Ezlyna NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Dented / Deformed	1,200.00 FN	*1,200.00 FN
2	1	*N/S FRONT BUMPER RETAINER	Not Necessary	150.00 FN	*- FN
3	1	*N/S FRONT BUMPER SIDE BRACKET	Cracked	85.00 FN	*85.00 FN
4	1	*N/S FRONT BUMPER LOWER CHROME GARNISH	Cracked	130.00 FN	*130.00 FN
5	1	*N/S FRONT BUMPER CENTRE GRILLE	Grazed	135.00 FN	*135.00 FN
6	1	*N/S FRONT BUMPER CENTRE GRILLE PARKING SENSOR	Not Necessary	280.00 FN	*- FN
7	1	*FRONT BUMPER RADAR SENSOR	Not Necessary	1,100.00 FN	*- FN
8	1	*FRONT BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	160.00 FN	*- FN
9	1	*FRONT BUMPER FOG LAMP TRIM	Not Necessary	70.00 FN	*- FN
10	1	*FRONT BUMPER LOWER BEAM	Not Necessary	345.00 FN	*- FN
11	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	420.00 FN	*- FN
12	1	*FRONT GRILLE ASSY	Cracked / Scratched	600.00 FN	*600.00 FN
13	1	*FRONT GRILLE STAY LOGO	Not Necessary	140.00 FN	*- FN
14	1	*FRONT GRILLE BASE	Cracked	70.00 FN	*70.00 FN
15	1	*N/S HEADLAMP ASSY	Cracked	940.00 FN	*940.00 FN
16	1	*N/S HEADLAMP CONTROL UNIT	Not Necessary	850.00 FN	*- FN
17	1	*N/S HEADLAMP SIDE BRACKET	Not Necessary	30.00 FN	*- FN
18	1	*FRONT BUMPER PLATE HOLDER	Torn	70.00 FN	*70.00 FN
19	1	*FRONT BUMPER UNDER COVER	Torn	266.20 FN	*266.20 FN
20	1	*FRONT BUMPER SPONGE	Torn	162.00 FN	*162.00 FN
21	1	*FRONT NUMBER PLATE	Scratched	60.00 FS	*40.00 FS
F=Fra	nchise	part. S=SpcNett. N=NettItemDisc.			
			Sub Total (S\$)	7,263.20	3,698.20
		- Nett Item Discount on N Iten	ns 10.00/10.00% (S\$)	720.32	365.82
			Total Parts (S\$)	6,542.88	3,332.38
		Report was unsubmitted during this prin	t-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	600.00	300.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
3	TO REINSTALL OF FRONT PARKING SENSOR	New	80.00	50.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	100.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	600.00	200.00
	Gross Labor	ur Cost (S\$)	1,460.00	570.00
	Report was unsubmitted during this	print-out		

< END OF ESTIMATES >