

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011669/GVP3Q2**Date:** 09/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00016182200		
Claimant Vehicle No :	SJV5698U	Insured Vehicle No :	PA7257K		
Date of Loss:	04/10/2022	Nature of Claim:	TP	Claim No:	SNM22D207141/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV5698U		Engine No:	L13A4226545
Make & Model:	HONDA FIT, 1.3 G (A)		Chassis No:	GE61206613
Reg. Date:	29/01/2010 (Man. Year: 2009)		Odometer:	0 km
Colour:	Red			
Engine Capacity:	1339 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50Z R16	Rear Tyre Size:	205/50Z R16
Front Left Side:	Habilead 5 mm	Rear Left Side:	Habilead 5 mm
Front Right Side:	Habilead 5 mm	Rear Right Side:	Habilead 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,076.00	2,744.40	7,331.60	72.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	830.00	2,220.00	72.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,126.00	3,574.40	9,551.60	72.77
Approved Total (Overridden) (\$\$)		2,850.00		
Nett Amount (\$\$)	13,126.00	2,850.00	10,276.00	78.29

INSPECTION

Date of Assignment:	18/11/2022		
Date Inspected:	23/11/2022	Inspected At:	J.E.W MOTORS PTE LTD (HQ) 60 Jalan Lam Huat Carros Centre #03-72 Singapore 737869
Estimated Period of Repair:	4.0 days		

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Feb 2023)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV5698U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET LOCK	Not Necessary	105.00 FL	*- FL
2	2		*HEADLAMP L+R	Cut	769.00 FL	*769.00 FL
3	2		*HEADLAMP BRACKET L+R	Not Necessary	53.00 FL	*- FL
4	1		*FRONT BUMPER RETAINER RH	Not Necessary	49.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT BAR	Bent	299.00 FL	*299.00 FL
6	1		*FRONT BUMPER UNDERCOVER	Not Necessary	158.00 FL	*- FL
7	2		*FRONT FENDER L+R	Not Necessary	1,144.00 FL	*- FL
8	2		*FRONT FENDER COWLING L+R	Not Necessary	218.00 FL	*- FL
9	1		*FRONT SUPPORT PANEL	Not Necessary	590.00 FL	*- FL
10	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	35.00 FL	*- FL
11	1		*AIRCON CONDENSOR	Not Necessary	855.00 FL	*- FL
12	1		*WIPER WASHER TANK	Not Necessary	95.00 FL	*- FL
13	1		*BONNET	Cracked	2,200.00 FS	*900.00 FS
14	1		*FRONT GRILLE	Not Necessary	600.00 FS	*- FS
15	1		*FRONT GRILLE LOGO -MUGEN	Necessary	150.00 FS	*120.00 FS
16	1		*FRONT BUMPER	Cracked	2,500.00 FS	*800.00 FS
17	1		*FRONT BUMPER TOW COVER	Not Necessary	150.00 FS	*- FS
18	1		*SET FRONT BUMPER FOG LAMP	Not Necessary	600.00 FS	*- FS
19	1		*FRONT NUMBER PLATE	Bent	80.00 FS	*40.00 FS
20	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
21	1		*FRONT FENDER COWLING CLIPS	Not Necessary	100.00 FS	*- FS
22	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
					Sub Total (\$\$)	10,950.00 2,958.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	874.00 213.60
					Total Parts (\$\$)	10,076.00 2,744.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	400.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	400.00
3	TO CHECK WIRING AND HEADLAMP FOCUS	New	150.00	30.00
4	TO RNR INNER TRIM AND UPHOLSTERY	New	200.00	0.00
5	TO CHECK WATER LEAK	New	150.00	0.00
6	TO RNR FRONT AIR CON CONDENSOR AND TOP UP GAS	New	300.00	0.00
7	TO PERFORM RUST PROOFING	New	100.00	0.00
8	TO RNR HORN AND TEST FUNCTION	New	150.00	0.00
Gross Labour Cost (S\$)			3,050.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >