



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 2155Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED / TORN	713.20	713.20
2	LHS & RHS FRONT BUMPER RETAINER @\$39.80	O/S BENT	79.60	39.80
1	FRONT BUMPER UPPER GRILLE	NOT NECESSARY	463.26	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	255.76	-
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	38.58	-
1	FRONT BUMPER LOGO	NOT NECESSARY	153.54	-
1	LHS FRONT BUMPER FOG LIGHT	NOT NECESSARY	186.90	-
1	LHS FRONT BUMPER FOG LIGHT COVER	NOT NECESSARY	75.21	-
1	RHS FRONT BUMPER FOG LIGHT	NOT NECESSARY	186.90	-
1	RHS FRONT BUMPER FOG LIGHT COVER	NOT NECESSARY	75.21	-
1	FRONT REINFORCEMENT	NOT NECESSARY	488.61	-
1	FRONT REINFORCEMENT BRACKET	NOT NECESSARY	134.86	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	899.17	-
1	SUPPORT PANEL TOP GARNISH	NOT NECESSARY	189.70	-
1	RHS HEADLIGHT	NOT NECESSARY	553.98	-
1	RHS HEADLIGHT BRACKET	NOT NECESSARY	78.30	-
	LESS 10% DISCOUNT		-457.28	-75.30
			4,115.50	677.70
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	90.00	40.00
10	SUPPORT PANEL TOP GARNISH CLIP @\$5.00 (SN)	NOT NECESSARY	50.00	-
1	FRONT NO PLATE WITH CASING (SN)	NOT NECESSARY	50.00	-
			190.00	40.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE ,REPLACE ,CUT ,WELD KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS ,INCLUSIVE OF REPLACEMENT PARTS.		1,000.00	200.00
	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS .		1,200.00	320.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS .	NOT NECESSARY	60.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SUPPLY UNDER COATING /PUTTY ON PARTS REPLACED.	NOT NECESSARY	60.00	-
	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR .	NOT NECESSARY	80.00	-
	TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT.	NOT NECESSARY	100.00	-
	DISCONNED AND CHECK ELECTRICAL WIRING HARNESS ,WIRE SOCKET.}		80.00	20.00
	TO CONDUCT HEADLIGHT FOCUS.}		150.00	-
	REMOVE AND REPLACE AIR-CON CONDENSER ,PIPES AND RADIATOR ,VACCUM AIR-CON SYSTEM AND REFILL GAS .	NOT NECESSARY	150.00	-
			2,880.00	540.00
<b>GRAND TOTAL</b>			<b>7,185.50</b>	<b>1,257.70</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,000.00</b>

Report Ref No. CS/SMO22011670/Uqy3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.