

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011671/TNP3Q2**Date:** 13/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00061812212		
Claimant Vehicle No :	GW9982C	Insured Vehicle No :	SJW4466Z		
Date of Loss:	17/11/2022	Nature of Claim:	TP	Claim No:	SNM22D208295/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GW9982C	Engine No:	QR20019940R
Make & Model:	NISSAN NV350 URVAN, 2.0 PANEL VAN 5MT (A)	Chassis No:	JN1MA2E26Z0000308
Reg. Date:	25/08/2022 (Man. Year: 2021)	Odometer:	6781 km
Colour:	Yellow		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,810.90	4,276.00	5,534.90	56.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	1,630.00	2,040.00	55.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,480.90	5,906.00	7,574.90	56.19
Approved Total (Overridden) (S\$)		4,700.00		
(S\$)	13,480.90	4,700.00	8,780.90	65.14
+ GST 8.00/8.00% (S\$)	1,078.47	376.00	702.47	65.14
Nett Amount (S\$)	14,559.37	5,076.00	9,483.37	65.14

INSPECTION

Date of Assignment:	19/11/2022	
Date Inspected:	21/11/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Jan 2023)	
Parts:	N/A	NISSAN NV350 URVAN 2.0 PANEL VAN 5MT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GW9982C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,816.17 FL	*1,816.17 FL
2	1		*TAILGATE WINDSCREEN GLASS RUBBER MOULDING	Necessary	61.20 FL	*61.20 FL
3	1		*TAILGATE NV350 EMBLEM	Necessary	101.30 FL	*101.30 FL
4	1		*TAILGATE URVAN EMBLEM	Necessary	69.70 FL	*69.70 FL
5	1		*TAILGATE CENTRE EMBLEM	Not Necessary	64.80 FL	*- FL
6	1		*TAILGATE CHROME MOULDING	Not Necessary	535.70 FL	*- FL
7	1		*TAILGATE RH NUMBER PLATE LAMP	Not Necessary	55.60 FL	*- FL
8	1		*TAILGATE LH NUMBER PLATE LAMP	Not Necessary	55.60 FL	*- FL
9	1		*TAILGATE OPEN HANDLE	Not Necessary	163.00 FL	*- FL
10	1		*TAILGATE LOCK	Bent	271.30 FL	*271.30 FL
11	1		*TAILGATE LOCK COVER	Not Necessary	37.30 FL	*- FL
12	1		*TAILGATE LOCK CATCH	Not Necessary	35.10 FL	*- FL
13	1		*TAILGATE CENTRAL LOCK DEVICE	Not Necessary	200.90 FL	*- FL
14	1		*TAILGATE RH HINGE	Not Necessary	55.60 FL	*- FL
15	1		*TAILGATE LH HINGE	Not Necessary	55.60 FL	*- FL
16	1		*TAILGATE RH ABSORBER STAY	Not Necessary	199.30 FL	*- FL
17	1		*TAILGATE LH ABSORBER STAY	Not Necessary	199.30 FL	*- FL
18	1		*TAILGATE INNER TRIM BOARD	Not Necessary	202.20 FL	*- FL
19	1		*TAILGATE WEATHERSTRIP	Cut	162.30 FL	*162.30 FL
20	1		*REAR BUMPER	Deformed	677.40 FL	*677.40 FL
21	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	22.30 FL	*- FL
22	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	22.30 FL	*- FL
23	1		*REAR BUMPER CENTRE STEP PANEL	Bent	169.70 FL	*169.70 FL
24	1		*RH TAILLAMP ASSY	Not Necessary	288.40 FL	*- FL
25	1		*RH TAILLAMP PANEL	Not Necessary	117.80 FL	*- FL
26	1		*LH TAILLAMP ASSY	Not Necessary	288.40 FL	*- FL
27	1		*LH TAILLAMP PANEL	Not Necessary	117.80 FL	*- FL
28	1		*END PANEL (OUTER)	Bent	461.80 FL	*461.80 FL
29	1		*FLOOR PANEL END PLATE MOULDING	Bent	75.80 FL	*75.80 FL
30	1		*FLOOR PANEL TOP TRIM CARPET	Not Necessary	587.00 FL	*- FL
31	1		*EXHAUST SILENCER	Not Necessary	708.00 FL	*- FL
32	1		*EXHAUST SILENCER GASKET	Not Necessary	36.00 FL	*- FL
33	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
34	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	60.00 FS	*30.00 FS
35	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	70.00 FS	*- FS
36	1		*TAILGATE 70KM/H STICKER	Necessary	28.00 FS	*28.00 FS
37	1		*TAILGATE 8 PAX STICKER	Necessary	28.00 FS	*28.00 FS
38	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
39	1		*END PANEL (OUTER)	Not Necessary	185.40 FS	*- FS
40	1		*END PANEL (OUTER)JOINT SEALANT	Not Necessary	70.00 FS	*- FS
41	1		*END PANEL (INNER)JOINT SEALANT	Necessary	70.00 FS	*40.00 FS
42	1		*SET REAR BUMPER CLIPS	Necessary	350.00 FS	*30.00 FS
43	1		*SET REAR BUMPER REVERSE SENSOR	Not Working	350.00 FS	*200.00 FS
44	1		*SPARE TYRE CARRIGE	Not Necessary	220.50 FS	*- FS
45	1		*SPARE TYRE CARRIGE HANGER GARNISH	Not Necessary	75.80 FS	*- FS
46	1		*FLOOR PANEL WOODEN BOARD	Cracked	1,050.00 FS	*400.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (S\$)	10,602.37
					- List Item Discount on L Items 10.00/10.00% (S\$)	791.47
					Total Parts (S\$)	9,810.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,400.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	30.00
5	REPLACE AND TAILGATE WINDSCREEN GLASS AND SEALANTS	New	200.00	120.00
6	REMOVE,CHECK AND REPLACE TAILGATE INNER MECHANISM TO NEW TAILGATE	New	180.00	60.00
7	REMOVE AND REPLACE REAR INNER WOODEN BOARD ,TRIM ,BOARDS AND GARNISH TO ASSIST REPAIR	New	280.00	60.00
8	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	30.00
9	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	New	150.00	0.00
Gross Labour Cost (\$\$)			3,670.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >