

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22011672/TYA3Q2**Date:** 07/06/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210048815
Claimant Vehicle No :	SHB5159M	Insured Vehicle No :	SMS6309S
Date of Loss:	20/11/2022	Nature of Claim:	TP
		Claim No:	2092127711SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5159M	Engine No:	2ZR6585781
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36U205767664
Reg. Date:	01/04/2016 (Man. Year: 2015)	Odometer:	505581 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,501.20	939.68	8,561.52	90.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,608.00	1,490.00	2,118.00	58.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,109.20	2,429.68	10,679.52	81.47
Approved Total (Overridden) (\$\$)		2,250.00		
Nett Amount (\$\$)	13,109.20	2,250.00	10,859.20	82.84
+ Loss of Use (7.0 x S\$50.00/day) (\$\$)		350.00		
+ Car Rental (7.0 x S\$100.58/day) (\$\$)		704.06		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		3,306.06		

INSPECTION

Date of Assignment:	21/11/2022	
Date Inspected:	21/11/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR RR/LH (DISC 25%)	Dented	1,213.70 F	*910.28 F
2	1		*STRIDES LOGO (SN)	Necessary	7.80 F	*7.80 F
3	1		*STICKER DECAL 65558888 (SN)	Necessary	21.60 F	*21.60 F
4	10		*BUMPER CLIPS	Not Necessary	2.40 F	*- F
5	1		*BUMPER REINFORCEMENT REAR	Not Necessary	234.70 F	*- F
6	1		*ARM SUB-ASSY ,RR BUMPER RH	Not Necessary	157.90 F	*- F
7	1		*ARM SUB-ASSY ,RR BUMPER LH	Not Necessary	157.90 F	*- F
8	1		*ANTENNA ELECTRICAL LOWER REAR	Not Necessary	208.10 F	*- F
9	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
10	1		*BUMPER SIDE RETAINER RR/LH	Not Necessary	108.70 F	*- F
11	1		*BUMPER SEAL ,RR LH	Not Necessary	101.80 F	*- F
12	1		*BUMPER LIP COVER RR/LH	Not Necessary	93.90 F	*- F
13	1		*BUMPER LIP REAR	Not Necessary	301.90 F	*- F
14	1		*END PANEL	Not Necessary	755.10 F	*- F
15	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
16	1		*QUARTER GLASS RR/LH	Not Necessary	192.30 F	*- F
17	1		*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
18	1		*FENDER LINER R/LH	Not Necessary	159.80 F	*- F
19	1		*TAIL LAMP LH	Not Necessary	618.60 F	*- F
20	1		*TAIL LAMP BRACKET ,LH	Not Necessary	35.20 F	*- F
21	1		*DOOR LOCK RR/LH	Not Necessary	798.80 F	*- F
22	1		*HINGE LOWER LHR ,DOOR	Not Necessary	93.90 F	*- F
23	1		*HINGE UPPER LHR ,DOOR	Not Necessary	107.00 F	*- F
24	1		*CHECK ASSY ,RR DOOR	Not Necessary	199.40 F	*- F
25	1		*DOOR REGULATOR MOTOR REAR LH	Not Necessary	1,003.80 F	*- F
26	1		*DOOR REGULATOR SUB-ASSY ,FRT/REAR LH	Not Necessary	256.60 F	*- F
27	1		*DOOR WEATHERSTRIP RR/LH	Not Necessary	195.20 F	*- F
28	1		*FENDER RR/LH	Repair	980.80 F	*- F
29	1		*MOULDING BODY ,LH	Repair	761.40 F	*- F
30	1		*BUMPER REAR	Repair	478.90 F	*- F

F=Franchise part.

Total Parts (S\$) **9,501.20** **939.68**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,014.00	600.00
2	SPRAY PAINT	New	1,854.00	800.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	30.00
6	TO TRANSFER DOOR MECHANISM	New	120.00	60.00
7	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
8	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	120.00	0.00
9	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (\$\$)			3,608.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >