12/7/22, 2:25 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22011677/KNP3Q2

118833 km

**Date:** 07/12/2022

**REFERENCE** 

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00079792203

TP

**Claimant Vehicle** 

SKP8797S

Insured Vehicle No :

Claim:

GBD1576D

No:
Date of Loss:

17/11/2022

Nature of

Claim

Odometer:

No: SNM22D208294/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SKP8797S

 Make & Model:
 PEUGEOT 508, 1.6 (A)
 Engine No:
 10JBFT0062603

 Reg. Date:
 17/10/2014 (Man. Year: 2014)
 Chassis No:
 VF38D9HD8EL017219

Colour: Metallic Black
Engine Capacity: 1560 cc

Engine Capacity: Market Value/New Car

1560

Price:

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,452.00	3,088.40	3,363.60	52.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	1,230.00	710.00	36.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,392.00	4,318.40	4,073.60	48.54
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	8,392.00	3,450.00	4,942.00	58.89
+ GST 7.00/7.00% (S\$)	587.44	241.50	345.94	58.89
Nett Amount (S\$)	8,979.44	3,691.50	5,287.94	58.89

**INSPECTION** 

Date of Assignment: 21/11/2022

Optima Werkz Pte Ltd (HQ)

Date Inspected: 25/11/2022 Inspected At: 6 Kung Chong Road

Singapore 159143

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Dec 2022)

Parts: M1-MPV PEUGEOT 508 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKP8797S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty Part No	o. Particulars	Condition	Repairer's	Amount
1	1	*REAR BOOTLID	Repair	1,347.00 FL	*- FL
2	1	*REAR BOOTLID CHROME MOULDING	Necessary	241.00 FL	*241.00 FL
3	1	*REAR BOOTLID OUTER PANEL	Bent	587.00 FL	*587.00 FL
4	1	*REAR BOOTLID PEUGEOT EMBLEM	Necessary	98.00 FL	*98.00 FL
5	1	*REAR BUMPER 508 EMBLEM	Necessary	88.00 FL	*88.00 FL
6	1	*REAR BOOTLID INNER LOCK	Repair	111.00 FL	*- FL
7	1	*REAR BOOTLID WEATHERSTRIP	Serviceable	277.00 FL	*- FL
8	1	*REAR BUMPER	Cracked	1,065.00 FL	*1,065.00 FL
9	1	*REAR BUMPER LOWER LIP	Mtg Cracked	252.00 FL	*252.00 FL
10	1	*REAR BUMPER TOWING COVER	Repair	65.00 FL	*- FL
11	1	*REAR BUMPER REFLECTOR RH	Serviceable	65.00 FL	*- FL
12	1	*REAR BUMPER REINFORCEMENT	Repair	477.00 FL	*- FL
13	2	*REAR BUMPER PARKING SENSOR	Shorted	492.00 FL	*456.00 FL
14	1	*REAR BUMPER SIDE BRACKET RH	Cracked	115.00 FL	*115.00 FL
15	1	*REAR TAIL LAMP RH	Cracked	474.00 FL	*474.00 FL
16	1	*REAR END PANEL	Repair	971.00 FL	*- FL
17	1	*REAR END PANEL UPPER COVER	Serviceable	255.00 FL	*- FL
18	1	*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
19	1	*REAR END PANEL JOINT SEALANT	Not Necessary	80.00 FS	*- FS
20	1	*REAR END PANEL UPPER COVER CLIPS	Not Necessary	40.00 FS	*- FS
F=Fra	anchise part. S=S <sub> </sub>	ocNett. L=ListItemDisc.			
			Sub Total (S\$)	7,150.00	3,426.00
		- List Item Discount on L	. Items 10.00/10.00% (S\$)	698.00	337.60
			Total Parts (S\$)	6,452.00	3,088.40

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	700.00	500.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FORNISHING MATERIALS AT REAR BOOTLID ,REAR BUMPER ,REAR END PANEL & ETC	New	700.00	600.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED REAR BOOTLID INNER MECHANISIM & ETC ,BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
4	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER PARKING SENSOR & ETC	New	120.00	50.00
5	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	0.00
6	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	100.00	0.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	20.00
	Gross Labour Cost (S\$)		1,940.00	1,230.00
	Report was unsubmitted during this	print-out		

< END OF ESTIMATES >