



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 5744C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR CUT	1,158.00	-
1	HEADLAMP RHS (CONSISTENT)		2,135.00	2,135.00
	LESS 5% DISCOUNT		-	-106.75
			3,293.00	2,028.25
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS AND REPAIR THE ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		500.00	300.00
	TO SPRAY PAINT FRONT BUMPER AND FRONT FENDER RHS.		600.00	400.00
	TO CHECK & SCAN WITH BMW COMPUTER AND CLEAR ALL FAULT CODE.		250.00	80.00
			1,350.00	780.00
GRAND TOTAL			4,643.00	2,808.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,250.00

Report Ref No. CS/ASM22011686/Kqp3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.