



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOW GARNET			Ref: CS/ASM22011686/Kqp3e2 Date: 17/01/2023 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SLC 9639R	Veh. Inspected	SLP 5744C
	Policy No.	P1784310	Coverage (\$)	0.00
	Claim No.	S2M04F0R	Excess (\$)	0.00
	Assign From	LOW GARNET	Assign Date	21/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	B.M.W. 320i (A)	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WBA3B16040NS50927	Colour	METALLIC SILVER
	Odometer	114329 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	CONTINENTAL	7 mm
	L/H Front Tyre	225/40 R18	CONTINENTAL	7 mm
	R/H Rear Tyre	225/40 R18	CONTINENTAL	7 mm
	L/H Rear Tyre	225/40 R18	CONTINENTAL	7 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	16/11/2022	Inspection Date	29/11/2022
	Survey held at	RIVERVIEW AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #04-07 AMK AUTOPOINT SINGAPORE 568047		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	