

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011688/UVP3Q2**Date:** 08/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00055672201		
Claimant Vehicle No :	W9709Y	Insured Vehicle No :	YP3089U		
Date of Loss:	19/11/2022	Nature of Claim:	TP	Claim No:	SNM22D208336/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	W9709Y		Engine No:	G16A32X
Make & Model:	PERODUA ALZA, 1.5 EZ (A)		Chassis No:	PM2M502G002180169
Reg. Date:	01/01/2014 (Man. Year: 2014)		Odometer:	59925 km
Colour:	Black			
Engine Capacity:	1495 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Ardent 6 mm	Rear Left Side:	Ardent 6 mm
Front Right Side:	Ardent 6 mm	Rear Right Side:	Ardent 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,194.10	7,057.09	7,137.01	50.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,420.00	2,570.00	1,850.00	41.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,614.10	9,627.09	8,987.01	48.28
Approved Total (Overridden) (S\$)		7,600.00		
(S\$)	18,614.10	7,600.00	11,014.10	59.17
+ GST 7.00/7.00% (S\$)	1,302.99	532.00	770.99	59.17
Nett Amount (S\$)	19,917.09	8,132.00	11,785.09	59.17

INSPECTION

Date of Assignment:	22/11/2022	
Date Inspected:	21/11/2022 Inspected At:	Carsmith Private Limited (HQ) 13 KAKI BUKIT ROAD 4 #01-20 BARTLEY BIZ CENTRE Singapore 417807
Estimated Period of Repair:	9.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Dec 2022)
Parts:	M1-MPV	PERODUA ALZA 1.5 EZ (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for W9709Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	985.20 F	*680.00 FL
2	1		*REAR BUMPER RETAINER LH	Bent	169.30 F	*68.00 FL
3	1		*REAR BUMPER RETAINER RH	Bent	169.30 F	*68.00 FL
4	1		*REAR BUMPER REFLECTOR LH	Not Necessary	92.20 F	*- FL
5	1		*REAR BUMPER REFLECTOR RH	Not Necessary	92.20 F	*- FL
6	1		*REAR BUMPER TOWING COVER	Not Necessary	52.50 F	*- FL
7	1		*REAR EXHAUST	Repair	845.10 F	*- FL
8	1		*REAR EXHAUST RUBBER	Not Necessary	62.60 F	*- FL
9	1		*REAR END PANEL OUTER }	Badly Dented	756.20 F	*485.00 FL
10	1		*REAR END PANEL INNER }		963.30 F	*- FL
11	1		*REAR END PANEL TOP GARNISH	Distorted	295.80 F	*295.80 FL
12	1		*SPARE TYRE PANEL	Crumpled / Buckled	1,335.20 F	*980.00 FL
13	1		*SPARE TYRE PANEL TOP COVER BOARD	Torn	451.20 F	*451.20 FL
14	1		*SPARE TYRE PANEL TOP INSULATOR	Necessary	250.00 FS	*100.00 FS
15	1		*SPARE TYRE PANEL HOLDER	Bent	325.00 F	*266.00 FL
16	1		*TAILGATE	Badly Dented	1,125.00 F	*820.00 FL
17	1		*TAILGATE LOCK	Dented / Jammed	365.20 F	*225.00 FL
18	1		*TAILGATE CENTRE GARNISH	Cracked	265.30 F	*265.30 FL
19	1		*TAILGATE CENTRE GARNISH EMBLEM	Necessary	95.20 F	*50.00 FL
20	1		*TAILGATE HANDLE	Not Necessary	175.00 F	*- FL
21	1		*TAILGATE EMBLEM ALZA	Necessary	52.50 F	*52.50 FL
22	2		*TAILGATE HINGE	Not Necessary	142.60 F	*- FL
23	1		*TAILGATE INNER BOARD	Torn	548.50 F	*384.00 FL
24	1		*TAILGATE WIPER MOTOR	Bent / Jammed	415.50 F	*415.50 FL
25	2		*TAILGATE ABSORBER	Not Necessary	275.00 F	*- FL
26	1		*TAILGATE WEATHERSTRIP	Twisted	215.40 F	*215.40 FL
27	1		*TAILLAMP LH	Cracked	625.00 F	*420.00 FL
28	1		*TAILLAMP PANEL LH	Repair	215.20 F	*- FL
29	1		*TAILLAMP RH	Cracked	625.00 F	*420.00 FL
30	1		*TAILLAMP PANEL RH	Repair	215.20 F	*- FL
31	1		*3RD BRAKE LAMP	Not Necessary	275.00 F	*- FL
32	1		*WINDSCREEN	Shattered	658.40 F	*658.40 FL
33	1		*WINDSCREEN MOULDING	Necessary	150.00 F	*110.00 FL
34	1		*REAR NUMBER PLATE	Bent	90.00 FS	*40.00 FS
35	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
36	1		*SET REAR BUMPER SENSOR	Shorted	480.00 FS	*200.00 FS
37	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
38	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
39	1		*REAR JOINT SEALANT	Necessary	120.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,194.10	7,790.10
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	733.01
Total Parts (\$)	14,194.10	7,057.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	100.00	20.00
2	REMOVE AND REFIT REAR WINDSCREEN	New	200.00	120.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	50.00
4	REMOVE AND REFIT REAR LINING ,TRIM AND GARNISH	New	150.00	80.00
5	REMOVE AND RENEW REAR EXHAUST	New	150.00	0.00
6	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,800.00	1,200.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,800.00	1,100.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	0.00
Gross Labour Cost (\$\$)			4,420.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >