

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22011710/KYA3Q2**Date:** 12/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800086303
Claimant Vehicle No :	SHD9793U	Insured Vehicle No :	SMC8007J
Date of Loss:	17/11/2022	Nature of Claim:	TP
		Claim No:	6608453182SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9793U		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H36887
Reg. Date:	11/12/2020 (Man. Year: 2020)	Chassis No:	JTDKB3FU203093195
Colour:	Metallic Pearl White/Red	Odometer:	145559 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Wanli 9 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Wanli 9 mm	Rear Right Side:	Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,234.90	1,281.22	5,953.68	82.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,260.00	490.00	4,770.00	90.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	12,494.90	1,771.22	10,723.68	85.82
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	18/11/2022		
Date Inspected:	18/11/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER ,REAR BUMPER	Buckled / Cracked	485.60 FL	*485.60 FL
2	1	*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1	*COVER ,REAR BUMPER LOWER	Dented	22.00 FL	*22.00 FL
4	1	*GUARD ,REAR BUMPER ,CENTER	Cracked	374.50 FL	*374.50 FL
5	1	*RETAINER ,REAR BUMPER SIDE ,RH	Distorted	132.60 FL	*132.60 FL
6	1	*REFLECTOR ASSY ,REFLEX ,RH	Cracked	39.00 FL	*39.00 FL
7	1	*LENS & BODY REAR COMBINATION LAMP ,RH (UPPER)	Serviceable	339.60 FL	*- FL
8	1	*LENS & BODY REAR COMBINATION LAMP ,NO.2 RH (LOWER)	Serviceable	261.00 FL	*- FL
9	1	*COVER SUB-ASSY ,FRONT PILLAR ,UPR RH	Serviceable	100.40 FL	*- FL
10	1	*PANEL SUB-ASSY ,BACK DOOR	Repair	1,147.80 FL	*- FL
11	1	*PLATE ,LUGGAGE COMPARTMENT DOOR NAME NO.2	Not Necessary	54.60 FL	*- FL
12	1	*PLATE ,BACK DOOR NAME NO.1	Not Necessary	54.60 FL	*- FL
13	1	*ORNAMENT SUB-ASSY ,BACK DOOR	Not Necessary	47.90 FL	*- FL
14	1	*GARNISH SUB-ASSY BACK DOOR OUTSIDE	Serviceable	913.60 FL	*- FL
15	1	*WEATHERSTRIP BACK DOOR	Serviceable	372.30 FL	*- FL
16	1	*PAN ,REAR FLOOR	Repair	583.40 FL	*- FL
17	1	*COVER ,FLOOR UNDER NO.1 LH	Serviceable	175.10 FL	*- FL
18	1	*COVER ,FLOOR UNDER NO.2 RH	Distorted	241.90 FL	*241.90 FL
19	1	*COVER ,REAR FLOOR CTR	Serviceable	229.90 FL	*- FL
20	1	*COVER ,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
21	1	*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
22	1	*STAY ASSY ,BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
23	1	*STAY ASSY ,BACK DOOR ,RH	Serviceable	242.50 FL	*- FL
24	1	*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
25	1	*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- FL
26	1	*SET PARKING AID	Serviceable	700.00 FS	*- FS
27	1	*SET REAR BUMPER CLIP	Necessary	95.00 FS	*60.00 FS
28	2	*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
29	1	*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
30	1	*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
31	1	*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
32	1	*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
33	1	*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*- FS
34	1	*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
35	1	*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,058.20	1,688.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,823.30	407.08
Total Parts (\$\$)	7,234.90	1,281.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,400.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
6	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
7	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	220.00
8	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
10	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
11	TO REMOVE AND REPLACE CORPORATE STICKER	New	250.00	0.00
Gross Labour Cost (\$\$)			5,260.00	490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >