

A.C.S. REC'D BY: ToupinREF: CS/ASM-22011711/TWPS**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / MS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$102K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMU 9834LYr Regn: 2020 Sep

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda VezelC.C. 1496Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 56141

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: CU11327394

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215 / 60R16R: a -BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 22/11/22Survey held at Xin Yun

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS, \$1

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B.H. / P

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMU9834L Honda Vezel PI New Model

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ 1,208.00 <i>de</i>
2	1	Rear bumper left bracket	\$ 75.00 <i>one</i>
3	1	Rear bumper right bracket	\$ 75.00 <i>one</i>
4	1	Rear bumper left reflector	\$ 98.00 <i>x</i>
5	1	Rear bumper right reflector	\$ 98.00 <i>x</i>
6	1	Rear bumper tow cover	\$ 88.00 <i>x</i>
7	2	Rear bumper both side cover x2pc	\$ 400.00 <i>Rx</i>
8	1	Rear center center chrome	\$ 300.00 <i>x</i>
9	1	Rear tailgate assy	\$ 1,750.00 <i>bt</i>
10	1	Rear tailgate centre logo	\$ 85.00 <i>one</i>
11	1	Rear tailgate emblem	\$ 68.00 <i>one</i>
12	1	Rear tailgate weatherstrip	\$ 275.00 <i>de</i>
13	1	Rear tailgate lock mechanism	\$ 285.00 <i>bt</i>
14	1	Rear end top garnish	\$ 280.00 <i>de</i>
15	1	Rear tailgate inner trim board	\$ 330.00 <i>x</i>
16	1	Rear tailgate outer garnish-one round garnish cover	\$ 250.00 <i>x</i>
17	2	Rear tailgate no plate lamp	\$ 180.00 <i>x</i>
18	1	Rear tailgate left taillamp	\$ 585.00 <i>one</i>
19	1	Rear tailgate right taillamp	\$ 585.00 <i>x</i>
20	1	Rear left taillamp	\$ 785.00 <i>one</i>
21	1	Rear right taillamp	\$ 785.00 <i>x</i>
22	2	Rear tailgate damper	\$ 300.00 <i>x</i>
23	1	Rear end lower panel	\$ 850.00 <i>Rx</i>
24	1	Exhaust	\$ 800.00 <i>x</i>
25	1	Keyless sensor	\$ 285.00 <i>one</i>
26	1	Tailgate switch	\$ 295.00 <i>x</i>
Parts Sub-total			\$ 9,493.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SMU9834L Honda Vezel PI New Model

			Estimated Parts Price	
No	Qty	Parts Description		
<u>Special Nett Items</u>				
1	10	Rear bumper clips	\$	80.00 3 Only ✓
2	8	Rear end lower panel top garnish clips	\$	80.00 x
3	1	Rear end lower panel sealant	\$	120.00 x
4	8	Rear tailgate inner trim board clips	\$	50.00 x
5	6	Rear tailgate outer garnish clips	\$	50.00 x
6	1	Rear floor panel sealant	\$	120.00 x
7	1	Rear windscreen glass sealant	\$	80.00 50ml ✓
8	10	Rear windscreen inner side garnish clips	\$	80.00 3 Only ✓
9	2	Rear bumper reverse sensor	\$	500.00 200mm ✓
10	1	Rear no plate with casing	\$	80.00 x
24	1	Rear windscreen glass rubber seal	\$	105.00 x
Special Nett Items			\$	1,075.00



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

Number Plate: SMU9834L

Modle: HONDA VEZEL

No	Description	Labour Charges
1	Checking rear wiring harness and lighting system for proper function	\$ 80.00 30
2	Carry up body cavity preservation for affected area \$50 per panel	\$ 200.00 30
3	Replacing accident damages parts, knock, jack and straighten accident damages area	\$ 1,500.00 600
4	Spray painting for accident affected damaged area, including: Tailgate in & out, bumper, rear end panel side cover x2, fender	\$ 1,750.00 600
5	To replacing rear undercarriage parts, including brake bleeding brake system etc.	\$ 120.00 x
5	Replacing rim /tyre, including rear wheel balancing	\$ 100.00 x
6	Carry out wheel alignment	\$ 120.00 x
7	Removing and installing rear bootlid compartment garnish, trimming etc, to facilitate the necessary repair.	\$ 150.00 x
8	Transferring tailgate /bootlid lock mechanisam, trimming etc to the new tailgate /bootlid	\$ 120.00 60
9	Removing and installing rear exhaust muffler assy to facilitate the repair	\$ 150.00 x
10	Checking central lock system for proper function	\$ 120.00 x
11	Removing and installing rear fender internal garnish and training to facilitate the necessary repair	\$ 120.00 60
12	Removing and installing rear window /windscreen glass	\$ 150.00 120
13	To remove and install rear camera	\$ 80.00 x

MV: \$102K.

Taufik 97495749
 'WP' 28/11/22 @ 2pm
 L/S Resurvey after repair
 Taufik @ Kuantan on
 05 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Stamp: