2/27/23, 1:17 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI22011715/TWY3Q2

27/02/2023 Date:

REFERENCE

No:

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: ML000183 **Claimant Vehicle**

SHA7144Y Insured Vehicle No: GBK9851U

Date of Loss: 20/11/2022 Nature of Claim: TP Claim No: M2206575

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA7144Y**

TOYOTA PRIUS TAXI, 1.8 (A) 2ZR2C20813 Make & Model: **Engine No:**

Reg. Date: 29/05/2019 (Man. Year: 2018) Chassis No: JTDKB3FU503080831

Colour: Odometer: 403766 km Blue

Engine Capacity: 1798 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Good Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes **Engine Modification:** No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 195/65 R15 Rear Tyre Size: Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,391.56	557.72	833.84	59.92
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	970.00	630.00	340.00	35.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,372.56	1,198.72	1,173.84	49.48
Approved Total (Overridden) (S\$)		950.00		
(S\$)	2,372.56	950.00	1,422.56	59.96
+ GST 7.00/7.00% (S\$)	166.08	66.50	99.58	59.96
Nett Amount (S\$)	2,538.64	1,016.50	1,522.14	59.96

INSPECTION

Date of Assignment: 22/11/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 22/11/2022 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Feb 2023)

Parts: 144 TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA7144Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*REAR BUMPER	Repair	503.04 FL	*- FL
2		*REAR BUMPER BRACKET - LH / RH	Not Necessary	61.40 FL	*- FL
1		*REAR BUMPER LOWER COVER	Cut	654.96 FL	*654.96 FL
1		*REAR BUMPER RENFORCEMENT	Not Necessary	378.32 FL	*- FL
10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
1		*REAR BUMPER MAT	Not Necessary	50.00 FL	*- FL
1		*REAR BUMPER REVERSE SENSOR	Not Necessary	135.70 FL	*- FL
1		*REAR BUMPER ADVERTISEM,ENT	Cut	50.00 FL	*50.00 FS
nchise	part. S=SpcNe	ett. L=ListItemDisc.	-		
			Sub Total (S\$)	1,855.42	726.96
		- List Item Discount or	L Items 25.00/25.00% (S\$)	463.86	169.24
			Total Parts (S\$)	1,391.56	557.72
	1 2 1 1 10 1 1	1 1 10 1 1	1 *REAR BUMPER 2 *REAR BUMPER BRACKET - LH / RH 1 *REAR BUMPER LOWER COVER 1 *REAR BUMPER RENFORCEMENT 10 *REAR BUMPER CLIPS 1 *REAR BUMPER MAT 1 *REAR BUMPER REVERSE SENSOR 1 *REAR BUMPER ADVERTISEM,ENT Inchise part. S=SpcNett. L=ListItemDisc.	1 *REAR BUMPER BRACKET - LH / RH Not Necessary 1 *REAR BUMPER LOWER COVER Cut 1 *REAR BUMPER RENFORCEMENT Not Necessary 10 *REAR BUMPER CLIPS Necessary 1 *REAR BUMPER MAT Not Necessary 1 *REAR BUMPER REVERSE SENSOR Not Necessary 1 *REAR BUMPER REVERSE SENSOR Not Necessary 1 *REAR BUMPER ADVERTISEM,ENT Cut Inchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 25.00/25.00% (S\$)	1 *REAR BUMPER Repair 503.04 FL 2 *REAR BUMPER BRACKET - LH / RH Not Necessary 61.40 FL 1 *REAR BUMPER LOWER COVER Cut 654.96 FL 1 *REAR BUMPER RENFORCEMENT Not Necessary 378.32 FL 10 *REAR BUMPER CLIPS Necessary 22.00 FL 1 *REAR BUMPER MAT Not Necessary 50.00 FL 1 *REAR BUMPER REVERSE SENSOR Not Necessary 135.70 FL 1 *REAR BUMPER ADVERTISEM,ENT Cut 50.00 FL Inchise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) 1,855.42 - List Item Discount on L Items 25.00/25.00% (S\$) 463.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount		
Misc	Miscellaneous Items						
1	1	OD/TP Case (Insurer)		11.00	11.00		
			Sub Total (S\$)	11.00	11.00		

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	PANEL BEATING	New	550.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
4	TUFF COATING	New	60.00	0.00
		Gross Labour Cost (S\$)	970.00	630.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.