

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22011716/Sqp3e2
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	09/12/2022
	ATTN: ANG YVON	NE		Code:	ASM
1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SH 6569U	Veh. Inspected	k	SJM 4487R
	Policy No.		Coverage (\$)		0.00
	Claim No.	S2M04F9S	Excess (\$)		0.00
	Assign From	ANG YVONNE	Assign Date		22/11/2022
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA AXIO	c.c		1496
	Engine No.	HIDDEN	Year of Reg.		2009
	Chassis No.	NZE1416096043	Colour		BLUE
	Odometer	308478 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	MAXXIS		5 mm
	L/H Front Tyre	195/65 R15	MAXXIS		5 mm
	R/H Rear Tyre	195/65 R15	MAXXIS		5 mm
	L/H Rear Tyre	195/65 R15	MAXXIS		5 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information					
	Accident Date	22/11/2022	Inspect Date /	Time	22/11/2022 (04:00 PM)
	Survey held at	JHK AUTO SERVICES			
	BLK 3007 UBI ROAD 1, #01-406 SINGAPORE 408701				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,500				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

Report Ref No. CS3/ASM22011716/Sqp3e2

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

K.K.LAU CPT(RET)

Asst. Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser