



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 9817G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER (CONSISTENT)	DEFORMED	1,304.00	1,304.00
2	REAR BUMPER SIDE HOLDER @\$45.00 (CONSISTENT)	NOT NECESSARY	90.00	-
2	REAR BUMPER REFLECTOR @\$89.00 (CONSISTENT)	NOT NECESSARY	178.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	651.00	-
1	REAR BUMPER LOWER GARNISH (CONSISTENT)	DEFORMED	343.00	343.00
1	REAR BUMPER CENTRE GUIDE (CONSISTENT)	DEFORMED	195.00	195.00
4	REVERSE SENSOR @\$265.00 (CONSISTENT)	DAMAGED (1PC ONLY)	1,060.00	265.00
	LESS 10% DISCOUNT		-	-210.70
			3,821.00	1,896.30
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR NUMBER PLATE HOLDER (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
			90.00	30.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		500.00	200.00
	SPRAY PAINTING.		500.00	200.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
			1,150.00	480.00
<b>GRAND TOTAL</b>			<b>5,061.00</b>	<b>2,406.30</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,900.00</b>

Report Ref No. CS/ASM22011719/Aqp3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.