

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT                 |   |  |                |       |                         |  |
|--|---|--|----------------|-------|-------------------------|--|
|  | AXA INSURANCE   | PTE LTD  |                | Ref:  | CS3/ASM22011721/Tnp3m4  |  |
|  | 8 SHENTON WAY<br>SINGAPORE 0688   | #24-01 AXA TOWER<br>11                                     |                | Date: | 16/12/2022              |  |
|  | ATTN: HO WINNIE   |  |                | Code: | ASM                     |  |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) |   |  |                |       |                         |  |
|  | Insured Veh.  | SHA 2253Z  | Veh. Inspected | t     | SLK 5836Y               |  |
|  | Policy No.  | VFX/P2419138   | Coverage (\$)  |       | 0.00                    |  |
|  | Claim No.   | S2M04F4J   | Excess (\$)    |       | 0.00                    |  |
|  | Assign From   | HO WINNIE  | Assign Date    |       | 22/11/2022              |  |
| 2. Vehicle Particulars & Condition           |   |  |                |       |                         |  |
|  | Make & Model  | CHEVROLET ORLANDO  | c.c            |       | 1362                    |  |
|  | Engine No.  | HIDDEN   | Year of Reg.   |       | 2017                    |  |
|  | Chassis No.   | KL1YA7589HK608364  | Colour         |       | WHITE                   |  |
|  | Odometer  | 288703 KM  | Steering       |       | IN ORDER                |  |
|  | Brakes  | IN ORDER   | Modification   |       | SPORTS RIM              |  |
|  | General   | GOOD   |                |       |                         |  |
| 3. Conditions of Tyres                       |   |  |                |       |                         |  |
|  |   | Size   | Make           |       | Balance                 |  |
|  | R/H Front Tyre  | 215/60 R16   | MAXTREK        |       | 6 mm                    |  |
|  | L/H Front Tyre  | 215/60 R16   | MAXTREK        |       | 6 mm                    |  |
|  | R/H Rear Tyre   | 215/60 R16   | MAXTREK        |       | 6 mm                    |  |
|  | L/H Rear Tyre   | 215/60 R16   | MAXTREK        |       | 6 mm                    |  |
| 4.   | Description of Damages  |  |                |       |                         |  |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  |  |                |       |                         |  |
| 5.   | . General Information   |  |                |       |                         |  |
|  | Accident Date   | 17/11/2022   | Inspect Date / | Time  | 22/11/2022 ( 05:50 PM ) |  |
|  | Survey held at  | held at BLK 3012 BEDOK INDUSTRIAL PARK E #01-2016 & 2048 S |                |       |                         |  |
|  | Repairer  | Repairer YK SUPREME AUTOWERKZ PTE LTD                      |                |       |                         |  |
| 5a.  | Remarks   |  |                |       |                         |  |
|  | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000 |  |                |       |                         |  |
| 5b.  | Estimate Days of Repair   |  |                |       |                         |  |
|  | ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days  |  |                |       |                         |  |

Report Ref No. CS3/ASM22011721/Tnp3m4

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser