

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Page No.:1 of 2 ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNE 801M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER RH	BADLY DENTED	1,572.00	1,572.00
1	REAR BUMPER	CUT	1,418.00	1,418.00
1	REAR BUMPER RETAINER RH	NOT NECESSARY	148.00	-
1	REAR WHEEL HUB BEARING RH	NOT NECESSARY	681.00	-
1	REAR KNUCKLE ARM RH (NPA)	NOT NECESSARY	-	-
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	215.00	-
1	REAR ABSORBER MOUNTING RH	NOT NECESSARY	142.00	-
	LESS 10% DISCOUNT		-	-299.00
			4,176.00	2,691.00
	SPECIAL NETT ITEMS			
1	REAR WHEEL RIM RH (SN)	CUT / WARPED	1,752.00	600.00
1	REAR DOOR RH (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
1	REAR FENDER WHEEL HOUSING RH (NPA) (SN)	TO REPAIR SEE LABOUR	-	-
1	REAR TYRE RH (SN)	SERVICEABLE	580.00	-
			2,332.00	600.00
	<u>LABOUR</u>			
	LABOUR TO REMOVE & REFIT NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF REAR DOOR RH AND REAR FENDER WHEEL HOUSING RH.		1,000.00	600.00
	SPRAY PAINT ON THE AFFECTED AREAS.		1,000.00	600.00
	ANTI-RUST COATING.		150.00	30.00
	TO REMOVE & REFIT UNDERCARRIAGE.	NOT NECESSARY	350.00	-
	TO REMOVE & REFIT CUSHION & UPHOLSTERY .		300.00	80.00
	TO REMOVE & REFIT FUEL TANK.		300.00	60.00
	FOUR WHEEL ALIGNMENT.		150.00	60.00
			3,250.00	1,430.00
	GRAND TOTAL		9,758.00	4,721.00

Report Ref No. CS/AGI22011725/Uny3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	3,700.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/AGI22011725/Uny3q2

CHUA KANG SENG

**Licensed Appraiser**