

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011729/AQP3Q2**Date:** 01/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00164362200
Claimant Vehicle No :	SKM3017J	Insured Vehicle No :	SKL1306T
Date of Loss:	21/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D208346/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM3017J	Engine No:	G4KJDH735821
Make & Model:	KIA SORENTO, 2.2 (A)	Chassis No:	KNAKU816ME5470474
Reg. Date:	18/02/2014 (Man. Year: 2013)	Odometer:	142436 km
Colour:	Silver		
Engine Capacity:	2359 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Habilead 6 mm	Rear Left Side:	Habilead 6 mm
Front Right Side:	Habilead 6 mm	Rear Right Side:	Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,469.60	3,614.25	2,855.35	44.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	750.00	900.00	54.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,119.60	4,364.25	3,755.35	46.25
Approved Total (Overridden) (S\$)		3,400.00		
Nett Amount (S\$)	8,119.60	3,400.00	4,719.60	58.13

INSPECTION

Date of Assignment:	22/11/2022	Automobile Hub Enterprise 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT Singapore 417883
Date Inspected:	23/11/2022 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jan 2023)
Parts:	M1-SUV	KIA SORENTO 2.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM3017J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	645.40 F	*645.40 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER SIDE HOLDER LH	Damaged	34.20 F	*34.20 FL
4	1		*FRONT BUMPER LOWER GARNISH	Cut	348.90 F	*348.90 FL
5	1		*FRONT BUMPER SENSOR	Damaged	245.40 F	*245.40 FL
6	1		*FRONT BUMPER FOG LAMP LH	Cracked	352.80 F	*352.80 FL
7	1		*FRONT BUMPER FOG LAMP COVER LH	Cracked	151.40 F	*151.40 FL
8	1		*FRONT BUMPER SPONGE	Not Necessary	130.60 F	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	142.50 F	*- FL
10	1		*HEADLAMP LH	Cracked	2,059.30 F	*2,059.30 FL
11	1		*FRONT LH FENDER	Repair	447.30 F	*- FL
12	1		*FRONT LH FENDER ARC GARNISH	Not Necessary	224.20 F	*- FL
13	1		*FRONT LH FENDER ARC GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
14	1		*FRONT LH WING MIRROR	Repair	642.50 F	*- FL
15	1		*FRONT LH WING MIRROR SIGNAL LAMP	Cut	145.10 F	*145.10 FL
16	1		*FRONT LH WHEEL RIM	Not Necessary	850.00 FS	*- FS
					Sub Total (\$\$)	6,469.60 4,012.50
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 398.25
					Total Parts (\$\$)	6,469.60 3,614.25

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	700.00	300.00
2	SPRAY PAINTING	New	600.00	400.00
3	WIRING	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	20.00
5	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
Gross Labour Cost (S\$)			1,650.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >