

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011734/SQP3E2**Date:** 13/02/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00207692200

**Claimant Vehicle
No :** SFW31T**Insured Vehicle
No :** SNG1481K

Date of Loss: 20/11/2022

Nature of Claim: TP

Claim
No: SNM22D208348/C02/LEEPGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SFW31T**

Make & Model: KIA CARENS, 1.7 D DCT DIESEL 5DR FWD (A)

Engine No: D4FDJH553020

Reg. Date: 06/06/2018 (Man. Year: 2018)

Chassis No: KNAHU815VJ7208295

Colour: Brown

Odometer: 80575 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,700.60	3,954.20	4,746.40	54.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,720.00	1,630.00	2,090.00	56.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,420.60	5,584.20	6,836.40	55.04
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	12,420.60	4,200.00	8,220.60	66.19
+ GST 8.00/8.00% (S\$)	993.65	336.00	657.65	66.19
Nett Amount (S\$)	13,414.25	4,536.00	8,878.25	66.19

INSPECTION

Date of Assignment: 22/11/2022

Date Inspected: 23/11/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Feb 2023)
Parts:	M1-MPV	KIA CARENS 1.7 D DCT DIESEL 5DR FWD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFW31T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	1,219.00 FL	*1,219.00 FL
2	1		*TAILGATE CRDI EMBLEM	Necessary	33.00 FL	*20.00 FL
3	1		*TAILGATE CARANS EMBLEM	Necessary	42.00 FL	*20.00 FL
4	1		*TAILGATE CENTRE EMBLEM	Not Necessary	56.00 FL	*- FL
5	1		*TAILGATE LOCK	Not Necessary	112.00 FL	*- FL
6	1		*TAILGATE LOCK CATCH	Not Necessary	35.00 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Bent	378.00 FL	*200.00 FL
8	1		*TAILGATE WEATHERSTRIP	Cut	134.00 FL	*134.00 FL
9	1		*REAR BUMPER TOP	Cracked	576.00 FL	*576.00 FL
10	1		*REAR BUMPER LOWER	Cracked	231.00 FL	*180.00 FL
11	1		*REAR BUMPER CENRE SKID PLATE GARNISH	Cracked	182.00 FL	*150.00 FL
12	1		*REAR BUMPER RH SIDE REVERSE SENSOR	Not Necessary	167.00 FL	*- FL
13	1		*REAR BUMPER RH REVERSE SENSOR	Shorted	167.00 FL	*167.00 FL
14	1		*REAR BUMPER LH REVERSE SENSOR	Shorted	167.00 FL	*167.00 FL
15	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Not Necessary	167.00 FL	*- FL
16	4		*REAR BUMPER REVERSE SENSOR HOLDES	Necessary	22.00 FL	*22.00 FL
17	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	251.00 FL	*- FL
18	1		*REAR BUMPER REINFORCEMENT	Cracked	367.00 FL	*300.00 FL
19	1		*REAR BUMPER REINFORCEMENT RH BRACKET	Not Necessary	167.00 FL	*- FL
20	1		*REAR BUMPER REINFORCEMENT LH BRACKET	Not Necessary	167.00 FL	*- FL
21	1		*REAR BUMPER RH BRACKET	Cracked	22.00 FL	*22.00 FL
22	1		*REAR BUMPER LH BRACKET	Cracked	22.00 FL	*22.00 FL
23	1		*REAR BUMPER RH LOWER BRACKET	Not Necessary	18.00 FL	*- FL
24	1		*REAR BUMPER LH LOWER BRACKET	Not Necessary	18.00 FL	*- FL
25	1		*REAR BUMPER CENTRE BRACKET	Not Necessary	37.00 FL	*- FL
26	1		*REAR BUMPER RH FOG LAMP	Not Necessary	127.00 FL	*- FL
27	1		*REAR BUMPER LH FOG LAMP	Not Necessary	127.00 FL	*- FL
28	1		*REAR BUMPER RH SIDE RETAINER	Not Necessary	27.00 FL	*- FL
29	1		*REAR BUMPER LH SIDE RETAINER	Not Necessary	27.00 FL	*- FL
30	1		*REAR BUMPER TOWING COVER	Not Necessary	16.00 FL	*- FL
31	1		*END PANEL	Repair	543.00 FL	*- FL
32	1		*END PANEL PANEL	Repair	188.00 FL	*- FL
33	1		*END PANEL INNER GARNISH	Broken	89.00 FL	*89.00 FL
34	1		*RH TAILLAMP ASSY	Not Necessary	456.00 FL	*- FL
35	1		*RH TAILLAMP PANEL	Not Necessary	113.00 FL	*- FL
36	1		*SET RH TAILLAMP LOCK CLIPS	Not Necessary	15.00 FL	*- FL
37	1		*LH TAILLAMP ASSY	Not Necessary	456.00 FL	*- FL
38	1		*LH TAILLAMP PANEL	Not Necessary	113.00 FL	*- FL
39	1		*SET LH TAILLAMP LOCK CLIPS	Not Necessary	15.00 FL	*- FL
40	1		*REAR COMPARTMENT TRIM BOX	Not Necessary	223.00 FL	*- FL
41	1		*REAR RH FENDER INNER TRIM BOARD	Cracked	421.00 FL	*400.00 FL
42	1		*REAR LH FENDER INNER TRIM BOARD	Cracked	421.00 FL	*400.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*TAILGATE WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*50.00 FS
44	1		*TAILGATE WINDSCREEN GLASS INNER SEAL	Necessary	60.00 FS	*30.00 FS
45	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	80.00 FS	*50.00 FS
46	1		*TAILGATE C&C EMBLEM	Necessary	120.00 FS	*45.00 FS
47	1		*TAILGATE REVERSE CAMERA	Not Necessary	680.00 FS	*- FS
48	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*40.00 FS
49	1		*SET REAR FENDER RH INNER BOARD CLIPS	Necessary	70.00 FS	*30.00 FS
50	1		*SET REAR FENDER LH INNER BOARD CLIPS	Necessary	70.00 FS	*30.00 FS
51	1		*END PANEL JOINT SEALANT	Not Necessary	70.00 FS	*- FS
52	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,514.00	4,363.00
- List Item Discount on L Items 10.00/10.00% (S\$)	813.40	408.80
Total Parts (S\$)	8,700.60	3,954.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE, CHECK, REPLACE AND REINSTALL DAMAGES BODYPARTS. TO PANEL BEATING, CUT / WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,400.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	100.00	60.00
5	REMOVE AND REINSTALL TAILGATE WINDSCREEN GLASS TO ASSIST REPAIR	New	240.00	120.00
6	REMOVE AND REPLACE TAILGATE INNER PARTS TO NEW TAILGATE	New	180.00	60.00
7	REMOVE AND REPLACE TAILGATE REVERSE CAMERA TO ASSIST REPAIR	New	100.00	50.00
8	REMOVE AND REPLACE REAR INNER TRIMS, GARNISH, BOARDS AND MAT TO ASSIST REPAIR	New	320.00	60.00
9	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	50.00
Gross Labour Cost (S\$)			3,720.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >