

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011736/KQP3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00226342200

Claimant Vehicle No : SLC4876E **Insured Vehicle No :** SDW1524E

Date of Loss: 18/11/2022 Nature of Claim: TP Claim No: SNM22D208337/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC4876E**

Make & Model: HONDA VEZEL, 1.5 (A) Engine No: LEB5070533

Reg. Date: 17/05/2016 (Man. Year: 2016) Chassis No: RU31120517

Colour: Metallic Black Odometer: 140832 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 10,730.42 | 2,481.12 | 8,249.30 | 76.88 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,700.00 | 1,530.00 | 1,170.00 | 43.33 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 13,430.42 | 4,011.12 | 9,419.30 | 70.13 |
| Approved Total (Overridden) (\$\$) | | 3,200.00 | | |
| Nett Amount (\$\$) | 13,430.42 | 3,200.00 | 10,230.42 | 76.17 |

INSPECTION

Date of Assignment: 22/11/2022

Date Inspected: 22/11/2022 Inspected At: Autoworx House - Sin Ming (HQ)
176 SIN MING DRIVE #02-01
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|---|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 17 Apr 2023) |
| Parts: | M1-SUV | HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SLC4876E) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|-------------------------------|-------------|------------|
| 1 | 1 | | *REAR BUMPER CENTER PAD | Bent | 897.62 FL | *762.00 FL |
| 2 | 1 | | *REAR BUMPER SIDE PAD | N/S Serviceable/O/SMtgCracked | 866.40 FL | *182.00 FL |
| 3 | 16 | | *REAR BUMPER CLIP | Necessary | 51.20 FL | *51.20 FL |
| 4 | 2 | | *REAR BUMPER SIDE RETAINER | Serviceable | 157.80 FL | *- FL |
| 5 | 2 | | *REAR BUMPER REFLECTOR | Serviceable | 592.80 FL | *- FL |
| 6 | 1 | | *REAR BUMPER LOWER DUST COVER | Serviceable | 422.10 FL | *- FL |
| 7 | 1 | | *REAR END OUTER PANEL | Repair | 863.74 FL | *- FL |
| 8 | 1 | | *REAR END INNER SUB PANEL | No such part | 552.30 FL | *- FL |
| 9 | 1 | | *REAR END PANEL TRIM | Mtg Cracked | 363.20 FL | *266.00 FL |
| 10 | 1 | | *REAR REMOTE LOCK BUZZER | Serviceable | 265.40 FL | *- FL |
| 11 | 1 | | *REAR REMOTE LOCK SENSOR | Serviceable | 314.80 FL | *- FL |
| 12 | 1 | | *REAR TAIL DOOR LOCK CATCH | Repair | 84.60 FL | *- FL |
| 13 | 1 | | *REAR TAIL DOOR EMBLEM VEZEL | Necessary | 67.50 FL | *67.50 FL |
| 14 | 1 | | *REAR TAIL DOOR EMBLEM LOGO | Not Necessary | 62.80 FL | *- FL |
| 15 | 1 | | *REAR TAIL DOOR WEATHERSTRIP | Serviceable | 369.51 FL | *- FL |
| 16 | 1 | | *REAR TAIL DOOR GLASS MOULDING | Necessary | 269.40 FL | *112.00 FL |
| 17 | 1 | | *REAR TAIL DOOR OUTER GARNISH | Serviceable | 598.74 FL | *- FL |
| 18 | 2 | | *REAR TAIL DOOR LAMP | Serviceable | 1,197.20 FL | *- FL |
| 19 | 2 | | *REAR TAIL LAMP | Serviceable | 1,096.20 FL | *- FL |
| 20 | 3 | | *REAR TAIL LAMP CLIP | Not Necessary | 10.80 FL | *- FL |
| 21 | 3 | | *REAR TAIL LAMP CLIP GORMET | Not Necessary | 8.55 FL | *- FL |
| 22 | 1 | | *REAR TAIL LAMP HOUSING PANEL | Repair | 561.00 FL | *- FL |
| 23 | 1 | | *REAR TAIL DOOR | Bent | 1,693.50 FL | *953.00 FL |
| 24 | 1 | | *REAR TAIL DOOR INNER TRIM | Serviceable | 568.65 FL | *- FL |
| 25 | 1 | | *REAR TAIL DOOR SERVO LIFTER LH | Serviceable | 354.11 FL | *- FL |
| 26 | 1 | | *REAR TAIL DOOR RUBBER STOPPER LH | Serviceable | 16.20 FL | *- FL |
| 27 | 1 | | *REAR TAIL DOOR LOCK | Dented | 215.40 FL | *145.00 FL |
| 28 | 1 | | *REAR FENDER ARCH PROTECTOR (O/S) | Buckled | 196.40 FL | *196.40 FL |
| 29 | 9 | | *REAR FENDER ARCH PROTECTOR CLIP | Necessary | 28.80 FL | *28.80 FL |
| 30 | 1 | | *REAR FENDER DUST COVER | Serviceable | 186.70 FL | *- FL |
| 31 | 8 | | *REAR FENDER DUST COVER CLIP | Not Necessary | 29.60 FL | *- FL |
| 32 | 1 | | *SET REVERSE SENSOR | Shorted | 250.00 FS | *200.00 FS |
| 33 | 1 | | *REAR TAIL DOOR GLASS INNER SEAL | Necessary | 45.00 FS | *30.00 FS |
| 34 | 1 | | *TUBE WINDSCREEN GLASS SEALANT | Necessary | 65.00 FS | *40.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------|----------|
| Sub Total (\$\$) | 13,323.02 | 3,033.90 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 2,592.60 | 552.78 |
| Total Parts (\$\$) | 10,730.42 | 2,481.12 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE ,PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS | New | 1,000.00 | 500.00 |
| 2 | TO CHECK WIRING SYSTEM | New | 60.00 | 20.00 |
| 3 | TO APPLY RUST PROOFING ON AFFECTED AREAS | New | 120.00 | 30.00 |
| 4 | TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS | New | 120.00 | 0.00 |
| 5 | TO APPLY PUTTY AND SPRAY PAINTING ON AFFECTED AREAS (12 SURFACES) | New | 950.00 | 700.00 |
| 6 | TO INSTALL REVERSE SENSORS AND REVERSE CAMERA | New | 120.00 | 50.00 |
| 7 | TO REMOVE REAR GLASS TO ENABLE REPAIR | New | 150.00 | 120.00 |
| 8 | TO REMOVE CARPET ,TRIMMING AND SEATS TO ENABLE REPAIR | New | 120.00 | 50.00 |
| 9 | TO TRANSFER TAIL DOOR ACCESSORIES | New | 60.00 | 60.00 |
| Gross Labour Cost (\$\$) | | | 2,700.00 | 1,530.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >