

11/21/22, 11:36 AM

Estimate Report

Accord Auto Services Pte Ltd (Co.Reg.No:201113141K)10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	JF1SJGK85GG070809	Date of Loss:	14/11/2022
Vehicle Reg. No.:	SGM40H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	RAJ KUMAR S/O GUNALAN	Contact No:	+6581111077
Driver:	RAJ KUMAR S/O GUNALAN		
Make/Model:	SUBARU IMPREZA, 2.0 (A)	Vehicle Reg. Date:	03/05/2016
Vehicle Colour:	BLUE	Chassis No:	JF1SJGK85GG070809
Engine No:	FA20A909748		
Odometer:	65415 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)		

*Not available
Repair by paint
5 days*

COST OF CLAIMS

	Amount
Parts	5,373.50
Miscellaneous Items	680.00
Labour	2,220.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	8,273.50
+ GST 7.00% (S\$)	579.15
Nett Amount (S\$)	8,852.65

This claim is handled by: **GOH JACQUELINE**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

11/21/22, 11:36 AM

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 21 Nov 2022)
 Parts: N/A SUBARU IMPREZA 2.0 (A) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGM40H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1			0.00	0.00	R *540.00 F	✓
2	1		*FRONT BONNET	0.00	0.00	R *50.00 F	X
3	1		*FRONT BONNET HINGE LH & RH	0.00	0.00	DI *40.00 F	✓
4	1		*FRONT BONNET LOCK	0.00	0.00	su *10.00 F	X
5	1		*FRONT BONNET STOPPER	0.00	0.00	CM *130.00 F	✓
6	1		*FRONT BONNET CHROME	0.00	0.00	R *90.00 F	✓
7	1		*FRONT GRILLE @ TOP	0.00	0.00	R *55.00 F	✓
8	1		*FRONT GRILLE LOGO	0.00	0.00	CM *190.00 F	✓
9	1		*FRONT GRILLE LOWER	0.00	0.00	Bu *300.00 F	✓
10	1		*FRONT BUMPER	0.00	0.00	su *20.00 F	X
11	1		*FRONT BUMPER SIDE RETAINER LH & RH	0.00	0.00	*1,450.00 F	✓
12	1		*FRONT HEADLAMP RH	0.00	0.00	*30.00 F	✓
13	1		*FRONT HEADLAMP LOWER BRACKET	0.00	0.00	su *140.00 F	X
14	1		*FRONT FOGLAMP LH	0.00	0.00	su *60.00 F	X
15	1		*FRONT FOGLAMP RH	0.00	0.00	su *140.00 F	X
16	1		*FRONT FOGLAMP GARNISH LH	0.00	0.00	su *60.00 F	X
17	1		*FRONT FOGLAMP GARNISH RH	0.00	0.00	*80.00 F	✓
18	1		*NOZZLE MOTOR LH	0.00	0.00	mi *45.00 F	✓
19	1		*NOZZLE MOTOR RH	0.00	0.00	*80.00 F	✓
20	1		*NOZZLE COVER LH	0.00	0.00	mi *45.00 F	✓
21	1		*FRONT REINFORCMENT BAR	0.00	0.00	R *200.00 F	✓
22	1		*FRONT BUMPER SPONGE	0.00	0.00	*130.00 F	✓
23	1		*FRONT BUMPER SIDE GARNISH LH & RH	0.00	0.00	*40.00 F	✓
24	1		*FRONT FENDER LH	0.00	0.00	R *300.00 F	X
25	1		*FRONT FENDER SHIELD LH	0.00	0.00	su *70.00 F	X
26	1		*FRONT FENDER RH	0.00	0.00	R *300.00 F	X
27	1		*FRONT FENDER SHIELD RH	0.00	0.00	su *70.00 F	X
28	1		*FRONT LH SIGNAL LAMP	0.00	0.00	su *110.00 F	X
29	1		*FRONT RH SIGNAL LAMP	0.00	0.00	*110.00 F	✓

F=Franchise part.

Sub Total (\$\$)

4,885.00

+ Margin on L,N Items 10.00% (\$\$)

488.50

Total Parts (\$\$)

5,373.50

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS



SI

Estimates on Miscellaneous Items

IMPORT	Particulars
1. Please	CAR PLATE NUMBER WITH HOLDER
2. This	FRONT BUMPER CLIPS
3. Inf	FRONT BUMPER LOWER SPOILER LIP
4. poli	FRONT BUMPER UNDER COVER CLIPS
5. F	FRONT FENDER INNER SHILED CLIPS LH & RH
6. 1	FRONT GRILLE CLIPS

Amount

CM	50.00	4512
MC	45.00	✓
NZ	400.00	X
NA	50.00	X
NA	100.00	X
MC	35.00	✓

Sub Total (S\$) 680.00

Estimates on Labour

No Particulars

Labour Items

	Lab.Type	Amount
1 SPRAY PAINT ON ALL AFFECTED AREA	New	1,000.00
2 LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00
3 TO CHECK WIRING SYSTEM & LIGHT	New	120.00
4 TO APPLY ANTI RUST TREATMENT	New	100.00

Gross Labour Cost (S\$) 2,220.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after sprav painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowe
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

system