

Plate Number	Case Number	Brand	Model Details	Body Type	Insurance company	Export CSV
GBF5380P	-	Toyota	Hiace	MPV	India International	
Technician	SA	Parts Manager				
-	LKK_assignments	-				

Parts

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	FRONT WIND SCREEN <div>Customized</div>			\$0.00	\$980.30	-25 %	1	\$735.22
02	FRONT WIND SCREEN WEA THERSTRIP <div>Customized</div>			\$0.00	\$228.90	-25 %	1	\$171.68
03	A PILLAR OUTER <div>Customized</div>			\$0.00	\$389.00	-25 %	1	\$291.75
04	MIRROR STAY WITH SIDE MIRROR <div>Customized</div>			\$0.00	\$636.40	-25 %	1	\$477.30
05	ROUND MIRROR <div>Customized</div>			\$0.00	\$145.50	-25 %	1	\$109.13
06	BLACK MOLDING LH <div>Customized</div>			\$0.00	\$195.90	-25 %	1	\$146.93
07	MIRROR STAY CAP <div>Customized</div>			\$0.00	\$49.50	-25 %	1	\$37.13
08	MIRROR STAY COVER <div>Customized</div>			\$0.00	\$198.50	-25 %	1	\$148.88
09	BLACK TRIM LH			\$0.00	\$113.50	-25 %	1	\$85.13

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
	Customized							
10	HEADLAMP L H Customized			\$0.00	\$727.10	-25 %	1	\$545.33
11	FRONT DOOR LH Customized			\$0.00	\$1280.00	-25 %	1	\$960.00
12	FRONT DOOR QTR TRIM LH Customized			\$0.00	\$28.60	-25 %	1	\$21.45
13	WINDSOW GL ASS LH DOOR Customized			\$0.00	\$408.00	-25 %	1	\$306.00
14	WINDOW CHA NNEL Customized			\$0.00	\$111.00	-25 %	1	\$83.25
15	FRONT DOOR WEATHERSTR IP LH Customized			\$0.00	\$146.00	-25 %	1	\$109.50
16	FRONT DOOR FRAME SEAL Customized			\$0.00	\$92.70	-25 %	1	\$69.53
17	DOOR TRIM L H Customized			\$0.00	\$438.90	-25 %	1	\$329.17
								Total :\$4627.35

Materials

#	Description	OE Number	Part Type	Unit Price	Cost	Mark up/Disc	Qty	Sum
01	ERP BRACKET <div>Customized</div>			\$0.00	\$26.00	0 %	1.0	\$26.00
02	ROV STICKER <div>Customized</div>			\$0.00	\$20.00	0 %	1.0	\$20.00
								Total :\$46.00

Labors

Replace / RnR

#	Description	Labor Code	Type	Labor Hour	Unit Price	Mark up/Disc	Sum
01	REPLACE F RONT WIND SCREEN <div>Customized</div>		RnR	0.00	\$120.00	0 %	\$120.00
02	REPLACE F RONT DOOR LH, HEADLAMP LH, A PILLAR AND REPAIR OTHER AFFECTED AREA <div>Customized</div>		RnR	0.00	\$750.00	0 %	\$750.00
							Total :\$870.00

Paint

#	Description	Labor Code	degree	Labor Hour	Unit Price	Mark up/Disc	Sum
01	FRONT BUMPER, CORNER PANEL LH , A PILLAR AND FRONT DOOR		Full spray	0.00	\$700.00	0 %	\$700.00

1/5/23, 12:39 PM

Estimate Preview Estimated-DE Assessor

#	Description	Labor Code	degree	Labor Hour	Unit Price	Mark up/Disc	Sum
	LH						
	<div>Customized</div>						
							Total :\$700.00

Remarks 2 remarks

2023-01-05 12:33 Assessor Supervisor-Insurlogic 1 6584981566

FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$5,000 WITH 7 DAYS

2022-11-25 08:25 Assessor Supervisor-Insurlogic 1 6584981566

Pre Review done base on survey information provided
Take note that this review is done before finalization, a final review on repair
cost to be concluded after repair.

Pre Review By : Insurlogic
Amount : \$7654.48
Check: \$180.00
Total: \$7654.48
Lump Sum: \$6100.00 (Before check item)
Repair Duration: 7 days