

AS: S. REC: 3Y: T&M

REF:

CS/111220/1739/7043

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

DD/TP/VS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: tkn

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

457K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Mr Koe

Veh No: _____

GBF 5380P

Yr Regn: _____

2016 / Dec

Type: M.Car / M.Cycle / Bus / Van / Long / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Toyota Dyna

C.O. 2982

Colour _____

White

A/C: Insured / Std / NI / NA

Sp. Reading _____

65321

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

JTFAT 35920 K 206542

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Mil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

6

mm

Rear

R/Bal. _____

0/6

mm

L/Bal. _____

6

mm

L/Bal. _____

6/6

mm

D.O.A. _____

D.O.I. _____

23/11/22

Survey held at _____

Sin Sheng

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front MS

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Form: _____

Lum Sum / L.B. / P

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____

: Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

SIN SHENG AUTO WORKSHOP PTE LTD

REGISTRATION NO.: 202019500G

NO. 5 TUAS AVE 3 SINGAPORE 639405

TEL: (+65) 6416 1996 FAX: (+65) 6863 1944 EMAIL: ENQUIRY@SINSHENG.COM.SG

India International Insurance Pte Ltd

64 Cecil Street

#04/#05 IOB Building

Singapore 049 711

Attn: Motor Claims Department

Estimate No : ES2022/0079

Date : 21/11/2022

Vehicle No : GBF 5380P

Make/Model : TOYOTA DYNA 150 MANUAL

Date of Accident : 18/11/2022

Prepared By : Hoe

S/N	Description	Qty	Unit Amount (\$\$)	Amount (\$\$)
<u>Parts (List)</u>				
1	Front Windscreen	1	980.30	980.30 <i>cur</i>
2	Front Windscreen Weatherstrip	1	391.50	391.50 <i>cut</i>
3	A-pillar outer	1	433.90	433.90 <i>bt</i>
4	A-pillar inner	1	371.20	371.20 <i>Rx</i>
5	A-pillar inner trim	1	216.70	216.70 <i>Rx</i>
6	Mirror Stay c/w Side Mirror	1	737.00	737.00 <i>bno</i>
7	Round Mirror	1	145.50	145.50 <i>miz</i>
8	Centre Panel <i>Black moulding LH</i>	1	350.80	350.80 <i>cut</i>
9	Mirror Stay Cap	1	49.50	49.50 <i>miz</i>
10	Mirror Stay Cover	1	198.50	198.50 <i>miz</i>
11	Black Trim, LH	1	113.50	113.50 <i>miz</i>
12	Headlamp, LH	1	979.00	979.00 <i>cur</i>
13	Front Door, LH	1	1,902.20	1,902.20 <i>bt</i>
14	Front Door Qtr Trim, LH	1	28.60	28.60 <i>de</i>
15	Window Glass, LH Door	1	733.70	733.70 <i>bno</i>
16	Window Channel	1	258.40	258.40 <i>de</i>
17	Front Door Weatherstrip, LH	1	217.30	217.30 <i>fr</i>
18	Front Door Frame Seal	1	92.70	92.70 <i>cut</i>
19	Front Bumper	1	658.50	658.50 <i>Rx</i>
20	ERP Bracket	1	80.00	80.00 <i>net</i>
21	Dashboard	1	1,595.80	1,595.80 <i>Rx</i>
22	Door Trim, LH	1	438.90	438.90 <i>de</i>
				10,973.50
			Less: 25%	(2,743.38)
			Price after disc	8,230.13
1	ROV Sticker	1	20.00	20.00 <i>net</i>
			Parts total	8,250.13

Parts (Nett)

SIN SHENG AUTO WORKSHOP PTE LTD
REGISTRATION NO.: 202019500G
NO. 5 TUAS AVE 3 SINGAPORE 639405
TEL: (+65) 6416 1996 FAX: (+65) 6863 1944 EMAIL: ENQUIRY@SINSHENG.COM.SG

Labour charges

To dismantle/replace front windscreen	120.00	✓
To dismantle/replace dashboard	250.00	180? p.m/po.
To panel beat/repair LH body	950.00	750
To dismantle/replace abovementioned parts	950.00	700
To spray painting on repaired areas		
Labour total	2,270.00	

TOTAL 10,520.13

Hoe

Quek Beng Hoe

Tanfilm 97445749 / 62563561
not authorize 23/11/22 @ 520 pm
Exp: to be advise
4/5 Resury after repair
tanfilm@Tuhant.com
27 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: