

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)

#02-146, Singapore 608586

Tel: 64688834 Fax: 67228585

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2211-627-TG

DATE : 21-Nov-2022

POLICY NO. :

VEHICLE REG. NO. : SMG8264L

VEHICLE MAKE : MAZDA6 SEDAN 2.0 AT STANDARD 2WD
JM6GL1072K0311105

TO Motor Claim Department

QBE INSURANCE (SINGAPORE) PTE LTD

1 Wallich St, #35-01 Guoco Tower, Singapore 078881

Tel: +65 6224 6633

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
<u>SPARE PARTS</u>				
1	Rear Bumper	1	\$ 1,185.00	\$ 1,185.00
2	Rear Bumper Side Retainer LH/RH	2	\$ 62.50	\$ 125.00
3	Rear Bumper Reinforcement	1	\$ 525.80	\$ 525.80
4	Rear Bumper Towing Cover LH/RH	2	\$ 66.00	\$ 132.00
5	Rear Boot	1	\$ 970.50	\$ 970.50
6	Rear Boot Emblem	1	\$ 75.80	\$ 75.80
7	Rear Boot Lock	1	\$ 235.10	\$ 235.10
8	Rear Boot Weatherstrip	1	\$ 185.20	\$ 185.20
9	Rear Boot Logo (Mazda)	1	\$ 54.70	\$ 54.70
10	Rear Boot Logo (6)	1	\$ 39.50	\$ 39.50
11	Rear Boot Logo (Skyactive)	1	\$ 106.80	\$ 106.80
12	Rear Boot Hinge LH/RH	2	\$ 310.50	\$ 621.00
13	Rear End Panel	1	\$ 725.80	\$ 725.80
14	Rear End Panel Top Garnish	1	\$ 358.30	\$ 358.30
Parts Less 20%				\$ (1,068.10)
Total Spare Parts				\$ 4,272.40
<u>SPECIAL NETT</u>				
15	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
16	Rear Reverse Sensor	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 250.00
<u>LABOUR</u>				
17	Remove, Refit and Repair Affected Accident Parts	1	\$ 800.00	\$ 800.00
18	Spray Paint (Rear Bumper, Rear Boot, Rear End Panel)	1	\$ 800.00	\$ 800.00
19	Remove & Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
20	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
21	Check and rectify electrical wiring	1	\$ 50.00	\$ 50.00
Total Labour				\$ 1,830.00
Amount Before Excess				\$ 6,352.40
Add GST @ 7%				444.67
Total Amount Payable				\$ 6,797.07

Estimate prepared by: JAMES TAN

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.