

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDP 1970L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOTLID (CONSISTENT)	BUCKLED	781.10	781.10
1	REAR BOOTLID 'ALTIS' EMBLEM (CONSISTENT)	NECESSARY	54.10	54.10
1	REAR BOOTLID 'COROLLA' EMBLEM (CONSISTENT)	NECESSARY	50.20	50.20
1	REAR BOOTLID 'LOGO' EMBLEM (CONSISTENT)	NECESSARY	58.50	58.50
2	REAR BOOTLID HINGES L/R @\$79.60(CONSISTENT)	NOT NECESSARY	159.20	-
1	REAR BOOTLID INNER TRIM GARNISH (CONSISTENT)	NOT NECESSARY	181.85	-
1	REAR BOOTLID LOCK STRIKER (CONSISTENT)	NOT NECESSARY	85.00	-
1	REAR BOOTLID LOCK STRIKER COVER (CONSISTENT)	NOT NECESSARY	42.00	-
1	REAR BOOTLID MECHANISM LOCK (CONSISTENT)	DAMAGED	379.20	379.20
2	REAR BOOTLID REFLECTOR GASKET SEAL L/R @\$43.10 (CONSISTENT)	NOT NECESSARY	86.20	-
2	REAR BOOTLID REFLECTOR L/R @\$374.45 (CONSISTENT)	NOT NECESSARY	748.90	-
4	REAR BOOTLID RUBBER GUIDE STOPPER @\$6.80 (CONSISTENT)	NOT NECESSARY	27.20	-
1	REAR BOOTLID WEATHERSTRIP (CONSISTENT)	CUT	271.45	271.45
1	REAR BUMPER (CONSISTENT)	DEFORMED	556.40	556.40
2	REAR BUMPER END SEAL COVER L/R @\$55.10 (CONSISTENT)	NOT NECESSARY	110.20	-
2	REAR BUMPER REFLECTOR L/R @\$59.80(CONSISTENT)	CRACKED	119.60	119.60
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	DENTED	398.70	398.70
2	REAR BUMPER REINFORCEMENT BRACKET L/R @\$68.20 (CONSISTENT)	DENTED	136.40	136.40
2	REAR BUMPER REVERSE SENSOR @\$198.00 (CONSISTENT)	DAMAGED	396.00	396.00
2	REAR BUMPER REVERSE SENSOR HOLDER @\$43.00 (CONSISTENT)	NECESSARY	86.00	86.00
2	REAR BUMPER SIDE RETAINER L/R @\$109.30 (CONSISTENT)	NOT NECESSARY	218.60	-
1	REAR END PANEL (CONSISTENT)	DENTED	670.00	670.00
1	REAR END PANEL INNER TOP GARNISH (CONSISTENT)	DEFORMED	241.90	241.90
1	REAR END PANEL KEYLESS SENSOR (CONSISTENT)	DAMAGED	168.00	168.00
2	REAR FENDER INNER TRIM L/R @\$338.00(CONSISTENT)	NOT NECESSARY	676.00	-
1	REAR FLOOR PANEL TOP BOARD COVER(CONSISTENT)	DEFORMED	267.00	267.00

Report Ref No. CC4/ASM22011751/Apa3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By	Our Adjusted
	·		Workshop (\$))	(\$)
1	REAR SPARE TYRE PANEL FASTENER LOCK (CONSISTENT)	BENT	28.40	28.40
2	REAR TAILLAMP INNER BLACK RUBBER GASKET @ \$25.50(CONSISTENT)	NECESSARY	51.00	51.00
2	REAR TAILLAMP L/R @\$391.90(CONSISTENT)	CRACKED	783.80	783.80
2	REAR TAILLAMP LOWER BRACKET L/R @\$88.70 (CONSISTENT)	CRACKED	177.40	177.40
	LESS 25% DISCOUNT		-2,002.58	-1,418.79
			6,007.72	4,256.36
	SPECIAL NETT ITEMS			
1	SET REAR BOOTLID CHROME MOULDING CLIPS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	SET BOOTLID INNER TRIM GARNISH CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	50.00	30.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	10.00
2	SET REAR FENDER INNER TRIM CLIPS L/R @\$40.00(SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR NUMBER PLATE (SN)(CONSISTENT)	NOT NECESSARY	25.00	-
1	REAR NUMBER PLATE HOLDER (SN)(CONSISTENT)	NOT NECESSARY	50.00	-
			305.00	40.00
	<u>LABOUR</u>			
	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR .		80.00	60.00
	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR .		80.00	80.00
	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR).		100.00	60.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID ,REAR END PANEL ,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER .		1,300.00	1,000.00
	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS,REPAIR RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT .		1,000.00	800.00

Report Ref No. CC4/ASM22011751/Apa3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		100.00	60.00
			2,660.00	2,060.00
	GRAND TOTAL		8,972.72	6,356.36

RECOMMENDED COST OF LUMP SUM REPAIRS		5,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM22011751/Apa3q2



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.