

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 4206B

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-----------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT WINDSCREEN (CONSISTENT) | BROKEN | 876.20 | 876.20 |
| 1 | FRONT WINDSCREEN MOULDING (CONSISTENT) | NECESSARY | 58.40 | 58.40 |
| 1 | FRONT BONNET (CONSISTENT) | BUCKLED | 826.30 | 826.30 |
| 2 | FRONT BONNET HINGE @\$85.20(CONSISTENT) | BENT | 170.40 | 170.40 |
| 1 | FRONT BONNET LOCK (CONSISTENT) | TWISTED | 174.50 | 174.50 |
| 1 | FRONT BONNET CABLE (CONSISTENT) | JAMMED | 90.40 | 90.40 |
| 1 | FRONT BONNET LOCK CATCH (CONSISTENT) | NOT NECESSARY | 98.20 | - |
| 1 | FRONT BONNET INSULATOR(CONSISTENT) | DISTORTED | 176.20 | 176.20 |
| 14 | FRONT BONNET INSULATOR CLIP @\$5.50(CONSISTENT) | NECESSARY | 77.00 | 77.00 |
| 2 | FRONT BONNET SEAL @\$52.20(CONSISTENT) | NOT NECESSARY | 104.40 | - |
| 2 | FRONT FENDER @\$457.50(CONSISTENT) | BUCKLED | 915.00 | 915.00 |
| 2 | FRONT FENDER DUST COVER @\$154.20(CONSISTENT) | TORN / DEFORMED | 308.40 | 308.40 |
| 2 | FRONT HEADLAMP @\$678.20(CONSISTENT) | BROKEN | 1,356.40 | 1,356.40 |
| 2 | FRONT HEADLAMP TOP PANEL @\$65.60(CONSISTENT) | BENT | 131.20 | 131.20 |
| 1 | FRONT SUPPORT PANEL (CONSISTENT) | DISTORTED | 908.70 | 908.70 |
| 1 | FRONT SUPPORT CENTRE BRACKET (CONSISTENT) | BENT | 48.20 | 48.20 |
| 1 | FRONT GRILLE (CONSISTENT) | BROKEN | 415.70 | 415.70 |
| 1 | FRONT GRILLE EMBLEM (CONSISTENT) | CRACKED | 89.20 | 89.20 |
| 1 | FRONT GRILLE GARNISH (CONSISTENT) | CRACKED | 298.40 | 298.40 |
| 1 | FRONT BUMPER (CONSISTENT) | DISTORTED | 890.00 | 890.00 |
| 1 | FRONT BUMPER REINFORCEMENT (CONSISTENT) | BENT | 546.30 | 546.30 |
| 2 | FRONT BUMPER SIDE RETAINER @\$48.20(CONSISTENT) | BENT | 96.40 | 96.40 |
| 1 | FRONT BUMPER TOWING COVER (CONSISTENT) | NOT NECESSARY | 38.40 | - |
| 2 | FRONT BUMPER SIDE GRILLE @\$128.90(CONSISTENT) | TWISTED | 257.80 | 257.80 |
| 1 | FRONT BUMPER CENTRE LOWER GRILLE (CONSISTENT) | TWISTED | 226.50 | 226.50 |
| 1 | FRONT NUMBER PLATE SUPPORT (CONSISTENT) | TORN | 58.20 | 58.20 |
| 1 | FRONT AIR CLEANER BOX ASSEMBLY(CONSISTENT) | CRACKED | 367.40 | 367.40 |
| 1 | FRONT AIR CLEANER AIR DUCT (CONSISTENT) | CRACKED | 106.20 | 106.20 |
| 1 | FRONT AIR CLEANER AIR DUCT COVER (CONSISTENT) | CRACKED | 48.60 | 48.60 |
| 1 | FRONT RADIATOR (CONSISTENT) | DISTORTED | 689.20 | 689.20 |
| 1 | FRONT RADIATOR TOP HOSE (CONSISTENT) | NOT NECESSARY | 85.20 | - |

Report Ref No. CC4/ASM22011752/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|-------------------|
| 1 | FRONT RADIATOR FAN COWLING (CONSISTENT) | CRACKED | 346.20 | 346.20 |
| 1 | FRONT RADIATOR FAN BLADE WITH MOTOR (CONSISTENT) | JAMMED | 504.20 | 504.20 |
| 2 | FRONT RADIATOR BRACKET @\$36.40(CONSISTENT) | TWISTED | 72.80 | 72.80 |
| 1 | FRONT TURBO CHARGE PIPE (CONSISTENT) | BENT | 224.20 | 224.20 |
| 1 | FRONT TURBO CHARGE JOINT (CONSISTENT) | NOT NECESSARY | 104.60 | - |
| 1 | FRONT TURBO CHARGE HEAT COVER (CONSISTENT) | BENT | 89.20 | 89.20 |
| 1 | FRONT RADIATOR TOP COVER (CONSISTENT) | BENT | 32.20 | 32.20 |
| 1 | FRONT TURBO CHARGE CENTRE COVER (CONSISTENT) | NOT NECESSARY | 684.20 | - |
| 1 | FRONT AIR CON CONDENSER (CONSISTENT) | DISTORTED | 865.40 | 865.40 |
| 1 | FRONT AIR CON FAN BLADE WITH MOTOR (CONSISTENT) | CRACKED / JAMMED | 326.40 | 326.40 |
| 1 | FRONT AIR CON DISCHARGE HOSE (CONSISTENT) | BENT | 326.40 | 326.40 |
| 1 | FRONT AIR CON LIQUID HOSE (CONSISTENT) | BENT | 320.20 | 320.20 |
| 1 | FRON FUEL CHARCOAL BOX (CONSISTENT) | CRACKED | 267.20 | 267.20 |
| 1 | FRON FUEL CHARCOAL BOX BRACKET (CONSISTENT) | NOT NECESSARY | 65.20 | - |
| 1 | FRONT FUEL CHARCOAL BOX HOSE JOINT BRACKET (CONSISTENT) | NOT NECESSARY | 60.40 | - |
| 1 | FRONT ENGINE MOUNTING -RH (CONSISTENT) | TORN | 328.40 | 328.40 |
| 1 | FRONT DASH BOARD (CONSISTENT) | TORN | 1,246.20 | 1,246.20 |
| 1 | FRONT STEERING WHEEL AIR BAG(CONSISTENT) | ACTIVATED | 856.20 | 856.20 |
| 1 | FRONT AIR BAG -LH (CONSISTENT) | ACTIVATED | 1,267.20 | 1,267.20 |
| 2 | FRONT SEAT BELT @\$687.20(CONSISTENT) | ACTIVATED | 1,374.40 | 1,374.40 |
| 1 | FRONT AIR BAG ECU(CONSISTENT) | ACTIVATED | 750.00 | 750.00 |
| 1 | FRONT ROOM MIRROR (CONSISTENT) | CRACKED | 268.40 | 268.40 |
| 1 | FRONT DOOR -RH (CONSISTENT) | TO REPAIR SEE LABOUR | 984.20 | - |
| 1 | REAR END PANEL (CONSISTENT) | DENTED | 962.50 | 962.50 |
| 1 | REAR BUMPER (CONSISTENT) | DISTORTED | 1,123.80 | 1,123.80 |
| 1 | REAR BUMPER INNER TOP BEAM (CONSISTENT) | CRACKED | 184.20 | 184.20 |
| 1 | REAR BUMPER REINFORCEMENT (CONSISTENT) | TO REPAIR SEE LABOUR | 640.00 | - |
| 1 | REAR BUMPER LOWER SPOILER (CONSISTENT) | DISTORTED | 640.20 | 640.20 |
| 1 | REAR BUMPER UNDER COVER -LH (CONSISTENT) | TWISTED | 246.20 | 246.20 |
| 1 | REAR BUMPER TOWING COVER (CONSISTENT) | NOT NECESSARY | 48.40 | - |

Report Ref No. CC4/ASM22011752/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
| 3 | REAR BUMPER CLIP @\$5.50(CONSISTENT) | NECESSARY | 16.50 | 16.50 |
| 1 | REAR EXHAUST SILENCER (CONSISTENT) | TO REPAIR SEE LABOUR | 986.40 | - |
| 1 | REAR EXHAUST RUBBER (CONSISTENT) | NOT NECESSARY | 48.20 | - |
| 1 | REAR EXHAUST RUBBER BRACKET (CONSISTENT) | NOT NECESSARY | 56.40 | - |
| | LESS 10% DISCOUNT | | -2,685.00 | -2,284.58 |
| | | | 24,165.00 | 20,561.22 |
| | SPECIAL NETT ITEMS | | | |
| 1 | FRONT IU UNIT (SN)(CONSISTENT) | NECESSARY | 15.00 | 15.00 |
| 1 | FRONT HEADLAMP GARNISH (ACCESSORY) (SN) (CONSISTENT) | NOT NECESSARY | 80.00 | - |
| 1 | FRONT NUMBER PLATE (SN)(CONSISTENT) | BENT | 50.00 | 40.00 |
| 1 | REAR BUMPER SENSOR (SN)(CONSISTENT) | SHORTED | 300.00 | 200.00 |
| | | | 445.00 | 255.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT DOOR -RH ,REAR BUMPER REINFORCEMENT AND REAR EXHAUST SILENCER . | | 2,800.00 | 2,000.00 |
| | TO REMOVE & REPLACE FRONT WINDSCREEN. | | 160.00 | 120.00 |
| | TO REMOVE & REPLACE AIR CON CONDENSER AND CHARGE GAS . | | 160.00 | 100.00 |
| | TO CHECK WIRING AND DIAGNOSTICS CHECK. | | 280.00 | 100.00 |
| | TO REMOVE & REPLACE DASH BOARD AND AIR BAG. | | 520.00 | 300.00 |
| | TO REMOVE & REPLACE REAR BUMPER SENSOR . | | 80.00 | 50.00 |
| | TO REMOVE & REPLACE ENGINE MOUNTING . | | 80.00 | 50.00 |
| | TO SPRAY RUST PROOFING. | | 80.00 | 80.00 |
| | TO SPRAY PAINTING. | | 1,800.00 | 1,800.00 |
| | | | 5,960.00 | 4,600.00 |
| | GRAND TOTAL | | 30,570.00 | 25,416.22 |



Page No.:4 of 4

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 19,000.00 |
|--------------------------------------|--|-----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | · |

Report Ref No. CC4/ASM22011752/Upa3q2

CHUA KANG SENG
Licensed Appraiser