

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011755/AVP3Q2**Date:** 22/12/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00157152201

Claimant Vehicle No : SJA3420C **Insured Vehicle No :** SJR9346E

Date of Loss: 19/11/2022 Nature of Claim: TP Claim No: SNM22D208340/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJA3420C**

Make & Model: TOYOTA ESTIMA, 2.4 (A) Engine No: 2AZF094799

Reg. Date: 04/12/2007 (Man. Year: 2007) Chassis No: ACR500054804

Colour: Beige Odometer: 243225 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18

Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm

Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,883.50	5,562.25	3,321.25	37.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,730.00	1,980.00	750.00	27.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,613.50	7,542.25	4,071.25	35.06
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	11,613.50	6,000.00	5,613.50	48.34
+ GST 7.00/7.00% (S\$)	812.95	420.00	392.95	48.34
Nett Amount (S\$)	12,426.45	6,420.00	6,006.45	48.34

INSPECTION

Date of Assignment: 22/11/2022

Date Inspected: 22/11/2022 Inspected At: 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT
AUTOHUB SINGAPORE
Repairer : TWINCAR AUTOMOTIVE PTE LTD

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2022)
Parts: M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJA3420C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	546.00 FL	*546.00 FL
2	2		*REAR BUMPER REFLECTOR L/R	Cracked	112.00 FL	*112.00 FL
3	2		*REAR BUMPER SIDE CORNER RETAINER L/R	Necessary	90.00 FL	*90.00 FL
4	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	174.00 FL	*- FL
5	2		*REAR BUMPER TOW HOOK COVER L/R	Not Necessary	50.00 FL	*- FL
6	1		*REAR END PANEL	Dented	520.00 FL	*520.00 FL
7	1		*REAR END PANEL ANTENNA SENSOR	Damaged	107.00 FL	*107.00 FL
8	1		*REAR END PANEL INNER LOWER GARNISH	Deformed	175.00 FL	*175.00 FL
9	1		*REAR END PANEL INNER TOP GARNISH	Deformed	225.00 FL	*225.00 FL
10	1		*REAR FENDER INNER TRIM BARD L/R	O/S Deformed	1,490.00 FL	*745.00 FL
11	1		*REAR FLOOR HORIZONTAL PANEL	Repair	290.00 FL	*- FL
12	1		*REAR FLOOR PANEL	Repair	780.00 FL	*- FL
13	1		*REAR FLOOR PANEL TOP BOARD COVER	Deformed	780.00 FL	*690.00 FL
14	1		*REAR FLOOR PANEL TRIM LINER CARPET	Not Necessary	680.00 FL	*- FL
15	1		*REAR TAILGATE	Deformed	1,855.00 FL	*1,681.00 FL
16	1		*REAR TAILGATE ESTIMA EMBLEM	Necessary	57.00 FL	*57.00 FL
17	1		*REAR TAILGATE G EMBLEM	Necessary	57.00 FL	*57.00 FL
18	1		*REAR TAILGATE LOGO EMBLEM	Necessary	61.00 FL	*61.00 FL
19	2		*REAR TAILGATE HINGES L/R	Not Necessary	134.00 FL	*- FL
20	1		*REAR TAILGATE INNER PULL HANDLE	Not Necessary	55.00 FL	*- FL
21	2		*REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R	Not Necessary	38.00 FL	*- FL
22	1		*REAR TAILGATE INNER TRIM BOARD	Deformed	467.00 FL	*467.00 FL
23	1		*REAR TAILGATE LOCK STRIKER	Not Necessary	25.00 FL	*- FL
24	1		*REAR TAILGATE MECHANISM LOCK	Damaged	391.00 FL	*391.00 FL
25	1		*REAR TAILGATE MECHANISM LOCK GARNISH	Deformed	38.00 FL	*38.00 FL
26	1		*REAR TAILGATE WEATHERSTRIP	Cut	356.00 FL	*356.00 FL
27	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	205.00 FL	*205.00 FL
28	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
29	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
30	1		*REAR BUMPER TOP CHROME PLATE	Necessary	280.00 FS	*200.00 FS
31	1		*SET REAR END PANEL INNER LOWER GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
32	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
33	2		*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Necessary	100.00 FS	*30.00 FS
34	1		*REAR FLOOR PANEL INSULATOR MAT	Not Necessary	300.00 FS	*- FS
35	1		*SET REAR FLOOR PANEL TRIM LINER CARPET CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
37	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
38	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
39	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
40	1		*REAR TAILGATE STICKER	Necessary	150.00 FS	*80.00 FS
41	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,323.00	7,193.00
- List Item Discount on L Items 25.00/25.00% (S\$)	2,439.50	1,630.75
Total Parts (S\$)	8,883.50	5,562.25

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	----------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.						
---	--	--	--	--	--	--

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO REMOVE ,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
3	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	100.00	60.00
4	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	800.00
5	TO PROVIDE LABOUR WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
7	TO REMOVE ,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	60.00
Gross Labour Cost (S\$)			2,730.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >