

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011756/SVP3E2**Date:** 10/01/2023REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00073372204

**Claimant Vehicle  
No :** GBB4838P**Insured Vehicle  
No :** GBH5000B

Date of Loss: 16/11/2022

Nature of Claim: TP

Claim  
No: SNM22D208382/C02/LEWLCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBB4838P**

Make &amp; Model: TOYOTA HIACE, 3.0 D (M)

Engine No: 1KD1911614

Reg. Date: 13/04/2009 (Man. Year: 2009)

Chassis No: JTFHT02P600041678

Colour: Silver

Odometer: 227553 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 18,950.75         | 2,154.50          | 16,796.25         | 88.63         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 6,500.00          | 1,430.00          | 5,070.00          | 78.00         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>25,450.75</b>  | <b>3,584.50</b>   | <b>21,866.25</b>  | <b>85.92</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>2,850.00</b>   |                   |               |
| <b>(S\$)</b>                             | 25,450.75         | 2,850.00          | 22,600.75         | 88.80         |
| <b>+ GST 8.00/8.00% (S\$)</b>            | 2,036.06          | 228.00            | 1,808.06          | 88.80         |
| <b>Nett Amount (S\$)</b>                 | <b>27,486.81</b>  | <b>3,078.00</b>   | <b>24,408.81</b>  | <b>88.80</b>  |

INSPECTION

Date of Assignment: 22/11/2022

Date Inspected: 24/11/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)  
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit  
Singapore 415875

Estimated Period of Repair: 5.0 days

**Adjuster:** S Mohamed Irfan Bin Mohamed Iqbal**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                          |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------|
| <b>Part Source:</b>  | (Last Synchronised: 10 Jan 2023)                                                                                                                                             |                                                          |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | TOYOTA HIACE 3.0 D (M) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                        |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GBB4838P)                                                                                                                                    |                                                          |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                          |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                          |

### Recommended Parts

| No. | Qty | Part No. | Particulars                                 | Condition     | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER                                | Cracked       | 491.60 FL   | *491.60 FL   |
| 2   | 4   |          | *REAR BUMPER LOWER BRACKET                  | Not Necessary | 112.80 FL   | *- FL        |
| 3   | 1   |          | *REAR BUMPER SIDE RETAINER RH               | Not Necessary | 25.30 FL    | *- FL        |
| 4   | 1   |          | *REAR BUMPER SIDE RETAINER LH               | Cracked       | 25.30 FL    | *25.30 FL    |
| 5   | 1   |          | *REAR END PANEL INNER                       | Not Necessary | 1,198.20 FL | *- FL        |
| 6   | 1   |          | *REAR END PANEL OUTER                       | Not Necessary | 371.40 FL   | *- FL        |
| 7   | 1   |          | *REAR END PANEL TOP GARNISH                 | Not Necessary | 165.00 FL   | *- FL        |
| 8   | 1   |          | *REAR END PANEL SIDE LH                     | Scratched     | 362.10 FL   | *362.10 FL   |
| 9   | 1   |          | *REAR FLOOR PANEL MAT                       | Not Necessary | 796.00 FL   | *- FL        |
| 10  | 1   |          | *REAR FLOOR PANEL                           | Not Necessary | 1,960.00 FL | *- FL        |
| 11  | 1   |          | *REAR TAILGATE                              | Repair        | 2,337.90 FL | *- FL        |
| 12  | 1   |          | *REAR TAILGATE WINDSCREEN GLASS             | Not Necessary | 1,451.30 FL | *- FL        |
| 13  | 1   |          | *REAR TAILGATE EMBLEM                       | Necessary     | 72.20 FL    | *72.20 FL    |
| 14  | 1   |          | *REAR TAILGATE INNER CARDBOARD              | Not Necessary | 196.00 FL   | *- FL        |
| 15  | 1   |          | *REAR TAILGATE INNER CENTER LOCKING CONTROL | Not Necessary | 264.00 FL   | *- FL        |
| 16  | 1   |          | *REAR TAILGATE MECHANISM LOCK               | Not Necessary | 299.60 FL   | *- FL        |
| 17  | 1   |          | *REAR TAILGATE MECHANISM LOCK STRIKER       | Not Necessary | 55.00 FL    | *- FL        |
| 18  | 1   |          | *REAR TAILGATE OUTER GARNISH                | Not Necessary | 298.00 FL   | *- FL        |
| 19  | 2   |          | *REAR TAILGATE RUBBER GUIDE STOPPER         | Not Necessary | 83.60 FL    | *- FL        |
| 20  | 2   |          | *REAR TAILGATE RUBBER CAP                   | Not Necessary | 38.60 FL    | *- FL        |
| 21  | 1   |          | *REAR TAILGATE WEATHERSTRIP                 | Not Necessary | 442.00 FL   | *- FL        |
| 22  | 1   |          | *REAR TAILGATE WEATHERSTRIP PROTECTOR       | Not Necessary | 217.00 FL   | *- FL        |
| 23  | 1   |          | *REAR TAILLAMP ASSEMBLY RH                  | Not Necessary | 354.80 FL   | *- FL        |
| 24  | 1   |          | *REAR TAILLAMP ASSEMBLY LH                  | Cracked       | 354.80 FL   | *354.80 FL   |
| 25  | 1   |          | *REAR TAILLAMP LOWER GARNISH RH             | Not Necessary | 170.00 FL   | *- FL        |
| 26  | 1   |          | *REAR TAILLAMP LOWER GARNISH LH             | Not Necessary | 170.00 FL   | *- FL        |
| 27  | 1   |          | *REAR TAILLAMP LOWER GARNISH RETAINER RH    | Not Necessary | 60.00 FL    | *- FL        |
| 28  | 1   |          | *REAR TAILLAMP LOWER GARNISH RETAINER LH    | Cracked       | 60.00 FL    | *60.00 FL    |
| 29  | 1   |          | *REAR TAILLAMP PANEL LH                     | Not Necessary | 300.00 FL   | *- FL        |
| 30  | 1   |          | *REAR SIDE PANEL OUTER LH                   | Buckled       | 2,194.90 FL | *1,360.00 FL |
| 31  | 1   |          | *REAR SIDE PANEL INNER LH                   | Not Necessary | 1,070.20 FL | *- FL        |
| 32  | 1   |          | *REAR SIDE LOWER CORNER INNER PANEL LH      | Repair        | 187.50 FL   | *- FL        |
| 33  | 1   |          | *REAR SIDE PANEL INNER TRIM BOARD LH        | Not Necessary | 198.40 FL   | *- FL        |
| 34  | 1   |          | *REAR SIDE INNER LOWER PANEL LH             | Not Necessary | 1,140.40 FL | *- FL        |
| 35  | 1   |          | *REAR SIDE PANEL AIR VENT LH                | Not Necessary | 86.30 FL    | *- FL        |
| 36  | 1   |          | *REAR SIDE RAILWAY END GARNISH LH           | Not Necessary | 47.30 FL    | *- FL        |
| 37  | 1   |          | *REAR SIDE RAILWAY LH                       | Not Necessary | 864.10 FL   | *- FL        |
| 38  | 1   |          | *REAR WHEEL CAP LH                          | Not Necessary | 179.30 FL   | *- FL        |
| 39  | 1   |          | *REAR WHEEL RIM LH                          | Not Necessary | 260.00 FL   | *- FL        |
| 40  | 1   |          | *REAR WHEEL HUB BEARING LH                  | Not Necessary | 187.00 FL   | *- FL        |
| 41  | 1   |          | *REAR WHEEL HUB LH                          | Not Necessary | 390.00 FL   | *- FL        |
| 42  | 1   |          | *REAR SHOCK ABSORBER LH                     | Not Necessary | 439.00 FL   | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                 | Condition     | Repairer's  | Amount    |
|-----|-----|----------|---------------------------------------------|---------------|-------------|-----------|
| 43  | 1   |          | *REAR AXLE                                  | Not Necessary | 1,984.10 FL | *- FL     |
| 44  | 1   |          | *REAR NUMBER PLATE                          | Not Necessary | 50.00 FS    | *- FS     |
| 45  | 1   |          | *SET REAR BUMPER CLIPS                      | Necessary     | 50.00 FS    | *50.00 FS |
| 46  | 1   |          | *SET REAR TAILLAMP CLIPS                    | Not Necessary | 50.00 FS    | *- FS     |
| 47  | 1   |          | *SET TAILLAMP LOWER GARNISH CLIPS           | Not Necessary | 50.00 FS    | *- FS     |
| 48  | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS       | Not Necessary | 50.00 FS    | *- FS     |
| 49  | 1   |          | *SET REAR TAILGATE OUTER GARNISH CLIPS      | Not Necessary | 30.00 FS    | *- FS     |
| 50  | 1   |          | *SET REAR TAILGATE INNER BOARD CLIPS        | Not Necessary | 50.00 FS    | *- FS     |
| 51  | 1   |          | *REAR TAILGATE WINDSCREEN GLASS SEALANT     | Not Necessary | 150.00 FS   | *- FS     |
| 52  | 1   |          | *REAR TAILGATE 70KM/H STICKER               | Necessary     | 50.00 FS    | *30.00 FS |
| 53  | 1   |          | *REAR TAILGATE 8 PAX STICKER                | Necessary     | 50.00 FS    | *30.00 FS |
| 54  | 1   |          | *REAR TAILGATE SEALANT                      | Not Necessary | 150.00 FS   | *- FS     |
| 55  | 1   |          | *REAR END PANEL SEALANT                     | Not Necessary | 150.00 FS   | *- FS     |
| 56  | 1   |          | *REAR SIDE PANEL OUTER SEALANT              | Not Necessary | 150.00 FS   | *- FS     |
| 57  | 1   |          | *REAR SIDE PANEL INNER SEALANT              | Not Necessary | 150.00 FS   | *- FS     |
| 58  | 1   |          | *REAR SIDE LOWER PANEL SEALANT              | Not Necessary | 150.00 FS   | *- FS     |
| 59  | 1   |          | *SET REAR SIDE PANEL INNER TRIM BOARD CLIPS | Not Necessary | 50.00 FS    | *- FS     |
| 60  | 1   |          | *REAR TYRE LH                               | Not Necessary | 350.00 FS   | *- FS     |
| 61  | 1   |          | *SET REAR BUMPER REVERSE SENSOR             | Not Necessary | 250.00 FS   | *- FS     |
| 62  | 1   |          | *REAR TAILGATE REVERSE CAMERA               | Not Necessary | 500.00 FS   | *- FS     |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>24,441.00</b> | <b>2,836.00</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 5,490.25         | 681.50          |
| <b>Total Parts (\$\$)</b>                                  | <b>18,950.75</b> | <b>2,154.50</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                              | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                                                                          |          |                 |                 |
| 1                              | TO PANEL BEAT, REMOVE & REFIX PARTS                                      | New      | 2,100.00        | 800.00          |
| 2                              | TO SPRAY PAINT AFFECTED AREAS                                            | New      | 1,800.00        | 600.00          |
| 3                              | WIRING & BULB CHECK                                                      | New      | 100.00          | 30.00           |
| 4                              | TO REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS                         | New      | 150.00          | 0.00            |
| 5                              | TO TRANSFER REAR TAILGATE MECHANISM                                      | New      | 150.00          | 0.00            |
| 6                              | TO REMOVE & REFIX REAR TAILGATE REVERSE CAMERA                           | New      | 150.00          | 0.00            |
| 7                              | TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR                             | New      | 120.00          | 0.00            |
| 8                              | TO REMOVE & REFIX REAR EXHAUST PIPE TO FACILITATE REPAIR                 | New      | 150.00          | 0.00            |
| 9                              | TO REMOVE & REFIX INTERIOR UPHOLSTRY TO FACILITATE REPAIRS               | New      | 200.00          | 0.00            |
| 10                             | TO REMOVE & REFIX REAR UNDERCARRIAGE                                     | New      | 550.00          | 0.00            |
| 11                             | TO REMOVE & REFIX REAR TYRE AND CONDUCT WHEEL BALANCING                  | New      | 150.00          | 0.00            |
| 12                             | TO CONDUCT FOUR WHEEL ALIGNMENT                                          | New      | 150.00          | 0.00            |
| 13                             | TO APPLY ANTI RUST ON AFFECTED PARTS                                     | New      | 150.00          | 0.00            |
| 14                             | TO CONDUCT WATER LEAK TEST                                               | New      | 100.00          | 0.00            |
| 15                             | TO SEND FOR DIAGNOSTIC AND RESET CONTROL UNIT. PROGRAMMING & CALIBRATION | New      | 480.00          | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |                                                                          |          | <b>6,500.00</b> | <b>1,430.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >