

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011764/SNP3Q2**Date:** 22/12/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00155152101

**Claimant Vehicle No :** GBB7372X **Insured Vehicle No :** XE2046U

Date of Loss: 19/11/2022 Nature of Claim: TP Claim No: SNM22D208347/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB7372X**

Make & Model: HYUNDAI H-1 STAREX, 2.5 D CRDi (A) Engine No: D4CB9560311

Reg. Date: 18/12/2009 (Man. Year: 2009) Chassis No: KMFWBX7JMAU193016

Colour: White Odometer: 269279 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16

Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm

Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,155.20	6,184.40	2,970.80	32.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,340.00	1,230.00	2,110.00	63.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,495.20</b>	<b>7,414.40</b>	<b>5,080.80</b>	<b>40.66</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,700.00</b>		
		<b>(S\$)</b>		
	12,495.20	5,700.00	6,795.20	54.38
<b>+ GST 7.00/7.00% (S\$)</b>	874.66	399.00	475.66	54.38
<b>Nett Amount (S\$)</b>	<b>13,369.86</b>	<b>6,099.00</b>	<b>7,270.86</b>	<b>54.38</b>

INSPECTION

Date of Assignment: 30/11/2022

Date Inspected: 23/11/2022 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)  
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit  
Singapore 415875

Estimated Period of Repair: 5.0 days

**Adjuster:** S Mohamed Irfan Bin Mohamed Iqbal**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 22 Dec 2022)	
<b>Parts:</b>	N/A	HYUNDAI H-1 STAREX 2.5 D CRDi (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBB7372X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	1,353.00 FL	*1,182.00 FL
2	1		*BONNET RH HINGE	Dented	87.00 FL	*70.00 FL
3	1		*BONNET LH HINGE	Dented	87.00 FL	*70.00 FL
4	1		*BONNET LOCK	Serviceable	109.00 FL	*- FL
5	1		*BONNET LOCK GARNISH	Not Necessary	18.00 FL	*- FL
6	1		*FRONT BUMPER	Scratched	515.00 FL	*420.00 FL
7	1		*FRONT BUMPER INNER BRACKET	Not Necessary	211.00 FL	*- FL
8	1		*FRONT BUMPER RH SIDE RETAINER	Not Necessary	32.00 FL	*- FL
9	1		*FRONT BUMPER LH SIDE RETAINER	Not Necessary	32.00 FL	*- FL
10	1		*FRONT BUMPER LOWER	Scratched	387.00 FL	*350.00 FL
11	1		*FRONT BUMPER RH SIDE COVER	Not Necessary	67.00 FL	*- FL
12	1		*FRONT BUMPER LH SIDE COVER	Not Necessary	67.00 FL	*- FL
13	1		*FRONT BUMPER TOW COVER	Not Necessary	18.00 FL	*- FL
14	1		*FRONT BUMPER LOWER GRILLE	Scratched	167.00 FL	*167.00 FL
15	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	356.00 FL	*- FL
16	1		*FRONT BUMPER INNER SPONGE	Broken	98.00 FL	*98.00 FL
17	1		*LH HEADLAMP ASSY	Cracked	731.00 FL	*635.00 FL
18	1		*LH HEADLAMP LOWER BRACKET	Not Necessary	45.00 FL	*- FL
19	1		*RH HEADLAMP ASSY	Cracked	731.00 FL	*635.00 FL
20	1		*RH HEADLAMP LOWER BRACKET	Not Necessary	45.00 FL	*- FL
21	1		*FRONT GRILLE	Cracked	231.00 FL	*231.00 FL
22	1		*FRONT GRILLE EMBLEM	Necessary	33.00 FL	*33.00 FL
23	1		*FRONT GRILLE UPPER GARNISH	Necessary	49.00 FL	*49.00 FL
24	1		*SUPPORT PANEL	Dented	1,030.00 FL	*1,030.00 FL
25	1		*AIRCON CONDENSER	Dented	783.00 FL	*783.00 FL
26	1		*AIRCON SUCTION PIPE	Not Necessary	382.00 FL	*- FL
27	1		*AIRCON DISCHARGE PIPE	Not Necessary	321.00 FL	*- FL
28	1		*INTERCOOLER	Dented	976.00 FL	*550.00 FL
29	1		*RADIATOR ASSY	Dented	986.00 FL	*660.00 FL
30	1		*RADIATOR FAN ASSY	Broken	738.00 FL	*580.00 FL
31	1		*FRONT RH FENDER SPLASH SHIELD	Not Necessary	142.00 FL	*- FL
32	1		*FRONT LH FENDER SPLASH SHIELD	Not Necessary	142.00 FL	*- FL
33	1		*FRONT NUMBER PLATE	Necessary	80.00 FS	*50.00 FS
34	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*60.00 FS
35	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
36	1		*SET FRONT RH FENDER SPLASH SHIELD CLIPS	Not Necessary	70.00 FS	*- FS
37	1		*SET FRONT LH FENDER SPLASH SHIELD CLIPS	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,349.00</b>	<b>7,693.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	2,193.80	1,508.60
<b>Total Parts (\$\$)</b>	<b>9,155.20</b>	<b>6,184.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS .TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,400.00	600.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,200.00	600.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	0.00
5	REMOVE AND REPLACE AIRCON CONDENSER & PIPES TO ASSIST REPAIR	New	250.00	0.00
6	REMOVE AND REPLACE RADIATOR ASSY ,HOSES AND FAN ASSY TO ASSIST REPAIR	New	250.00	0.00
7	REFOCUS AND ADJUST HEADLAMPS ASSY	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>3,340.00</b>	<b>1,230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >