

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG22011766/APA3Q2**Date:** 15/06/2023**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7990000064
Claimant Vehicle No : SNF5803U **Insured Vehicle No :** GBL8303L
 Date of Loss: 23/11/2022 Nature of Claim: TP Claim No: 4164319725SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNF5803U**
 Make & Model: MERCEDES-BENZ C180, 1.8 CGI (A) Engine No: 27182030026768
 Reg. Date: 31/03/2010 (Man. Year: 2009) Chassis No: WDD2040492A360621
 Colour: Grey Odometer: 253700 km
 Engine Capacity: 1796 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/35 R19 Rear Tyre Size: 245/35 R19
 Front Left Side: RADAR 6 mm Rear Left Side: RADAR 6 mm
 Front Right Side: RADAR 6 mm Rear Right Side: RADAR 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,568.15	8,594.77	10,973.38	56.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,390.00	2,020.00	4,370.00	68.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,958.15	10,614.77	15,343.38	59.11
Approved Total (Overridden) (\$\$)		8,400.00		
(\$\$)	25,958.15	8,400.00	17,558.15	67.64
+ GST 8.00/8.00% (\$\$)	2,076.65	672.00	1,404.65	67.64
Nett Amount (\$\$)	28,034.80	9,072.00	18,962.80	67.64
+ Car Rental (6.0 x S\$120.00/day) (\$\$)		720.00		
+ Doc/Search Fee (\$\$)		38.45		
Nett Liability (\$\$)		9,830.45		
Global Sum Settlement (\$\$)		9,800.00		

INSPECTION

Date of Assignment: 23/11/2022
 Date Inspected: 23/11/2022 Inspected At: GARAGE 13 PTE LTD - KAKI BUKIT (HQ)
 8 KAKI BUKIT AVENUE 4, #02-54/55 PREMIER @ KB
 Singapore 415875
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ENFORCEMENT	Dented	780.00 FL	*780.00 FL
2	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	936.00 FL	*468.00 FL
3	4		*REAR BUMPER REVERSE SENSOR WIRE	Necessary	247.00 FL	*247.00 FL
4	2		*REAR BUMPER BRACKET (LOWER)	Damaged	178.00 FL	*178.00 FL
5	2		*REAR BUMPER RETAINER	Not Necessary	262.50 FL	*- FL
6	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	226.50 FL	*226.50 FL
7	1		*REAR END PANEL OUTER	Dented	1,300.40 FL	*980.00 FL
8	2		*REAR O/S & N/S TAIL-LAMP	Cracked	1,654.00 FL	*1,400.00 FL
9	2		*REAR O/S & N/S TAIL LAMP SEAL	Necessary	60.00 FL	*40.00 FL
10	2		*REAR O/S & N/S TAIL LAMP PANEL	Repair	885.00 FL	*- FL
11	2		*REAR REGN NO PLATE LAMP	Not Necessary	120.00 FL	*- FL
12	1		*BOOT OPENER SWITCH ASSY	Not Necessary	580.00 FL	*- FL
13	1		*REAR BOOT COVER	Dented	2,405.00 FL	*2,127.00 FL
14	1		*REAR BOOT COVER WEATHERSTRIP	Cut	253.50 FL	*253.50 FL
15	1		*REAR BOOT COVER EMBLEM	Necessary	63.70 FL	*63.70 FL
16	4		*REAR BOOT COVER O/S & N/S STOPPER	Not Necessary	31.20 FL	*- FL
17	2		*REAR BOOT COVER O/S & N/S HINGES	Not Necessary	87.80 FL	*- FL
18	2		*REAR BOOT COVER O/S & N/S HINGE GARNISH	Not Necessary	66.40 FL	*- FL
19	1		*REAR BOOT COVER LOCK (UPPER)	Damaged	416.00 FL	*416.00 FL
20	1		*REAR BOOT COVER MOULDING (DE CHROME)	Necessary	345.60 FL	*345.60 FL
21	1		*REAR SPARE WHEEL BOARD COVER (FIBER)	Not Necessary	351.50 FL	*- FL
22	1		*REAR EXHAUST MUFFLER	Repair	4,735.50 FL	*- FL
23	4		*REAR EXHAUST MUFFLER MOUNTING	Not Necessary	160.00 FL	*- FL
24	1		*REAR O/S EXHAUST MUFFLER HEAT SHIELD	Dented	430.40 FL	*180.00 FL
25	2		*REAR O/S & N/S SEAT BELT	Not Necessary	2,267.50 FL	*- FL
26	1		*REAR REGN NO PLATE	Not Necessary	120.00 FS	*- FS
27	1		*REAR REGN NO PLATE BRACKET	Not Necessary	29.00 FS	*- FS
28	4		*REAR O/S & N/S TAIL LAMP CLIPS	Necessary	20.00 FS	*20.00 FS
29	1		*REAR BUMPER (BODY KIT)	Distorted	2,400.00 FS	*1,600.00 FS
30	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
31	2		*REAR BOOT COVER EMBLEM CLIPS	Necessary	10.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,452.50	9,365.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,884.35	770.53
Total Parts (\$\$)	19,568.15	8,594.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	2,400.00	900.00
2	TO SPRAY PAINTING	New	2,200.00	900.00
3	TO RE-ALIGN REAR CHASSIS FRAME	New	200.00	0.00
4	TO REMOVE & REPLACE REAR EXHAUST	New	100.00	0.00
5	TO REMOVE & REFIT REAR WINDSCREEN ,REAR SEATS & ROOF LINING	New	280.00	0.00
6	TO REMOVE & REPLACE REAR REVERSE SENSOR CAMERA	New	60.00	50.00
7	TO RESET SEAT BELT	New	200.00	0.00
8	TO RESET FRONT HEAD LAMPS	New	30.00	0.00
9	TO REMOVE AND REPLACE REAR TAIL-GATE (MECHANISM)	New	100.00	80.00
10	TO REMOVE AND REFIT MECHANISM & MOTOR	New	150.00	0.00
11	TO RESET REAR TAIL GATE MOTOR	New	150.00	0.00
12	TO REMOVE & REPLACE RADIATOR	New	150.00	0.00
13	TO TOP UP AIR CON GAS (NPA)	New	0.00	0.00
14	TO RE-SET ELECTRICAL SYSTEM	New	250.00	0.00
15	TO CHECK WIRING	New	30.00	30.00
16	TO RE-SEAL ANTI-RUST	New	90.00	60.00
Gross Labour Cost (\$\$)			6,390.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >