



INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2001934456-01	Date of Loss:	22/11/2022
Vehicle Reg. No.:	SNB441J	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YEAU LIAN KOK		
Driver:	YEAU JUN WEI		
Make/Model:	TOYOTA WISH, 1.8 (A)	Vehicle Reg. Date:	16/11/2016
Vehicle Colour:	Grey		
Engine No:	2ZR1842077	Chassis No:	JTDGG20W90J005492
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)		

COST OF CLAIMS	Amount
Parts	6,754.70
Miscellaneous Items	0.00
Labour	3,460.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	10,214.70
+ GST 7.00% (\$\$)	715.03
Nett Amount (\$\$)	10,929.73

This claim is handled by: JOSHUA NG

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2022)

Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SNB441J/23/11/2022 13:47

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*O/S WIPER GARNISH SIDE COVER	0.00	0.00	*45.00 F
2	1		*BONNET	0.00	0.00	*450.00 F
3	2		*BONNET HINGE	0.00	0.00	*90.00 F
4	1		*BONNET LOGO	0.00	0.00	*42.00 F
5	1		*O/S HEAD LAMP	0.00	0.00	*525.00 F
6	1		*O/S HEAD LAMP BALLAST	0.00	0.00	*395.00 F
7	1		*O/S HEAD LAMP HID BULB	0.00	0.00	*195.00 F
8	1		*RADIATOR GRILLE	0.00	0.00	*195.00 F
9	1		*FRONT BUMPER	0.00	0.00	*295.00 F
10	10		*FRONT BUMPER CLIP	0	0.00	*50.00 FS
11	1		*O/S FRONT BUMPER SIDE RETAINER	0.00	0.00	*45.00 F
12	1		*O/S FRONT BUMPER FOG LAMP	0.00	0.00	*145.00 F
13	1		*O/S FRONT BUMPER FOG LAMP GARNISH WITH CHROME	0.00	0.00	*65.00 F
14	1		*O/S FRONT BUMPER GRILLE	0.00	0.00	*65.00 F
15	1		*O/S FRONT BUMPER INNER AIR GUIDE	0.00	0.00	*75.00 F
16	1		*FRONT BUMPER UNDER COVER	0.00	0.00	*125.00 F
17	10		*FRONT BUMPER UNDER COVER CLIP	0	0.00	*50.00 FS
18	1		*FRONT BUMPER SPONGE	0.00	0.00	*85.00 F
19	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*155.00 F
20	1		*O/S FRONT FENDER	0.00	0.00	*355.00 F
21	1		*O/S FRONT FENDER INNER SHIELD	0.00	0.00	*105.00 F
22	10		*O/S FRONT FENDER INNER SHIELD CLIP	0	0.00	*50.00 FS
23	1		*WIPER WASHER TANK	0.00	0.00	*85.00 F
24	1		*WIPER WASHER TANK MOTOR	0.00	0.00	*95.00 F
25	1		*SPARE COOLANT TANK	0.00	0.00	*85.00 F
26	1		*AIR CON PIPE CONDENSER TO COMPRESSOR	0.00	0.00	*230.00 F
27	1		*O/S SIDE SKIRT	0.00	0.00	*550.00 F
28	10		*O/S SIDE SKIRT CLIPS	0	0.00	*50.00 FS
29	1		*O/S FRONT BUMPER FOG LAMP BULB	0	0.00	*60.00 FS
30	1		*FRONT SUPPORT PANEL	0.00	0.00	*640.00 F
31	10		*BONNET INSULATOR CLIPS	0	0.00	*50.00 FS
32	1		*COOLANT	0	0.00	*40.00 FS
33	1		*O/S FRONT DOOR CHROME MOULDING	0.00	0.00	*250.00 F
34	1		*O/S FRONT LOWER ARM	0.00	0.00	*110.00 F
35	1		*O/S FRONT WHEEL HOUSE PANEL	0.00	0.00	*280.00 F
36	10		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	0	0.00	*50.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	6,177.00
+ Margin on L,N Items 10.00% (\$\$)	577.70

Total Parts (\$\$)	6,754.70
---------------------------	-----------------

Falcon-Air Auto Services Pte Ltd/SNB441J/23/11/2022 13:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO FOCUS HEAD LAMP & WIRING	New	50.00
2	TO VACUM, REOIL AND REGAS AIR CON	New	150.00
3	WHEEL ALIGNMENT	New	150.00
4	TO REPAIR INNER PANEL, ACCIDENT DAMAGE AREA, CUT/REWELD FRONT WHEELHOUSE PANEL, REPLACEMENT OF PARTS AND ALIGN THE SAME	New	1,200.00
5	TO PUTTY AND SPRAY PAINT ON DAMAGE AFFECTED AREA	New	1,200.00
6	TO REPAIR WIRE HARNESS	New	300.00
7	TO TRANSFER TYRE TO NEW RIM AND BALANCE	New	60.00
8	TO REPAIR O/S FRONT RIM	New	350.00
Gross Labour Cost (S\$)			3,460.00

Falcon-Air Auto Services Pte Ltd/SNB441J/23/11/2022 13:47. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >