



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 7809Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (CONSISTENT)	DEFORMED	986.40	986.40
1	REAR BUMPER SIDE HOLDER RH (CONSISTENT)	DAMAGED	130.20	68.00
1	REAR RH FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	2,051.90	-
1	REAR RH FENDER GLASS MOULDING (CONSISTENT)	NOT NECESSARY	85.40	-
	LESS 10% DISCOUNT		-325.39	-105.44
			2,928.51	948.96
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIPS (CONSISTENT) (SN)	NECESSARY	50.00	50.00
1	SET REAR RH FENDER GLASS SEALANT (CONSISTENT) (SN)	NOT NECESSARY	40.00	-
1	SET PAINT PROTECTION (CONSISTENT) (SN)	NECESSARY	500.00	400.00
			590.00	450.00
	<b><u>LABOUR</u></b>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR RH FENDER.		800.00	300.00
	SPRAY PAINTING.		800.00	400.00
	WIRING.		50.00	50.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO SPRAY TUFF COAT.		100.00	40.00
	TO REMOVE REAR FENDER GLASS.	NOT NECESSARY	100.00	-
			1,950.00	840.00
	<b>GRAND TOTAL</b>		<b>5,468.51</b>	<b>2,238.96</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,800.00</b>

Report Ref No. CS/ASM22011793/Avp3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.