

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22011795/TPA3Q2**Date:** 18/05/2023REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SPCM1000000063
Claimant Vehicle No :	SMN720C	Insured Vehicle No :	YP6910D
Date of Loss:	21/11/2022	Nature of Claim:	TP
		Claim No:	202222008345

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN720C		
Make & Model:	BMW X5XDRIVE40I, 3.0 7SEAT MSPT ADAPT LEDHL FL (A)	Engine No:	19216229B58B30C
Reg. Date:	05/04/2021 (Man. Year: 2020)	Chassis No:	WBACR620509F35257
Colour:	Blue	Odometer:	0 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/40 R21	Rear Tyre Size:	275/40 R21
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,155.35	2,757.50	1,397.85	33.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,877.00	4,101.00	1,776.00	30.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	10,032.35	6,858.50	3,173.85	31.64
+ GST 8.00/8.00% (\$\$)	802.59	548.68	253.91	31.64
Nett Amount (\$\$)	10,834.94	7,407.18	3,427.76	31.64
+ Loss of Use (5.0 x S\$100.00/day) (\$\$)		500.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		7,909.18		

INSPECTION

Date of Assignment:	23/11/2022	
Date Inspected:	24/11/2022 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2023)
Parts:	M1-SUV	BMW X5XDRIVE40I 3.0 7SEAT MSPT ADAPT LEDHL FL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN720C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*FRT LH DOOR	Bent	2,319.45 FS	*2,319.45 FS
3	1		*PRIME COATED COVERING	Not Necessary	51.20 FS	*- FS
4	1		*LH DOOR OUTER HANDLE PRIMED (CA/OVT)	Distorted	98.35 FS	*98.35 FS
5	1		*LH DOOR HANDLE OUTSIDE CARRIER	Not Necessary	183.90 FS	*- FS
6	1		*FRT LH DOOR SIDE WINDOW GLASS	Not Necessary	367.80 FS	*- FS
7	1		*FRT LH DOOR CARRIER	Not Necessary	724.95 FS	*- FS
8	1		*(S/L) DOOR WEATHERSTRIP	Necessary	208.60 FS	*208.60 FS
9	1		*(S/L) LH A PILLAR CAULKING	Deformed	51.10 FS	*51.10 FS
Total Parts (S\$)						4,155.35 2,757.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT LH DOOR AND ATTACHMENTS INCLUDE MAKING GOOD THE REAR LH DOOR AND KNOCKING OUT DENTS CAUSED BTY THE ACCIDENT	New	2,550.00	1,275.00
2	TO SPRAY PAINT FRONT LH DOOR AND HANDLE AND REAR LH DOOR	New	2,076.00	2,042.00
3	TO CHECK ELECTRICAL WIRING SYSTEM	New	177.00	168.00
4	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECK ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	504.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	112.00
6	TO SUPPLY AND INSTALL FRONT LEFT OR RIGHT WINDOW GLASS SOLAR FILM	New	425.00	0.00
Gross Labour Cost (S\$)			5,877.00	4,101.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >