

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22011797/ANCE2**Date:** 04/05/2023**REFERENCE**

Insured/Claimant:	SUZANNA BINTE HASHIM	Policy No:	2100503413
Date of Loss:	19/11/2022	Nature of Claim:	OD
		Claim No:	3203752497SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL8342E	Engine No:	CVN030936
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF48HA116013
Reg. Date:	11/03/2017 (Man. Year: 2017)	Odometer:	31389 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$86,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	31,813.00	14,244.00	17,569.00	55.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,394.00	4,732.00	5,662.00	54.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,207.00	18,976.00	23,231.00	55.04
- Excess (S\$)	3,300.00	3,300.00	0.00	0.00
(S\$)	38,907.00	15,676.00	23,231.00	59.71
+ GST 8.00/8.00% (S\$)	3,112.56	1,254.08	1,858.48	59.71
Nett Amount (S\$)	42,019.56	16,930.08	25,089.48	59.71

INSPECTION

Date of Assignment:	23/11/2022		
Date Inspected:	22/11/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	612.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Cracked	219.00 FS	*174.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	254.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	72.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,277.00 FS	*1,021.60 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	151.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	139.00 FS	*- FS
10	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
11	1		*FRONT BUMPER TOP COVER	Deformed	143.00 FS	*114.00 FS
12	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
13	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
14	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	41.00 FS	*- FS
15	1		*FRONT BUMPER BRACKET	Cracked	154.00 FS	*122.80 FS
16	1		*FRONT BUMPER SUPPORT - LH / RH	N/s Damaged	64.00 FS	*25.60 FS
17	1		*HORN HIGH TONE - LH	Not Necessary	134.00 FS	*- FS
18	1		*HORN BRACKET - LH	Not Necessary	33.00 FS	*- FS
19	1		*FRONT FENDER - LH	Buckled	861.00 FS	*688.80 FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	225.00 FS	*- FS
21	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	81.00 FS	*- FS
22	1		*FRONT FENDER BRACKET - LH	Not Necessary	41.00 FS	*- FS
23	1		*FRONT FENDER BRACE - LH	Not Necessary	132.00 FS	*- FS
24	6		*FRONT FENDER RIVET	Necessary	23.00 FS	*18.24 FS
25	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - LH	Not Necessary	55.00 FS	*- FS
26	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	260.00 FS	*- FS
27	1		*FRONT WHEEL SPOILER	Not Necessary	82.00 FS	*- FS
28	1		*FRONT WHEEL SPOILER END PLATE - LH	Not Necessary	39.00 FS	*- FS
29	1		*FRONT WHEEL SPOILER STONE CHIP GUARD	Not Necessary	57.00 FS	*- FS
30	1		*FRONT FENDER LEDGE COVER - LONG	Not Necessary	35.00 FS	*- FS
31	1		*FRONT FENDER LEDGE COVER - SHORT	Not Necessary	26.00 FS	*- FS
32	1		*BONNET	Dented	3,425.00 FS	*2,740.00 FS
33	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
34	2		*BONNET HINGE - LH / RH	Not Necessary	680.00 FS	*- FS
35	1		*BONNET STRIKER - LH	Not Necessary	56.00 FS	*- FS
36	1		*BONNET LOCK	Not Necessary	228.00 FS	*- FS
37	1		*BONNET BOWDEN CABLE	Not Necessary	64.00 FS	*- FS
38	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
39	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
40	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
41	1		*HEADLIGHT - LH	Cracked	8,294.00 FS	*6,635.20 FS
42	1		*HEADLIGHT POWER MODULE	Not Necessary	842.00 FS	*- FS
43	1		*HEADLIGHT CONTROL UNIT	Not Necessary	840.00 FS	*- FS
44	1		*HEADLIGHT HOSE - LH	Not Necessary	42.00 FS	*- FS
45	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	45.00 FS	*- FS
46	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	47.00 FS	*- FS
47	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	45.00 FS	*- FS
48	1		*LIFT CYLINDER - LH	Not Necessary	231.00 FS	*- FS
49	1		*LIFT CYLINDER BRACKET	Not Necessary	7.00 FS	*- FS
50	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
51	1		*LOCK CARRIER	Not Necessary	1,478.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*LOCK CARRIER SUPPORT - LH	Not Necessary	43.00 FS	*- FS
53	1		*A/C CONDENSER	Dented	683.00 FS	*546.00 FS
54	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	186.00 FS	*- FS
55	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	381.00 FS	*- FS
56	1		*A/C CONDENSER REFRIGERANT LINE	Not Necessary	277.00 FS	*- FS
57	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	21.00 FS	*- FS
58	1		*RADIATOR	Not Necessary	699.00 FS	*- FS
59	6		*READY-MIX COOLANT	Not Necessary	297.00 FS	*- FS
60	1		*RADIATOR AIR GUID E- LH / RH INNER	N/s Damaged	64.00 FS	*25.60 FS
61	1		*RADIATOR AIR GUID E- LH / RH OUTER	N/s Damaged	28.00 FS	*10.88 FS
62	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
63	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
64	1		*RADIATOR AIR GUIDE FAN RING	Not Necessary	292.00 FS	*- FS
65	1		*RADIATOR FAN CONTROL UNIT	Not Necessary	2,489.00 FS	*- FS
66	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
67	1		*SUNDRIES	Necessary	500.00 FS	*66.64 FS
68	1		*ADDITIONAL RADIATOR - LOWER CENTRE	Not Necessary	545.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	31,813.00	14,244.00
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	780.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,900.00	1,500.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND HINGES	New	3,000.00	1,650.00
6	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
Gross Labour Cost (\$\$)			10,394.00	4,732.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >