

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011801/UQP3Q2**Date:** 28/12/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNA00027032201

Claimant Vehicle No : SJU9596J**Insured Vehicle No :** SKJ3986C

Date of Loss: 21/11/2022

Nature of Claim: TP

Claim No: SNM22D208389/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJU9596J**Make & Model: HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD
4DR (A)

Engine No: G4FC9U775438

Reg. Date: 06/01/2010 (Man. Year: 2009)

Chassis No: KMH DU41BMAU932654

Colour: Silver

Odometer: 327206 km

Engine Capacity: 1591 cc

Market Value/New Car
Price: N/ASum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,020.40	4,878.56	6,141.84	55.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,730.00	2,680.00	1,050.00	28.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,750.40	7,558.56	7,191.84	48.76
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	14,750.40	6,000.00	8,750.40	59.32

INSPECTION

Date of Assignment: 23/12/2022

Date Inspected: 23/11/2022 Inspected At:

2ND Auto Pte Ltd (HQ)

15 Kaki Bukit Road 4, #01-05/53 Bartley Biz Centre
Singapore 417808

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts:	143	HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU9596J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed / Torn	1,200.00 FL	*494.40 FL
2	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	150.00 FL	*- FL
3	1		*FRONT BUMPER LOWER GRILLE	Torn	210.00 FL	*86.90 FL
4	1		*FRONT BUMPER GRILLE	No such part	340.00 FL	*- FL
5	1		*FRONT LOGO BADGE	Not Necessary	48.00 FL	*- FL
6	1		*FRONT BONNET	Not Necessary	1,450.00 FL	*- FL
7	1		*REAR BUMPER	Distorted	1,124.00 FL	*494.20 FL
8	2		*REAR BUMPER SIDE RETAINER	Bent	150.00 FL	*96.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Cracked	578.00 FL	*291.00 FL
10	6		*REAR BUMPER REINFORCEMENT BRACKETS	Not Necessary	271.20 FL	*- FL
11	1		*REAR BUMPER INNER FOAM	Torn	142.00 FL	*142.00 FL
12	2		*REAR BUMPER REFLECTORS	Not fitted	157.00 FL	*- FL
13	2		*REAR BUMPER BRACKETS	Bent	196.40 FL	*196.40 FL
14	1		*REAR END PANEL	Badly Dented	689.00 FL	*484.00 FL
15	1		*REAR END PANEL TOP GARNISH	Twisted	276.50 FL	*162.00 FL
16	1		*REAR SPARE TYRE PANEL	Repair	780.00 FL	*- FL
17	1		*BOOTLID	Badly Dented	1,245.00 FL	*1,245.00 FL
18	2		*BOOTLID HINGE	Not Necessary	220.00 FL	*- FL
19	1		*BOOT EDGE WEATHERSTRIP	Twisted	172.00 FL	*172.00 FL
20	1		*BOOTLID LOGO (CENTRE BADGE)	Necessary	48.00 FL	*48.00 FL
21	1		*BOOTLID HYUNDAI EMBLEM	Not fitted	110.00 FL	*- FL
22	1		*BOOTLID AVANTE EMBLEM	Necessary	110.00 FL	*48.00 FL
23	1		*BOOTLID S EMBLEM	Not Necessary	32.00 FL	*- FL
24	4		*BOOTLID RUBBER STOPPER	Not Necessary	48.00 FL	*- FL
25	1		*BOOTLID OUTER HANDLE	Cracked	230.00 FL	*166.00 FL
26	1		*BOOTLID LOCK	Bent	228.40 FL	*145.00 FL
27	1		*BOOTLID LOCK CATCH	Not Necessary	85.00 FL	*- FL
28	1		*BOOTLID INNER TRIM	Deformed / Torn	340.00 FL	*182.30 FL
29	2		*BOOTLID REFLECTOR RHS & LHS	Cracked	690.00 FL	*480.00 FL
30	1		*BOOTLID KEYLESS LOCK ACTUATOR	Not Necessary	242.50 FL	*- FL
31	2		*REAR LHS & RHS TAILLAMP	Cracked	1,300.00 FL	*690.00 FL
32	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
33	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
34	1		*REAR NUMBER PLATE W/BASE	Bent	75.00 FS	*40.00 FS
35	1		*FRONT NUMBER PLATE W/BASE	Bent	75.00 FS	*40.00 FS
36	1		*SET RHS REAR FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
37	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
38	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,593.00	6,003.20
- List Item Discount on L Items 20.00/20.00% (S\$)	2,572.60	1,124.64
Total Parts (S\$)	11,020.40	4,878.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & COMPONENTS TO COMMENCE REPAIRS PANEL BEAT & RESHAPE THE AFFECTED AREAS ,REPLACE DAMAGED PARTS	New	1,400.00	900.00
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	New	1,600.00	1,500.00
3	TO REMOVE CHECK AND REFIX WIRING AT REAR AND FRONT DAMAGED AREA	New	100.00	30.00
4	TO REMOVE AND REFIX /REPLACE INNER TRIMS ,GARNISH AND REAR FITTINGS ETC .SO AS TO FACILITATE REPAIRS	New	250.00	80.00
5	TO REMOVE AND REFIX REAR BOOTLID COMPONENTS	New	100.00	60.00
6	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTION	New	100.00	50.00
7	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	180.00	60.00
Gross Labour Cost (S\$)			3,730.00	2,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >