

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011802/TNP3Q2**Date:** 15/05/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00247532100
Claimant Vehicle No :	SKC5851G	Insured Vehicle No :	SLF4615B
Date of Loss:	22/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D208387/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC5851G	Engine No:	27091030866185
Make & Model:	MERCEDES-BENZ CLA180, 1.6 (A)	Chassis No:	WDD1173422N316563
Reg. Date:	12/04/2016 (Man. Year: 2015)	Odometer:	147471 km
Colour:	Orange		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,993.10	8,046.40	26,946.70	77.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,370.00	1,890.00	4,480.00	70.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	41,363.10	9,936.40	31,426.70	75.98
Approved Total (Overridden) (S\$)		7,900.00		
(S\$)	41,363.10	7,900.00	33,463.10	80.90
+ GST 8.00/8.00% (S\$)	3,309.05	632.00	2,677.05	80.90
Nett Amount (S\$)	44,672.15	8,532.00	36,140.15	80.90

INSPECTION

Date of Assignment:	31/01/2023	
Date Inspected:	25/11/2022	Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 May 2023)
Parts:	143	MERCEDES-BENZ CLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC5851G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,532.00 FL	*1,532.00 FL
2	1		*BOOTLID CENTRE EMBLEM	Necessary	78.00 FL	*78.00 FL
3	1		*BOOTLID LOCK	Not Necessary	316.00 FL	*- FL
4	1		*BOOTLID LOCK CATCH	Not Necessary	56.00 FL	*- FL
5	1		*BOOTLID RH HINGE	Not Necessary	189.00 FL	*- FL
6	1		*BOOTLID LH HINGE	Not Necessary	189.00 FL	*- FL
7	1		*BOOTLID WEATHERSTRIP	Not Necessary	389.00 FL	*- FL
8	1		*BOOTLID INNER TRIM	Not Necessary	366.00 FL	*- FL
9	1		*BOOTLID RH NUMBER PLATE LAMP	Not Necessary	78.00 FL	*- FL
10	1		*BOOTLID LH NUMBER PLATE LAMP	Not Necessary	78.00 FL	*- FL
11	1		*REAR BUMPER	Cracked	1,219.00 FL	*1,219.00 FL
12	1		*REAR BUMPER LOWER GARNISH	Deformed	313.00 FL	*313.00 FL
13	1		*REAR BUMPER TOWING COVER	Missing	36.00 FL	*36.00 FL
14	1		*REAR BUMPER RH CORNER REVERSE SENSOR	Not Necessary	257.00 FL	*- FL
15	1		*REAR BUMPER RH SIDE REVERSE SENSOR	Not Necessary	257.00 FL	*- FL
16	1		*REAR BUMPER RH CENTRE REVERSE SENSOR	Not Necessary	257.00 FL	*- FL
17	1		*REAR BUMPER LH CENTRE REVERSE SENSOR	Cut	257.00 FL	*257.00 FL
18	1		*REAR BUMPER LH SIDE REVERSE SENSOR	Missing	257.00 FL	*257.00 FL
19	1		*REAR BUMPER LH CORNER REVERSE SENSOR	Missing	257.00 FL	*257.00 FL
20	1		*REAR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	41.00 FL	*41.00 FL
21	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Torn	118.00 FL	*118.00 FL
22	1		*REAR BUMPER LOWER TRIM CHROME MOULDING	Missing	421.00 FL	*280.00 FL
23	1		*REAR BUMPER RH BRACKET	Not Necessary	56.00 FL	*- FL
24	1		*REAR BUMPER LH BRACKET	Not Necessary	56.00 FL	*- FL
25	1		*REAR BUMPER RH SIDE HOLDER	Not Necessary	43.00 FL	*- FL
26	1		*REAR BUMPER LH SIDE HOLDER	Distorted	43.00 FL	*43.00 FL
27	1		*REAR BUMPER CENTRE BRACKET	Deformed	116.00 FL	*116.00 FL
28	1		*REAR BUMPER RH LOWER BRACKET	Not Necessary	42.00 FL	*- FL
29	1		*REAR BUMPER LH LOWER BRACKET	Not Necessary	42.00 FL	*- FL
30	1		*REAR BUMPER RH EXHAUST CHROME COVER	Not Necessary	289.00 FL	*- FL
31	1		*REAR BUMPER LH EXHAUST CHROME COVER	Bent	289.00 FL	*289.00 FL
32	1		*REAR BUMPER REINFORCEMENT	Bent	790.00 FL	*790.00 FL
33	1		*RH TAILLAMP ASSY	Not Necessary	832.00 FL	*- FL
34	1		*RH TAILLAMP PANEL	Not Necessary	198.00 FL	*- FL
35	1		*SET RH TAILAMP LOWER CLIPS	Not Necessary	48.00 FL	*- FL
36	1		*RH TAILLAMP LOWER BRACKET	Not Necessary	48.00 FL	*- FL
37	1		*RH HEADLAMP FRAME SEALING	Not Necessary	69.00 FL	*- FL
38	1		*LH TAILLAMP ASSY	Cracked	832.00 FL	*720.00 FL
39	1		*LH TAILLAMP PANEL	Not Necessary	198.00 FL	*- FL
40	1		*SET LH TAILAMP LOCK CLIPS	Not Necessary	48.00 FL	*- FL
41	1		*LH TAILLAMP LOWER BRACKET	Deformed	48.00 FL	*48.00 FL
42	1		*LH HEADLAMP FRAME SEALING	Not Necessary	69.00 FL	*- FL
43	1		*END PANEL	Bent	1,012.00 FL	*1,012.00 FL
44	1		*END PANEL INNER GARNISH	Deformed	184.00 FL	*184.00 FL
45	1		*REAR SPARE TYRE PANEL	Not Necessary	1,874.00 FL	*- FL
46	1		*REAR SPARE TYRE PANEL INSULATOR	Not Necessary	296.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR SPARE TYRE TOP COVER BOARD	Not Necessary	569.00 FL	*- FL
48	1		*REAR WINDSCREEN GLASS WITH RUBBER MOULDING	Not Necessary	1,372.00 FL	*- FL
49	1		*REAR RH FENDER	Not Necessary	2,996.00 FL	*- FL
50	1		*REAR RH FENDER INNER TRIM	Not Necessary	684.00 FL	*- FL
51	1		*REAR RH FENDER SPLASH SHIELD	Not Necessary	189.00 FL	*- FL
52	1		*REAR LH FENDER	Not Necessary	2,996.00 FL	*- FL
53	1		*REAR LH FENDER INNER TRIM	Not Necessary	684.00 FL	*- FL
54	1		*REAR LH FENDER SPLASH SHIELD	Not Necessary	189.00 FL	*- FL
55	1		*REAR SPARE TYRE TOP COVER BOARD	Not Necessary	579.00 FL	*- FL
56	1		*EXHAUST SILENCER RUBBER MOUNTINGS	Deformed	86.00 FL	*86.00 FL
57	1		*DRIVER SEAT BELT	Not Necessary	755.00 FL	*- FL
58	1		*DRIVER SEAT BELT BUCKLE	Not Necessary	156.00 FL	*- FL
59	1		*FRONT LH PASSENGER SEAT BELT	Not Necessary	755.00 FL	*- FL
60	1		*FRONT LH PASSENGER SEAT BELT BUCKLE	Not Necessary	156.00 FL	*- FL
61	1		*REAR RH PASSENGER SEAT BELT	Not Necessary	755.00 FL	*- FL
62	1		*REAR RH PASSENGER SEAT BELT BUCKLE	Not Necessary	156.00 FL	*- FL
63	1		*REAR LH PASSENGER SEAT BELT	Not Necessary	755.00 FL	*- FL
64	1		*REAR LH PASSENGER SEAT BELT BUCKLE	Not Necessary	156.00 FL	*- FL
65	1		*REAR RH WHEEL BEARING	Not Necessary	584.00 FL	*- FL
66	1		*REAR LH WHEEL BEARING	Not Necessary	584.00 FL	*- FL
67	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
68	1		*BOOTLID SPOILER	Not Necessary	1,100.00 FS	*- FS
69	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	80.00 FS	*- FS
70	1		*REAR WINDSCREEN GLASS INNER SEAL	Not Necessary	60.00 FS	*- FS
71	1		*REAR RH FENDER JOINT SEALANT	Not Necessary	100.00 FS	*- FS
72	1		*SET REAR RH FENDER INNER TRIM CLIPS	Not Necessary	85.00 FS	*- FS
73	1		*SET REAR RH FENDER SPLASH SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
74	1		*REAR RH FENDER JOINT SEALANT	Not Necessary	100.00 FS	*- FS
75	1		*SET REAR LH FENDER INNER TRIM CLIPS	Not Necessary	85.00 FS	*- FS
76	1		*SET REAR LH FENDER SPLASH SHIELD CLIPS	Not Necessary	60.00 FS	*- FS
77	1		*END PANEL JOINT SEALANT	Necessary	80.00 FS	*40.00 FS
78	1		*SET END PANEL INNER GARNISH CLIPS	Necessary	70.00 FS	*20.00 FS
79	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
80	1		*EXHAUST SILENCER (AFTER MARKET)	Bent	2,800.00 FS	*1,000.00 FS
81	1		*EXHAUST SILENCER GASKET (AFTER MARKET)	Necessary	78.00 FS	*78.00 FS
82	1		*REAR RH SPORT RIM	Not Necessary	1,150.00 FS	*- FS
83	1		*REAR RH TYRE	Not Necessary	550.00 FS	*- FS
84	1		*REAR LH SPORT RIM	Not Necessary	1,150.00 FS	*- FS
85	1		*REAR LH TYRE	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	37,957.00	8,814.00
- List Item Discount on L Items 10.00/10.00% (\$)	2,963.90	767.60
Total Parts (\$)	34,993.10	8,046.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,CHECK ,REPLACE AND REINSTALL DAMAGES BODYPARTS ,TO PANEL BEATING ,CUT/WELD AND REALIGN ALL AFFECTED PANELS AND AREAS	New	1,400.00	700.00
2	SPRAY PAINTING ON AFFECTED AREAS AND PANELS	New	1,300.00	700.00
3	CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS	New	80.00	30.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED AREAS AND PANELS	New	80.00	30.00
5	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	New	100.00	30.00
6	REMOVE AND REPLACE GARNISH ,TRIMS ,SEAT AND BOARDS TO ASSIST REPAIR	New	360.00	60.00
7	REMOVE AND REPLACE EXHAUST SILENCER ,GASKET AND RUBBER MOULDINGS TO ASSIST REPAIR	New	350.00	80.00
8	CONDUCT DIAGNOSE AND RESET ELECTRONIC CONTROL SYSTEM	New	450.00	200.00
9	REMOVE AND REPLACE BOOTLID INNER MECHANISM TO NEW BOOTLID	New	220.00	60.00
10	REMOVE AND REPLACE ROOF LINING ,GARNISH ,TRIMS ,SEAT AND BOARDS TO REPAIR	New	550.00	0.00
11	REMOVE AND REPLACE FRONT AND REAR SEAT BELTS AND BUCKLES TO REPAIR	New	320.00	0.00
12	CONDUCT DIAGNOSE AND RESET ELECTRONIC CONTROL SYSTEM	New	480.00	0.00
13	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	180.00	0.00
14	REMOVE AND REPLACE REAR WHEEL BEARINGS TO ASSIST REPAIR	New	500.00	0.00
Gross Labour Cost (\$\$)			6,370.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >