

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22011804/UYA3Q2**Date:** 17/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100478584
Claimant Vehicle No :	SLS9993H	Insured Vehicle No :	SLF1262E
Date of Loss:	20/11/2022	Nature of Claim:	TP
		Claim No:	1440154042SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS9993H	Engine No:	2ARH938843
Make & Model:	TOYOTA ALPHARD, 2.5 (A)	Chassis No:	AGH300135041
Reg. Date:	27/07/2017 (Man. Year: 2017)	Odometer:	137091 km
Colour:	Black		
Engine Capacity:	2493 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,948.35	5,488.40	2,459.95	30.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,300.00	1,200.00	48.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,448.35	6,788.40	3,659.95	35.03
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	10,448.35	5,400.00	5,048.35	48.32
+ GST 7.00/7.00% (S\$)	731.38	378.00	353.38	48.32
Nett Amount (S\$)	11,179.73	5,778.00	5,401.73	48.32
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
(S\$)		6,206.00		
Liabe Amount (50.00%) (S\$)		3,103.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,105.00		

INSPECTION

Date of Assignment:	02/12/2022		
Date Inspected:	02/12/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,893.84 FL	*1,295.10 FL
2	4		*FRONT BUMPER CLIP	Necessary	17.20 FL	*17.20 FL
3	1		*O/S FRONT BUMPER FOG LAMP	Cracked	516.00 FL	*516.00 FL
4	1		*O/S FRONT BUMPER FOG LAMP GARNISH	No such part	38.20 FL	*- FL
5	1		*O/S FRONT BUMPER FOG LAMP OUTER CHROME	Cracked	234.00 FL	*234.00 FL
6	1		*FRONT BUMPER BEAM	Not Necessary	238.00 FL	*- FL
7	1		*FRONT BUMPER LOWER BEAM	Not Necessary	452.00 FL	*- FL
8	1		*FRONT BUMPER FOAM	Not Necessary	79.60 FL	*- FL
9	1		*O/S FRONT BUMPER SIDE RETAINER	Cracked	75.00 FL	*75.00 FL
10	1		*O/S FRONT BUMPER SIDE CHROME MOULDING	Missing	143.00 FL	*143.00 FL
11	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	135.00 FL	*- FL
12	1		*O/S HEADLAMP	Cracked	3,796.90 FL	*3,796.90 FL
13	1		*O/S HEADLAMP BRACKET	Not Necessary	95.00 FL	*- FL
14	1		*O/S HEADLAMP CHROME MOULDING	Not Necessary	238.60 FL	*- FL
15	1		*O/S FRONT FENDER	Bent	780.10 FL	*780.10 FL
16	1		*O/S FRONT FENDER COWLING	Torn	175.90 FL	*175.90 FL
17	4		*O/S FRONT FENDER COWLING CLIP	Necessary	18.00 FL	*18.00 FL
18	1		*BONNET	Not Necessary	792.00 FL	*- FL
19	2		*BONNET INSULATOR CLIP	Not Necessary	8.60 FL	*- FL
20	1		*BONNET OUTER CHROME GARNISH	Not Necessary	249.00 FL	*- FL
21	2		*BONNET HINGE	Not Necessary	115.20 FL	*- FL
22	1		*SET FRONT BUMPER PARKING SENSOR	Shorted	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,471.14	7,251.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,522.79	1,762.80
Total Parts (\$\$)	7,948.35	5,488.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	180.00	30.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	100.00	20.00
3	TO REINSTALL OF FRT BUMPER PARKING SENSOR	New	120.00	50.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,100.00	400.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,500.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >