



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 4168G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDE MIRROR ASSY RH	BROKEN	1,000.00	1,000.00
1	SIDE MIRROR COVER RH	CRACKED	234.00	234.00
	LESS 10% DISCOUNT		-123.40	-123.40
			1,110.60	1,110.60
	<u>LABOUR</u>			
	TO REMOVE THE AFFECTED PARTS & FITTING TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.		100.00	100.00
	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		200.00	100.00
	TO REMOVE AND REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION.		60.00	30.00
			360.00	230.00
	GRAND TOTAL		1,470.60	1,340.60
RECOMMENDED COST OF REPAIRS				1,340.60

Report Ref No. CS/LIP22011822/Tvy3e2

MARKET VALUE: \$118,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$42,104.00=NETT VALUE: \$75,896.00

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.