

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG22011823/AYA3Q2**Date:** 17/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900083522
Claimant Vehicle No :	SLW1544C	Insured Vehicle No :	SMK4355M
Date of Loss:	18/11/2022	Nature of Claim:	TP
		Claim No:	5164091225SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW1544C	Engine No:	2ARH782635
Make & Model:	TOYOTA VELLFIRE, 2.5 CVT S/R (A)	Chassis No:	JTNGF3DH308006547
Reg. Date:	01/12/2016 (Man. Year: 2016)	Odometer:	110877 km
Colour:	Black		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,919.00	943.12	3,975.88	80.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	980.00	960.00	49.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,859.00	1,923.12	4,935.88	71.96
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	6,859.00	1,500.00	5,359.00	78.13
+ Car Rental (4.0 x S\$150.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,107.45		

INSPECTION

Date of Assignment:	12/12/2022		
Date Inspected:	12/12/2022	Inspected At:	Fong Motors - Kaki Bukit (HQ) 1 KAKI BUKIT AVE 6 #01-27/01-45 Singapore 417883
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Repair	2,210.20 F	*- FL
2	1		*REAR BUMPER	Deformed	790.20 F	*790.20 FL
3	1		*REAR END PANEL	Repair	844.40 F	*- FL
4	1		*LH CORNER PANEL	Not Necessary	314.00 F	*- FL
5	1		*REVERSE SENSOR	Damaged	393.60 F	*393.60 FL
6	1		*VELLFIRE EMBLEM	Necessary	73.70 F	*73.70 FL
7	1		*BUMPER SIDE RETAINER	Not Necessary	111.80 F	*- FL
8	1		*END PANEL GARNISH	Not Necessary	181.10 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	4,919.00	1,257.50
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	314.38
Total Parts (S\$)	4,919.00	943.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	KNOCKING	New	800.00	400.00
2	TO SPRAY PAINT TAILGATE ,BUMPER ,CORNER END PANEL ,END PANEL	New	1,000.00	500.00
3	TO CONDUCT WIRING CHECKS	New	60.00	30.00
4	TO REMOVE AND REPLACE REVERSE SERNSORS	New	80.00	50.00
Gross Labour Cost (\$\$)			1,940.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >