

SKP3696H. 2011 Feb.

TP China

BMW 523i 2497cc

Xiao Chen

WBAFP32060C863790

| | | | |
|--|------------|---------------------------------|---|
| Front Bumper. | Repair | 1480. | X |
| Front Bumper clips. | | 50(SN) | X |
| Front Bumper Side Holder. | } MP HR | 110. | X |
| Front Bumper Sensor. | | 285 | X |
| Front LH Fender. | Dented | 988 | / |
| Front RH Fender Garnish. | cut | 180(SN) | / |
| Front LH Fender Garnish Chrome Moulding. | rer | 50(SN) | / |
| Front LH Door. | Repair | 1985 | X |
| Front Wheel Rim x 2. | cut | 1500 x 2 = 3000 (SN) | |
| Headlamp LH. | cracked | 2486. | / |

3474

SN: 1750

32660

SKP 3696 H.

Panel Beating.

~~800~~ 400

Spray Painting.

~~1000~~ 600

Wiring.

1150

~~1000~~ 300

To apply tuff coat.

~~150~~ 40

To transfer front door fittings.

150. +

To perform wheel alignment.

~~150~~ 80

Total: 6026.60

2/s: 4.8K.

05 Days.