

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22011826/UVY3M4**Date:** 11/01/2023**REFERENCE**

Insured/Claimant: ACTECO HOLDING PTE LTD Policy No: DMCG22011262  
Date of Loss: 14/10/2022 Nature of Claim: OD Claim No: CDMCG22002192

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **YQ4020E**  
Make & Model: MITSUBISHI CANTER, 3.0 D FEB21ER3SDEN (CBU) (M) Engine No: 4P10E55388  
Reg. Date: 13/08/2021 (Man. Year: 2021) Chassis No: FEB21EA35325  
Colour: White Odometer: 25812 km  
Engine Capacity: 2998 cc  
Market Value/New Car Price: S\$102,000.00  
Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/85 R15 Rear Tyre Size: 195/85 R15 (D/D)  
Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7/7 mm  
Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7/7 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 1,237.50          | 489.50            | 748.00            | 60.44         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 2,590.00          | 2,400.00          | 190.00            | 7.34          |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>3,827.50</b>   | <b>2,889.50</b>   | <b>938.00</b>     | <b>24.51</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>2,300.00</b>   |                   |               |
| <b>- Excess (\$\$)</b>                    | 0.00              | 1,000.00          | -1,000.00         |               |
| <b>(\$\$)</b>                             | 3,827.50          | 1,300.00          | 2,527.50          | 66.04         |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 267.93            | 91.00             | 176.93            | 66.04         |
| <b>Nett Amount (\$\$)</b>                 | <b>4,095.43</b>   | <b>1,391.00</b>   | <b>2,704.43</b>   | <b>66.04</b>  |

**INSPECTION**

Date of Assignment: 23/11/2022 Present Location: Jin Auto Services Pte Ltd (Defu)  
Date Inspected: 05/12/2022 Inspected At: Jin Auto Services Pte Ltd (Defu)  
Estimated Period of Repair: 5.0 days Blk 14 Defu Lane 10, #01-410/412  
Singapore 539195

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |  |  |
|---------------|--|--|
| Reference     |  |  |
| Part Source:  | (Last Synchronised: 11 Jan 2023)   |  |
| Parts:        | N/A  | mitsubishi canter 3.0 d feb21er3sden (cbu) (m) (model not available in database) |
| Labour:       | Repairer's   | (Price-denominated Standard List)  |
| Print Code:   | (Unsubmitted, no print-code for YQ4020E)   |  |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.   |  |

Recommended Parts

| No.                                       | Qty | Part No. | Particulars                                  | Condition     | Repairer's | Amount    |
|---|-----|----------|--|---------------|------------|-----------|
| Supplementary #1                          |     |          |  |               |            |           |
| 1   | 1   |          | *FRONT RH DOOR GLASS<br>(WCP)                | Serviceable   | 330.00 F   | *- F      |
| 2   | 1   |          | *FRONT RH DOOR GLASS OUTER MOULDING<br>(WCP) | Grazed        | 110.00 F   | *110.00 F |
| 3   | 1   |          | *HEADLAMP RH<br>(WCP)                        | Not Necessary | 350.00 F   | *- F      |
| 4   | 1   |          | *DOOR SIDE MIRROR<br>(WCP)                   | Broken        | 115.00 F   | *115.00 F |
| 5   | 1   |          | *REPEATER LAMP<br>(WCP)                      | Cracked       | 220.00 F   | *220.00 F |
| F=Franchise part.                         |     |          |  |               |            |           |
| Sub Total (\$\$)                          |     |          |  |               | 1,125.00   | 445.00    |
| + Margin on L,N Items 10.00/10.00% (\$\$) |     |          |  |               | 112.50     | 44.50     |
| Total Parts (\$\$)                        |     |          |  |               | 1,237.50   | 489.50    |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars  | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>            |  |          |                 |                 |
| 1                              | To supply & labour rewrap driver side (01) front pillar & fix panel ,<br>replace front driver side box (01) hollow section & To supply & rewrap<br>front driver side roof aluminium sheet<br>(Distorted) | New      | 1,700.00        | 1,700.00        |
| <b>Supplementary #1</b>        |  |          |                 |                 |
| <b>Labour Items</b>            |  |          |                 |                 |
| 2                              | LABOUR CHARGE TO REPAIR DOOR , DOOR PILLAR   | New      | 450.00          | 400.00          |
| 3                              | REMOVE AND RENEW DOOR GLASS  | New      | 80.00           | 0.00            |
| 4                              | SPRAY PAINTING   | New      | 360.00          | 300.00          |
| <b>Gross Labour Cost (S\$)</b> |  |          | <b>2,590.00</b> | <b>2,400.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >