

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 3800D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	GUIDE PIECE LHR BUMPER SIDE BRACKET (SN) (CONSISTENT)	NOT NECESSARY	43.33	-
1	ALLOY WHEEL BLACK TURNED (SN) (CONSISTENT)	SCRATCHED	2,932.25	2,932.25
1	RUBBER VALVE (SN) (CONSISTENT)	NECESSARY	3.85	3.85
1	COVER FOR BUMPER PRIMED (SN) (CONSISTENT)	SCRATCHED	1,190.76	1,190.76
1	SENSOR BRACKET (SN) (CONSISTENT)	NECESSARY	14.29	14.29
1	SENSOR BRACKET (SN) (CONSISTENT)	NECESSARY	14.29	14.29
1	SENSOR BRACKET (SN) (CONSISTENT)	NECESSARY	14.93	14.93
1	SENSOR BRACKET (SN) (CONSISTENT)	NECESSARY	14.29	14.29
1	2K-PLASTIC ADHESIVE (SN) (CONSISTENT)	NECESSARY	85.94	85.94
1	BONDING AGENT FOR PLASTIC (SN) (CONSISTENT)	NECESSARY	68.85	68.85
			4,382.78	4,339.45
	LABOUR			
	LABOUR.		2,800.00	1,400.00
	SPRAY PAINTING.		1,950.00	1,300.00
	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR .		280.00	280.00
	B&P DIAGNOSIS AND PROGRAMMING.		480.00	480.00
	B&P WHEEL ALIGNMENT.		360.00	360.00
	R&R RIM & BALANCE.		50.00	50.00
			5,920.00	3,870.00
	GRAND TOTAL		10,302.78	8,209.45

RECOMMENDED COST OF REPAIRS		8,209.45

Report Ref No. CC4/ASM22011834/Rpa3q2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

mon

**HO LEONG CHUAN** 

**Automotive Assessor**