



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2303679

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 12/06/2023
Reference CC6/CTI22011837/Aya3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. GBG 9986K
Insured Veh. SLL 2511Z
Claim No. SNM22D208404/C02
Policy No. DMPCSNW00166992100
Accident Date 20/11/2022
Inspection Date 21/11/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22011837/Aya3q2 Date: 12/06/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLL 2511Z	Veh. Inspected	GBG 9986K
	Policy No.	DMPCSNW00166992100	Coverage (\$)	0.00
	Claim No.	SNM22D208404/C02	Excess (\$)	0.00
	Assign From		Assign Date	21/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KDH2010236067	Colour	BLACK
	Odometer	149128 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/80 R15	DUNLOP	6 mm
	L/H Front Tyre	195/80 R15	DUNLOP	6 mm
	R/H Rear Tyre	195/80 R15	DUNLOP	6 mm
	L/H Rear Tyre	195/80 R15	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/11/2022	Inspection Date	21/11/2022
	Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 9986K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	DENTED	1,654.10	1,654.10
1	REAR TAILGATE INNER TRIM	NOT NECESSARY	276.40	-
1	REAR TAILGATE LOCK	DAMAGED	254.70	254.70
1	REAR TAILGATE LOCK CATCH	NOT NECESSARY	110.30	-
1	REAR TAILGATE LOGO	NECESSARY	59.30	59.30
1	REAR TAILGATE EMBLEM HIACE	NECESSARY	55.60	55.60
1	REAR TAILGATE EMBLEM SUPER GL	NECESSARY	65.30	65.30
1	REAR BUMPER	DEFORMED	598.60	598.60
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	67.20	67.20
1	REAR END PANEL (INNER)	TO REPAIR SEE LABOUR	547.10	-
1	REAR END PANEL (OUTER)	DENTED	852.20	597.00
1	REAR END PANEL EXTENSION PANEL RH	DENTED	398.40	398.40
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	112.30	-
1	REAR WEATHER STRIPE	NOT NECESSARY	326.80	-
1	REAR TAILLAMP RH	CRACKED	397.60	397.60
1	REAR TAILLAMP INNER PANEL	TO REPAIR SEE LABOUR	297.10	-
1	REAR TAILLAMP LOWER BRACKET RH	NOT NECESSARY	67.40	-
1	REAR TAILGATE LOWER APRON PANEL RH	DEFORMED	387.10	102.00
	LESS 25% DISCOUNT		-1,631.88	-1,062.45
			4,895.62	3,187.35
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	150.00	60.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	120.00	60.00
1	REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	480.00	-
			1,110.00	350.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR FOR PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL (INNER) AND REAR TAILLAMP INNER PANEL .		1,500.00	1,000.00
	LABOUR FOR SPRAYPAINTING.		1,000.00	900.00
	LABOUR FOR REMOVE & TRANSFER REAR WINDSCREEN GLASS .		150.00	120.00
	WIRING CHECK .		80.00	30.00
	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS .		200.00	80.00
	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING.		300.00	80.00
			3,230.00	2,210.00
	GRAND TOTAL		9,235.62	5,747.35
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,600.00

Report Ref No. CC6/CTI22011837/Aya3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 9986K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 9986K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

