

12/6/22, 2:26 PM

Repairer Estimates

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SPCM1000000915	Date of Loss:	10/11/2022
Vehicle Reg. No.:	XE4928L	Driveable?	
Driver Age/Info:	32 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	ATS LOGITICS PTE LTD	Contact No:	+6562660608
Driver:	ZHANG MENG		
Make/Model:	SCANIA P370A4X2NZ, 12.7 D (M)	Vehicle Reg. Date:	04/06/2019
Vehicle Colour:	WHITE	Chassis No:	YS2P4X20005540287
Engine No:	DC13149L017148573		
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	30		
Description of Accident/Loss	REFER TO SKETCH		
Remarks:	VEHICLE IN WORKSHOP CAN ARRANGE SURVEY		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	115,351.50
Miscellaneous Items	0.00
Labour	9,550.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	124,901.50
- Excess (S\$)	1,500.00
(S\$)	123,401.50
+ GST 7.00% (S\$)	8,638.11
Nett Amount (S\$)	132,039.61

This claim is handled by: **SAMANTHA TAN YONG SING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

DETAILS

Source: (Last Synchronised: 06 Dec 2022)
 Model: N/A SCANIA P370A4X2NZ 12.7 D (M) (Model not available in database)
 Repairer's: (Price-denominated Standard List)
 Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/XE4928L/06/12/2022 14:19
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE <i>bt</i>	0	0.00	*15.00 F
2	2		*FRT BUMPER TOW COVER <i>mis</i>	0.00	0.00	*24.00 F
3	1		*FRT BUMPER <i>cut</i>	0.00	0.00	*1,100.00 F
4	2		*FRT BUMPER LH/RH <i>des</i>	0.00	0.00	*1,310.00 F
5	1		*FRT BUMPER REINFORCEMENT <i>bt</i>	0.00	0.00	*3,400.00 F
6	2		*FRT BUMPER SIDE COVER <i>mis</i>	0.00	0.00	*160.00 F
7	1		*FRT BUMPER LOWER PANEL <i>3ca</i>	0.00	0.00	*1,600.00 F
8	2		*FRT BUMPER LOWER PANEL HINGE <i>ex</i>	0.00	0.00	*1,130.00 F
9	1		*FRT LOWER PANEL GRILLE (TOP) <i>X</i>	0.00	0.00	*300.00 F
10	1		*FRT LOWER PANEL GRILLE (BTM) <i>X</i>	0.00	0.00	*300.00 F
11	1		*FRT LOWER PANEL COVER (TOP) <i>X</i>	0.00	0.00	*350.00 F
12	1		*FRT LOWER PANEL COVER (BTM) <i>X</i>	0.00	0.00	*150.00 F
13	2		*FRT LOWER PANEL LIFTER <i>?</i>	0.00	0.00	*596.00 F
14	2		*FRT LOWER PANEL CORNER COVER <i>?</i>	0.00	0.00	*160.00 F
15	3		*FRT LOWER PANEL ANTI SLIP <i>?</i>	0.00	0.00	*255.00 F
16	2		*FRT HEADLAMP <i>br</i>	0.00	0.00	*2,800.00 F
17	2		*FRT HEADLAMP COVER <i>br</i>	0.00	0.00	*80.00 F
18	2		*FRT HEADLAMP BRACKET <i>br</i>	0.00	0.00	*500.00 F
19	2		*FRT HEADLAMP GARNISH <i>br</i>	0.00	0.00	*360.00 F
20	2		*FRT HEADLAMP SOCKET <i>?</i>	0.00	0.00	*130.00 F
21	2		*FRT FOGLAMP <i>br</i>	0.00	0.00	*550.00 F
22	2		*FRT FOGLAMP BRACKET <i>des</i>	0.00	0.00	*590.00 F
23	1		*FRT APRON GRILLE <i>?</i>	0.00	0.00	*300.00 F
24	2		*FRT APRON SIDE GRILLE <i>?</i>	0.00	0.00	*170.00 F
25	1		*FRT CORNER PANEL RH <i>des</i>	0.00	0.00	*920.00 F
26	1		*FRT CORNER PANEL SEAL RH <i>br</i>	0.00	0.00	*120.00 F
27	1		*FRT PANEL <i>ex</i>	0.00	0.00	*1,600.00 F
28	1		*FRT PANEL FRAME <i>ex</i>	0.00	0.00	*2,850.00 F
29	1		*FRT PANEL SCAN EMBLEM <i>br</i>	0.00	0.00	*160.00 F
30	1		*FRT PANEL IA EMBLEM <i>br</i>	0.00	0.00	*150.00 F
31	1		*FRT PANEL LOGO <i>br</i>	0.00	0.00	*200.00 F
32	1		*FRT PANEL LOWER GARNISH <i>?</i>	0.00	0.00	*850.00 F
33	1		*FRT PANEL LOWER GRILLE <i>?</i>	0.00	0.00	*280.00 F
34	1		*FRT PANEL CTR GARNISH <i>X</i>	0.00	0.00	*425.00 F
35	1		*FRT PANEL CTR GRILLE <i>?</i>	0.00	0.00	*350.00 F
36	2		*FRT CABIN BRACKET (TOP) <i>?</i>	0.00	0.00	*3,000.00 F
37	2		*FRT CABIN BRACKET (BTM) <i>?</i>	0.00	0.00	*1,760.00 F
38	1		*FRT CABIN SUPPORT BEAM <i>?</i>	0.00	0.00	*3,100.00 F
39	1		*FRT CABIN SUPPORT BRACKET RH <i>?</i>	0.00	0.00	*1,600.00 F
40	1		*FRT CABIN SUPPORT BRACKET RH <i>?</i>	0.00	0.00	*1,600.00 F
41	1		*FRT CABIN SUPPORT BRACKET LH <i>?</i>	0.00	0.00	*900.00 F
42	1		*FRT CABIN SUPPORT <i>?</i>	0.00	0.00	*900.00 F
43	1		*FRT STEERING BOX <i>?</i>	0.00	0.00	*4,800.00 F
44	2		*FRT STEERING BOX SCREW <i>?</i>	0.00	0.00	*50.00 F
45	1		*AIR CLEANER BOX <i>br</i>	0.00	0.00	*3,450.00 F

Sng Ah Tee Motor & Panel Service Pte Ltd/XE4928L/06/12/2022 14:19. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Repairer Estimates

Part No.	Particulars	%Disc	%Depr	Amount
	*ANTI ROLL BAR	0.00	0.00	*1,750.00 F
	*ANTI ROLL BAR LINKAGE LH	0.00	0.00	*600.00 F
	*POWER STEERING TANK	0.00	0.00	*270.00 F
	*POWER STEERING TANK BRACKET	0.00	0.00	*390.00 F
	*REAR MUDGUARD (CTR)	0.00	0.00	*600.00 F
	*REAR MUDGUARD STRAP	0.00	0.00	*290.00 F
	*REAR MUDGUARD @ FRT	0.00	0.00	*520.00 F
	*REAR MUDGUARD BRACKET LH	0.00	0.00	*460.00 F
	*FRT LOWER PANEL GRILLE SIDE COVER	0.00	0.00	*120.00 F
	*FRT LOWER PANEL COVER SIDE	0.00	0.00	*200.00 F
	*FRT FOGLAMP GARNISH	0.00	0.00	*120.00 F
	*FRT STEP BRACKET	0.00	0.00	*950.00 F
	*FRT DOOR TOP SEAL	0.00	0.00	*90.00 F
	*FRT DOOR LH	0.00	0.00	*4,400.00 F
	*FRT DOOR RUBBER	0.00	0.00	*450.00 F
	*FRT DOOR SEAL	0.00	0.00	*470.00 F
	*FRT SIDE MIRROR LH (COMPLETE)	0.00	0.00	*1,050.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	104,930.00
+ Margin on L,N Items 10.00% (\$\$)	10,421.50
Total Parts (\$\$)	115,351.50

Sng Ah Tee Motor & Panel Service Pte Ltd/XE4928L/06/12/2022 14:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

R
Lu

S
S
S
S
S

Estimates on Miscellaneous Items

No new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO CHECK WIRING	New	100 200.00
2	TOP UP AIRCON GAS	New	X 100.00
3	TO REPAIR & REPLACE UNDERCARRIAGE	New	500? 1,000.00
4	WHEEL ALIGNMENT	New	100 150.00
5	TO REPAIR & REPLACE DASHBOARD X2	New	X 200.00
6	TO STRAIGHTEN FRT CHASSIS FRAME	New	X 1,200.00
7	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	1750 3,500.00
8	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1000 2,500.00
9	TO CHECK BRAKES, AIR BRAKES SYSTEM, RECTIFY BRAKES UNDER AIR/VACUUM SYSTEM, TO DO BRAKE BLEEDING & SYSTEM RESET	New	200 300.00
10	TO DIAGNOSE & RESET SYSTEM	New	200 400.00
Gross Labour Cost (S\$)			9,550.00

Sng Ah Tee Motor & Panel Service Pte Ltd/XE4928L/06/12/2022 14:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Parma
 Hp 90010068
 12 days
 4S
 25/11/22 @ 1215
 EXCESS: 1500
 REVERT
 Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

R
Lu