

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/HLA22011844/AVY3Q2**Date:** 05/01/2023REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP308346
Claimant Vehicle No :	GBG108M	Insured Vehicle No :	SJJ2661H
Date of Loss:	22/11/2022	Nature of Claim:	TP
		Claim No:	MPC03855/GN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG108M		
Make & Model:	NISSAN NV200, 1.5 (A)	Engine No:	K9KC400D056497
Reg. Date:	20/05/2017 (Man. Year: 2016)	Chassis No:	VSKYBAM20Z0141758
Colour:	Grey	Odometer:	121460 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,276.77	6,799.19	6,477.58	48.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,860.00	2,270.00	2,590.00	53.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,136.77	9,069.19	9,067.58	50.00
Approved Total (Overridden) (S\$)		7,200.00		
(S\$)	18,136.77	7,200.00	10,936.77	60.30
+ GST 8.00/8.00% (S\$)	1,450.94	576.00	874.94	60.30
Nett Amount (S\$)	19,587.71	7,776.00	11,811.71	60.30

INSPECTION

Date of Assignment:	24/11/2022	
Date Inspected:	25/11/2022	Inspected At:
Estimated Period of Repair:	8.0 days	LEE BROTHERS AUTOMOTIVE PTE. LTD. (HQ) 1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit Singapore 417883

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Jan 2023)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG108M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE -LH	Distorted	1,560.90 FL	*1,469.00 FL
2	1		*TAILGATE LOGO	Necessary	79.90 FL	*79.90 FL
3	1		*TAILGATE EMBLEM NV 200	Necessary	124.20 FL	*124.20 FL
4	1		*TAILGATE OUTER GARNISH	Cracked	351.50 FL	*351.50 FL
5	1		*TAILGATE WIPER MOTOR	Not Necessary	481.90 FL	*- FL
6	1		*TAILGATE LOCK -LOWER	Damaged	186.10 FL	*186.10 FL
7	1		*TAILGATE LOCK STRIKER	Not Necessary	110.50 FL	*- FL
8	1		*TAILGATE LOCK -CTR	Damaged	289.30 FL	*289.30 FL
9	1		*TAILGATE LOCK ACTUATOR	Damaged	441.50 FL	*441.50 FL
10	1		*TAILGATE LOCK -TOP	Not Necessary	186.10 FL	*- FL
11	1		*TAILGATE OPENING W/STRIP	Cut	261.90 FL	*261.90 FL
12	1		*TAILGATE CHECKER	Not Necessary	138.10 FL	*- FL
13	2		*TAILGATE HINGES	Not Necessary	243.00 FL	*- FL
14	1		*TAILGATE INNER TRIM	Cut	186.90 FL	*120.00 FL
15	10		*TAILGATE INNER TRIM CLIPS	Necessary	55.00 FL	*20.00 FL
16	1		*TAILGATE -RH	Distorted	1,253.70 FL	*1,102.00 FL
17	1		*TAILGATE SEAL	Not Necessary	126.20 FL	*- FL
18	2		*TAILLAMPS -R/L	Cracked	566.40 FL	*566.40 FL
19	2		*TAILLAMP FILLER PANELS-R/L	Repair	963.20 FL	*- FL
20	1		*REAR BUMPER	Deformed	632.70 FL	*632.70 FL
21	1		*REAR BUMPER REFLECTOR	O/S Cut	123.00 FL	*61.50 FL
22	1		*REAR BUMPER INNER FOAM	Cracked	194.70 FL	*194.70 FL
23	2		*REAR BUMPER SIDE RETAINERS -R/L	Damaged	97.80 FL	*97.80 FL
24	1		*REAR END PANEL	Dented	481.50 FL	*481.50 FL
25	1		*REAR END PANEL INNER MEMBER	Dented	899.60 FL	*461.00 FL
26	1		*REAR END PANEL TOP GARNISH	Cracked	138.10 FL	*138.10 FL
27	10		*REAR END PANEL TOP GARNISH CLIPS	Necessary	55.00 FL	*20.00 FL
28	1		*REAR EXHAUST PIPE	Not Necessary	451.70 FL	*- FL
29	1		*REAR EXHAUST MOUNTINGS	Not Necessary	28.60 FL	*- FL
30	1		*REAR FLOOR MAT	Not Necessary	861.90 FL	*- FL
31	1		*REAR FLOOR PANEL	Repair	1,755.90 FL	*- FL
32	1		*REAR FLOOR PANEL LOWER MEMBER	Repair	286.50 FL	*- FL
33	1		*REAR SPARE WHEEL CARRIER	Not Necessary	311.50 FL	*- FL
34	1		*REAR SPARE WHEEL LOCK CATCH	Not Necessary	110.50 FL	*- FL
35	2		*SET TAILGATE GLASS SEALANT -R/L	Necessary	120.00 FS	*80.00 FS
36	2		*SET TAILGATE GLASS FOAM TAPE -R/L	Necessary	120.00 FS	*80.00 FS
37	1		*REAR STICKER 70KM/H	Necessary	10.00 FS	*10.00 FS
38	1		*REAR STICKER 6 PAX	Necessary	10.00 FS	*10.00 FS
39	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
40	1		*SET REAR NO PLATE WITH HOLDER	Not Necessary	60.00 FS	*- FS
41	1		*SET REAR REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,680.30	7,509.10
- List Item Discount on L Items 10.00/10.00% (S\$)	1,403.53	709.91
Total Parts (S\$)	13,276.77	6,799.19

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR ELECTRICAL WIRING	New	80.00	30.00
2	TO REMOVE & REPLACE TAILGATE GLASS -R/L	New	300.00	120.00
3	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	New	120.00	60.00
4	TO REMOVE & REPLACE EXHAUST SYSTEM	New	100.00	0.00
5	TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS	New	80.00	80.00
6	TO TUFF KOTE	New	180.00	80.00
7	TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS	New	1,500.00	800.00
8	TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACE DAMAGED PARTS	New	2,500.00	1,100.00
Gross Labour Cost (\$\$)			4,860.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >