

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22011847/ANP3Q2**Date:** 21/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNW00005682200
Claimant Vehicle No :	SNE6912L	Insured Vehicle No :	SNE7528G
Date of Loss:	23/11/2022	Nature of Claim:	TP
		Claim No:	SNM22D208450/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNE6912L	Engine No:	R16B25510354
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650KT000358
Reg. Date:	11/06/2019 (Man. Year: 2019)	Odometer:	76474 km
Colour:	Blue		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R15	Rear Tyre Size:	215/55 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,362.20	4,233.28	2,128.92	33.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,780.00	860.00	32.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,002.20	6,013.28	2,988.92	33.20
Approved Total (Overridden) (S\$)		4,800.00		
(S\$)	9,002.20	4,800.00	4,202.20	46.68
+ GST 7.00/7.00% (S\$)	630.15	336.00	294.15	46.68
Nett Amount (S\$)	9,632.35	5,136.00	4,496.35	46.68

INSPECTION

Date of Assignment:	24/11/2022	
Date Inspected:	25/11/2022 Inspected At:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2022)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNE6912L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	684.50 FL	*684.50 FL
2	1		*REAR BOOTLID CIVIC EMBLEM	Necessary	31.50 FL	*31.50 FL
3	1		*REAR BOOTLID I-VTEC EMBLEM	Necessary	34.20 FL	*34.20 FL
4	1		*REAR BOOTLID LOGO EMBLEM	Necessary	28.00 FL	*28.00 FL
5	2		*REAR BOOTLID HINGES GARNISH L/R	Not Necessary	248.60 FL	*- FL
6	2		*REAR BOOTLID HINGES L/R	Not Necessary	98.40 FL	*- FL
7	2		*REAR BOOTLID INNER RUBBER STOPPER L/R	Not Necessary	19.60 FL	*- FL
8	1		*REAR BOOTLID INNER TRIM BOARD	Not Necessary	105.60 FL	*- FL
9	1		*REAR BOOTLID LOCK STRIKER	Not Necessary	49.20 FL	*- FL
10	1		*REAR BOOTLID MECHANISM LOCK	Damaged	84.90 FL	*84.90 FL
11	1		*REAR BOOTLID OUTER GARNISH	Cracked	268.00 FL	*268.00 FL
12	1		*REAR BOOTLID RH REFLECTOR	Cracked	133.60 FL	*133.60 FL
13	1		*REAR BOOTLID WEATHERSTRIP	Not Necessary	80.40 FL	*- FL
14	1		*REAR BUMPER	Deformed	617.20 FL	*617.20 FL
15	1		*REAR BUMPER LOWER LID	Deformed	198.10 FL	*198.10 FL
16	1		*REAR BUMPER LOWER LID CHROME MOULDING	Cracked	173.30 FL	*173.30 FL
17	1		*REAR BUMPER REINFORCEMENT	Dented	288.40 FL	*288.40 FL
18	2		*REAR BUMPER REVERSE SENSOR	Damaged	298.40 FL	*298.40 FL
19	2		*REAR BUMPER REVERSE SENSOR O RING	Necessary	30.00 FL	*30.00 FL
20	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	72.00 FL	*72.00 FL
21	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	87.40 FL	*- FL
22	1		*REAR BUMPER RH LOWER COVER	Deformed	60.40 FL	*60.40 FL
23	1		*REAR BUMPER RH REFLECTOR	Not Necessary	24.50 FL	*- FL
24	1		*REAR BUMPER RH REFLECTOR GARNISH	Cut	31.50 FL	*31.50 FL
25	1		*REAR BUMPER SIDE RETAINER L/R	O/S Damaged	150.80 FL	*75.40 FL
26	1		*REAR END PANEL	Dented	377.50 FL	*377.50 FL
27	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	80.40 FL	*- FL
28	1		*REAR END PANEL BUZZLE SENSOR	Not Necessary	85.10 FL	*- FL
29	1		*REAR END PANEL INNER TOP GARNISH	Deformed	70.30 FL	*70.30 FL
30	1		*REAR FLOOR PANEL TOP BOARD COVER	Torn	255.40 FL	*255.40 FL
31	1		*REAR RH FENDER INNER SHIELD	Torn	73.70 FL	*73.70 FL
32	2		*REAR RH FENDER INNER TRIM BOARD L/R	Not Necessary	538.60 FL	*- FL
33	1		*REAR RH TAILLAMP INNER PANEL	Repair	68.90 FL	*- FL
34	1		*REAR TAILLAMP L/R	O/S Cracked	596.80 FL	*298.40 FL
35	1		*REAR TAILLAMP LOWER BRACKET L/R	O/S Cracked	38.80 FL	*19.40 FL
36	1		*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*REAR BOOTLID NUMBER PLATE	Not Necessary	25.00 FS	*- FS
38	1		*REAR BOOTLID NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
39	1		*SET REAR BOOTLID OUTER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
40	1		*REAR BOOTLID TOP SPOILER	Cracked	900.00 FS	*700.00 FS
41	1		*SET REAR BUMPER NUMBER CLIPS	Necessary	80.00 FS	*30.00 FS
42	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
43	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*60.00 FS
44	2		*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Not Necessary	100.00 FS	*- FS
45	1		*SET REAR RH FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*20.00 FS
46	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

12/21/22, 3:11 PMAdjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					7,579.00	5,074.10
- List Item Discount on L Items 20.00/20.00% (S\$)					1,216.80	840.82
Total Parts (S\$)					6,362.20	4,233.28
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
2	TO REMOVE ,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT , TRIM GARNISH TRIM LINER CARPET (TO FR)	New	120.00	60.00
3	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
4	TO REMOVE AND REINSTALL EXHAUST PIPE	New	80.00	0.00
5	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,100.00	800.00
6	TO APPLY ANTI RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	60.00
Gross Labour Cost (\$\$)			2,640.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >