

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIS22011859/KNY3M4**Date:** 08/12/2022REFERENCE

|                              |                                       |                             |              |
|------------------------------|---------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | Allianz Insurance Singapore Pte. Ltd. | Policy No:                  | SP2003056303 |
| <b>Claimant Vehicle No :</b> | SKF2137P                              | <b>Insured Vehicle No :</b> | GBJ5054K     |
| Date of Loss:                | 22/11/2022                            | Nature of Claim:            | TP           |
|                              |                                       | Claim No:                   | 202222008385 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SKF2137P</b>                   |             |                   |
| Make & Model:               | MERCEDES-BENZ E250, 1.8 CGI (A)   | Engine No:  | 27186030017575    |
| Reg. Date:                  | 09/04/2010 (Man. Year: 2009)      | Chassis No: | WDD2120472A123474 |
| Colour:                     | Metallic Grey                     | Odometer:   | 134221 km         |
| Engine Capacity:            | 1796 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 245/45 ZR17 | Rear Tyre Size:  | 245/45 ZR17 |
| Front Left Side:  | Dunlop 7 mm | Rear Left Side:  | Dunlop 7 mm |
| Front Right Side: | Dunlop 7 mm | Rear Right Side: | Dunlop 7 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                    | 0.00              | 0.00              | 0.00              |               |
| Miscellaneous Items      | 0.00              | 0.00              | 0.00              |               |
| Labour                   | 0.00              | 0.00              | 0.00              |               |
| Paintwork Labour         | 0.00              | 0.00              | 0.00              |               |
| Towing                   | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (S\$)</b> | <b>0.00</b>       | <b>0.00</b>       | <b>0.00</b>       |               |

INSPECTION

|                             |            |                                                                                                                         |
|-----------------------------|------------|-------------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 25/11/2022 |                                                                                                                         |
| Date Inspected:             | 06/12/2022 | Inspected At: KING'S AUTO REPAIR & SERVICE PTE LTD<br>176 SIN MING DRIVE, #02-10<br>SIN MING AUTOCARE, SINGAPORE 575721 |
| Estimated Period of Repair: | 12.0 days  |                                                                                                                         |

**Adjuster:** KENNETH KONG**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00  
-\$6,000.00

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                                  |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                                  |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 07 Dec 2022)                    |
| Parts:        | M1-COUPE                                                                                                                                                                     | MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                |
| Print Code:   | (Unsubmitted, no print-code for SKF2137P)                                                                                                                                    |                                                                  |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                  |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                  |

Recommended Parts

There are no new parts selected.

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >