

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 2321E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED/WARPED	1,350.00	1,350.00
1	REAR BUMPER BEAM BRACKET	NOT NECESSARY	105.00	-
1	REAR BUMPER REVERSE LAMP	NOT NECESSARY	120.00	-
1	TAILGATE	NOT NECESSARY	1,550.00	-
1	TAILGATE INNER LOCK	NOT NECESSARY	145.00	-
1	TAILGATE OUTER HANDLE	NOT NECESSARY	135.00	-
1	TAIL LAMP	NOT NECESSARY	435.00	-
1	SIGNAL LAMP	NOT NECESSARY	380.00	-
1	TAIL LAMP SIDE PANEL	TO REPAIR SEE LABOUR	1,450.00	-
1	REAR SIDE WINDSCREEN MOULDING	NOT NECESSARY	200.00	-
1	REAR FENDER PANEL RH	TO REPAIR SEE LABOUR	2,250.00	-
1	REAR SILENCER BOX	NOT NECESSARY	850.00	-
	LESS 25% DISCOUNT		-	-337.50
			8,970.00	1,012.50
	SPECIAL NETT ITEMS			
1	"60KM/H" STICKER (SN)	NOT NECESSARY	20.00	-
1	REAR SIDE WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
1	SET REAR BUMPER REFLECTIVE STICKER (SN)	NOT NECESSARY	250.00	-
1	REAR FENDER ORANGE REFLECTOR (SN)	NOT NECESSARY	65.00	-
			395.00	-
	<u>LABOUR</u>			
	SPRAY PAINTING.		2,000.00	700.00
	PANEL BEAT. INCLUSIVE OF THE REPAIR OF TAIL LAMP SIDE PANEL AND REAR FENDER PANEL RH.		2,000.00	800.00
			4,000.00	1,500.00
	GRAND TOTAL		13,365.00	2,512.50

Report Ref No. CS/UOI22011873/Uny3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/UOI22011873/Uny3m4

CHUA KANG SENG

**Licensed Appraiser**