



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 2979K

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | FRONT DOOR RH (CONSISTENT) | BENT | 1,655.50 | 1,655.50 |
| 1 | FRONT DOOR LOWER GARNISH RH (CONSISTENT) | CRACKED | 252.50 | 110.10 |
| 1 | REAR DOOR RH (NPA) (CONSISTENT) | TO REPAIR SEE LABOUR | - | - |
| 1 | REAR FENDER RH (NPA) (CONSISTENT) | TO REPAIR SEE LABOUR | - | - |
| 1 | REAR BUMPER (NPA) (CONSISTENT) | TO REPAIR SEE LABOUR | - | - |
| 1 | REAR DOOR LOWER GARNISH RH (CONSISTENT) | CUT | 195.32 | 125.30 |
| 1 | SIDE SKIRT RH (CONSISTENT) | CRACKED | 375.85 | 375.85 |
| 1 | FRONT FENDER RH (CONSISTENT) | BUCKLED | 753.34 | 588.80 |
| 1 | FRONT HYUNDAI WHEEL CAP RH (CONSISTENT) | SCRATCHED | 185.30 | 185.30 |
| 1 | REAR HYUNDAI WHEEL CAP RH (CONSISTENT) | SCRATCHED | 185.30 | 185.30 |
| | LESS 20% DISCOUNT | | -720.62 | -645.23 |
| | | | 2,882.49 | 2,580.92 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | SUNDRIES (SAND PAPER, WELDING WIRE ETC) (SN) | NOT NECESSARY | 60.00 | - |
| | | | 60.00 | - |
| | <u>LABOUR</u> | | | |
| | TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS, PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF REAR DOOR RH, REAR FENDER RH AND REAR BUMPER. | | 1,200.00 | 400.00 |
| | TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED. | | 1,200.00 | 1,100.00 |
| | TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS. | | 100.00 | 60.00 |
| | TO VACUUM, WAXING & CLEAN. | NOT NECESSARY | 60.00 | - |
| | TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS. | NOT NECESSARY | 50.00 | - |
| | | | 2,610.00 | 1,560.00 |
| | GRAND TOTAL | | 5,552.49 | 4,140.92 |

Report Ref No. CS/ASM22011882/Gvp3e2



| | | | |
|---|--|--|-----------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 3,300.00 |
|---|--|--|-----------------|

Report Ref No. CS/ASM22011882/Gvp3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.