

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22011885/DVP3Q2**Date:** 27/02/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00125242203	
<b>Claimant Vehicle No :</b>	GBK4388Z	<b>Insured Vehicle No :</b>	GW9051P	
Date of Loss:	24/11/2022	Nature of Claim:	TP	Claim No: SNM22D208490/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GBK4388Z</b>		
Make & Model:	TOYOTA REGIUS ACE, 2.8 SUPER GL DARK PRIME II (A)	Engine No:	1GD8492066
Reg. Date:	23/07/2020 (Man. Year: 2019)	Chassis No:	GDH2012009402
Colour:	Silver	Odometer:	146770 km
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>	
Parts	20,334.61	3,564.79	16,769.82	82.47	
Miscellaneous Items	0.00	0.00	0.00		
Labour	7,070.00	1,420.00	5,650.00	79.92	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>27,404.61</b>	<b>4,984.79</b>	<b>22,419.82</b>	<b>81.81</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>4,000.00</b>			
	<b>(S\$)</b>	27,404.61	4,000.00	23,404.61	85.40
	<b>+ GST 7.00/7.00% (S\$)</b>	1,918.32	280.00	1,638.32	85.40
	<b>Nett Amount (S\$)</b>	<b>29,322.93</b>	<b>4,280.00</b>	<b>25,042.93</b>	<b>85.40</b>

**INSPECTION**

Date of Assignment:	25/11/2022	
Date Inspected:	25/11/2022 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	4.0 days	

**Adjuster:** BRYAN TANI**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b>	(Last Synchronised: 27 Feb 2023)	
<b>Parts:</b>	N/A	TOYOTA REGIUS ACE 2.8 SUPER GL DARK PRIME II (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBK4388Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,150.39 FL	*1,850.00 FL
2	1		*TAILGATE LOGO	Necessary	65.29 FL	*65.29 FL
3	1		*TAILGATE REGIUS ACE STICKER	Necessary	119.48 FS	*30.00 FS
4	1		*TAILGATE 1200KG STICKER	Necessary	107.47 FS	*20.00 FS
5	1		*TAILGATE INNER TRIM BOARD	Not Necessary	441.92 FL	*- FL
6	1		*TAILGATE INNER BOARD HANDLE	Not Necessary	197.00 FL	*- FL
7	1		*TAILGATE CENTER MOULDING	Not Necessary	298.00 FL	*- FL
8	1		*TAILGATE WEATHER STRIP	Necessary	395.00 FL	*288.20 FL
9	1		*TAILGATE INNER LOCK	Not Necessary	340.00 FL	*- FL
10	1		*TAILGATE STRIKER LOCK	Not Necessary	105.00 FL	*- FL
11	1		*TAILGATE WINDSCREEN MOULDING	Necessary	288.21 FL	*188.00 FL
12	2		*TAILGATE NUMBER PLATE LAMP LH/RH	Not Necessary	236.00 FL	*- FL
13	2		*TAILGATE HINGE LH/RH	Not Necessary	384.80 FL	*- FL
14	2		*TAILGATE DAMPER LH/RH	Not Necessary	996.20 FL	*- FL
15	2		*TAIL LAMP LH/RH	Not Necessary	1,364.78 FL	*- FL
16	2		*TAIL LAMP PANEL LH/RH	Not Necessary	1,178.40 FL	*- FL
17	2		*TAIL LAMP LOWER GARNISH LH/RH	Not Necessary	679.60 FL	*- FL
18	2		*TAIL LAMP LOWER GARNISH BRACKET LH/RH	Not Necessary	210.56 FL	*- FL
19	1		*REAR BUMPER	Dented	893.41 FL	*599.30 FL
20	1		*REAR BUMPER CENTER STEP BEAM	Bent	398.00 FL	*262.30 FL
21	1		*REAR BUMPER SIDE RETAINER LH/RH	O/S Broken / N/S Not Necessary	116.58 FL	*36.20 FL
22	1		*REAR END PANEL INNER	Dented	1,033.00 FL	*589.30 FL
23	1		*REAR END PANEL OUTER	Dented	1,082.00 FL	*647.80 FL
24	1		*REAR END PANEL TOP GARNISH	Not Necessary	392.81 FL	*- FL
25	1		*REAR SPARE TYRE HOLDER BRACKET	Not Necessary	380.00 FL	*- FL
26	1		*REAR SPARE TYRE HOLDER BOLT	Not Necessary	60.00 FL	*- FL
27	2		*REAR FENDER LH/RH	Not Necessary	5,538.20 FL	*- FL
28	2		*REAR FENDER INNER TRIM LH/RH	Not Necessary	1,782.40 FL	*- FL
29	1		*REAR EXHAUST PIPE	Not Necessary	1,410.00 FL	*- FL
30	1		*REAR EXHAUST MOUNTING	Not Necessary	116.00 FL	*- FL
31	1		*REAR EXHAUST BRACKET	Not Necessary	90.00 FL	*- FL
32	1		*REAR NUMBER PLATE & GARNISH	Not Necessary	100.00 FS	*- FS
33	1		*REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
34	1		*REVERSE SENSOR	Not fitted	300.00 FS	*- FS
35	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
36	1		*TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
37	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
38	1		*TAILGATE CENTER MOULDING CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*TAILGATE INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
40	1		*TAILGATE TOYOTA STICKER	Not Necessary	60.00 FS	*- FS
41	1		*TAILGATE HIACE STICKER	Not Necessary	60.00 FS	*- FS
42	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
43	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*TAIL LAMP PANEL SEALANT	Not Necessary	160.00 FS	*- FS
45	1		*REAR END PANEL SEALANT	Necessary	150.00 FS	*40.00 FS
46	1		*TAILGATE 70KM/H STICKER	Necessary	50.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	900.00 FS	*- FS
48	1		*REAR FLOOR PANEL MATT	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>25,990.50</b>	<b>4,696.39</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	5,655.89	1,131.60
<b>Total Parts (\$)</b>	<b>20,334.61</b>	<b>3,564.79</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	0.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	400.00	120.00
6	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
7	TO RNR REAR BUMPER REVERSE SENSOR TO FACILITATE REPAIRS	New	120.00	0.00
8	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	New	150.00	0.00
9	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	300.00	0.00
10	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>7,070.00</b>	<b>1,420.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**